

## **Villages of Garrison Creek HOA**

College Place, WA

## Level II Reserve Study Update (With Site-Visit)

Fiscal Year: 2023 Report#: 16951 Version: Draft2

## Reserve Data Analyst, Inc.

www.reservedataanalyst.com

## **Prepared By**

Joel Tax, RS 866.574.5115 ext. 704 joel@reservedataanalyst.com Report Date: August 22, 2022

# Table of ContentsVillages of Garrison Creek HOA

Introduction	3
Executive Summary	4
Reserve Study Knowledge Base	5
Reserve Analyst Comments	10
The Component List	12
Current Cost by Category Chart	15
Projected Percent Funded Chart	16
Projected Reserve Account Balance Chart	17
100% Funded - Summary	18
100% Funded - Year End Projections	19
Recommended Funding - Summary	20
Recommended Funding - Year End Projections	21
Alternate Recommended Model - Diff. Annual % Increase - Summary	22
Alternate Recommended Model - Diff. Annual % Increase - Year End Projections $\_$	23
Baseline Funding - Summary	24
Baseline Funding - Year End Projections	25
Current Funding - Summary	26
Current Funding - Year End Projections	27
Projected Expenditures Chart	28
Projected Expenditures Report	29
Spreadsheet - Component Expenditures	44
Fully Funded Balance Calculations (Beginning Fiscal Year)	56
About the Component Detail Reports Section	60
Component Detail Reports	61
Definitions, Disclosure & Calculations Appendixes	113
Component Index	118

#### Villages of Garrison Creek HOA Introduction

Thank you for utilizing the services of Reserve Data Analyst for your reserve study. We strive to create a comprehensive report that can be utilized for your budgeting needs. If there are any questions, concerns, corrections, or revisions needed please do not hesitate to call or email us. While this study does have some explanations of the methodology used, we have kept it to a minimum for brevity. More detailed explanations of methodology & concepts are explained in our Reserve Study Guidebook available at the following link:



#### www.reservedataanalyst.com/guidebook

The recommendations for the allocation rates of the different funding models are only for the beginning year of this reserve study; all future years are projections which are educated guesses and have numerous assumptions (e.g., inflation, proper maintenance, proper installation, known reserve account balances, etc.) built into the models. The further out in time a reader of the study goes, the less reliable the projections are likely to be. Note that the recommendations for the first fiscal year in the study are based on current cost and current useful life estimate levels as opposed to future cost and future useful life projections which again are educated guesses.

From year to year the recommendations of the reserve analyst will typically change (sometimes significantly) based on variables such as what projects have been done, what projects has been deferred, changes to the allocation rate, changes to the starting balance, changes to the component list, actual inflation rate figure (versus projections), maintenance or lack of maintenance of components, etc. Annual updates to this report help to incorporate changes to these variables as they occur so revisions to the recommendations are less significant than if updates are done infrequently.

There are a couple of tips to consider that will help you both navigate this study and understand the different sections within the study:

Study Navigation - To navigate this study more easily, we recommend printing out the Table of Contents page at the beginning of the study and the Component Index page(s) at the rear of the study. We have found it easiest for most readers to have the PDF of this study open on their computer while referring to the printed-out Table of Contents and Component Index pages.

#### Within this reserve study you will find:

- A list of common questions that a typical reader of our reserve study will have, as well as links to additional information on the topics: (*Reserve Study Knowledge Base*)
- A list of the site and building components that are reportedly the Client's responsibility along with their respective costs and quantity: (*The Component List*)
- A timeline of the estimated dates that we recommend funds be allocated to the repair/replacement project. (*Projected Expenditures Chart, List & Spreadsheet*)
- <sup>2</sup> Various funding models with different goals in mind. (Summary Comments Page and Projections Page)

### Villages of Garrison Creek HOA Executive Summary

Name	Villages of Garrison Creek HOA
Location	College Place, WA
Contributing Members	240
Base Year / Age	June 1, 1997
Fiscal Year Ends	December 31, 2023
Level of Service	Level II Reserve Study Update (With Site-Visit)
Prepared for Fiscal Year	2023
Last On-Site Inspection Date	August 22, 2022
Inflation Rate for Projections	3.50%
*Interest Rate for Projections	0.50%
*Tax Rate on Interest Earned	30.0%
Funding Plan Method	Inflation Adjusted Pooled Cash Flow Method

#### **Reserve Account Summary**

Current Percent Funded	Fiscal Year Beginning Fully Funded Balance	\$1,148,280
(as of January 1, 2023)	*Estimated FY Start Balance	\$422,061
	Total Reserve Account Surplus or (Deficit)	(\$726,219)
36.8%	Avg. Surplus or (Deficit) Per Contributing Member	(\$3,026)
<b>JU.0</b> /0	*Current Annual Reserve Allocation Rate	\$177,987 per year
	*Approved Special Assessments	None in fiscal year 2023.
0-30% <u>30-70%</u> 70-100% Low Fair Good	*Approved Loans	None in fiscal year 2023.

#### 5-Year Summary - Annual Reserve Allocation Rates & Year End % Funded

	100% Funding Model		Recommended Funding Model		Baseline Funding Model				
2023	\$942,866	100%	\$225,000	30%	\$196,358	27%	\$177,987	26%	2023
2024	\$229,901	100%	\$232,875	38%	\$203,230	33%	\$184,217	30%	2024
2025	\$237,947	100%	\$241,026	45%	\$210,343	38%	\$190,664	34%	2025
2026	\$246,275	100%	\$249,462	50%	\$217,705	41%	\$197,337	36%	2026
2027	\$245,702	100%	\$258,193	53%	\$225,325	43%	\$204,244	36%	2027
	Account is at least funded each ye		Achieve 100% funde the timeframe of th		Reserve account al within timeframe c		Current allocation r been supplied by th		

\* Data supplied by the Client, assumed to be correct and not independently verified.

\*\*Any negative percent funded shown is for visual representation of deficiency.

#### What is a Reserve Study?

A reserve study is a budgeting tool that can be utilized to make more informed budgeting decisions regarding a reserve account, it is an independent assessment of the adequacy of the reserve account balance and allocation rate utilizing a mathematical formula known as the "Percent Funded" calculation.

The Reserve Analyst develops funding models that:


- Distribute the costs as fairly as possible over time
- Have stable budgets over time (i.e., limiting large fluctuations from one year to the next)
- Limit the risk for reliance on emergency financing or having to defer overdue projects

A Reserve Study is an independent assessment of the reserve account and is <u>not</u> the Budget ....

This study is not the budget, and it should not be revised to just reflect the budgeting decisions of the Client. An example of this is to push off overdue projects that the Client may not have the funds to complete. This report should reflect the replacement dates of the components utilizing average or historical records for the useful lives & costs for these projects; the useful lives can be updated to reflect actual on-site conditions as the components age and in updates to this report. Should the Client decide to make budgeting decisions such as deferring projects (typically due to a lack of funds) and that appear to be overdue carries its own risk with relation to scenarios like higher project costs later and marketability issues.


#### How Much Should We Reserve?

There is no right or wrong answer to the question of "How Much Should We Reserve?" as the reserve contributions in all the funding models in this study are based on different funding goals. It is more appropriate to consider the risk levels associated with different funding models as each Client has different risk tolerances and challenges in enacting whatever funding model is most appropriate to them. In our opinion any funding model that projects the reserve account balance to dip to zero would not be appropriate or fiscally responsible as future emergency financing or deferring projects are typically the outcome. Below are some of the more common funding models utilized:




#### About Percent Funded

Percent funded is a calculation of how much is in the reserve account versus an ideal amount known as the Fully Funded Balance. The different risk levels associated with the levels of funding are explained in more depth below.



The below video link explains the Percent Funded calculation in more detail:



www.reservedataanalyst.com/pf

#### About the Fully Funded Balance

The Fully Funded balance is a mathematical calculation that represents the accrued deterioration of a component or a group of components at a specific point in time. It is an answer to the question of "How much should be in a reserve account at a specific point in time?" When the reserve account balance is the same as the Fully Funded Balance the reserve account is considered Fully Funded (100% Funded) at that specific point in time.

The below video link provides a more in-depth explanation of the Fully Funded balance:



www.reservedataanalyst.com/ffb

#### **Calculating Inflation in the Reserve Study**

Inflationary factors impact the project costs over time and are the main driving force that must be overcome with diligent and steadfast budgeting towards reserves. Due to the compounding impact of inflation on costs, in a relatively short period of time, a reserve account can be become severely underfunded if it is not considered in the budgeting scenarios. Follow the below link to learn more about how we calculate inflationary factors (escalation of the prices) in the reserve study and some of the tools we use in the process:



www.reservedataanalyst.com/inf

#### **Component Useful Life Estimates**

The useful life of components in the reserve study are predominantly based on our experiences with many different types of organizations and their respective repair and replacement cycles with building and site components. In addition to our own experiences working with many organizations over the years there is ample data available online regarding useful life estimates of building and site components. It is important to note that the estimates in the reserve study are based on averages and are not specific to any one property. Follow the below link to view some of the various useful life tables that we utilize:



#### **Determining Component Project Costs**

We utilize many sources for determining what is an appropriate component project cost in the reserve study. These can include:

- Client invoices, bids, estimates
- Our in-house database that is based on the collection of many Client invoices, bids, and estimates
- Cost manuals that, when used correctly, are very accurate for average cost figures

It's important to understand that unless we are provided actual project costs based on a client invoice/bid or estimate we utilize average costs figures that are not specific to any one Client. In the bidding process you will find that there is a ... ... large difference in price from one vendor to the next for a variety of reasons. We aim to be in the middle of these estimates unless we have Client data to incorporate into the reserve study. Future costs (projections) for the component expenses are simply inflated from current cost based on the inflation assumption in the reserve study. It is important to remember that our current recommendations are based on current project costs and not the inflated number that is utilized in the projections portion of the reserve study. The below link goes into this topic in more detail:



www.reservedataanalyst.com/cost

#### **National Reserve Study Standards**

There are two recognized organizations that dictate national reserve study standards in the industry. The Community Association's Institute and the Association of Professional Reserve Analysts award designations to those reserve study professionals that meet education & work experience, adhere to the minimum report requirements, complete ongoing continuing education courses, and abide by ethical considerations in the field. The standards for both organizations can be viewed at the links below:





www.reservedataanalyst.com/APRA

#### What Components to Include in the Study?

Reserve expenses for components are major expenses which must be budgeted for in advance to provide the necessary funds in time for their occurrence. Reserve expenses are reasonably predictable both in terms of frequency and cost. They are expenses that when incurred would have a significant impact on the smooth operation of the budgetary process from one year to the next if they were not reserved for in advance.

A common concern when beginning this process is what components are to be included and funded for in the Reserve Study. Nationally recognized CAI Reserve Study Standards as well as APRA Standards of Practice dictate that the reserve components need to meet the following criteria:

- It's not already covered in the Operating Budget
- The component has a limited life expectancy
- The component has a reasonably defined remaining useful life
- As required by local statutes

#### When to Complete Reserve Projects?

Components should be replaced when they are no longer functioning as designed. This is best determined by your component specific Vendor who can inspect and give their best professional advice on the condition assessment and timeframe on when/what needs to be done. Note that this reserve study is <u>**not**</u> a "to do list"; it is a budgeting document with recommendations for when we suggest having the funds allocated towards the projects ... ... If something fails earlier than projected than replace it, if it lasts longer (as determined by your component specific Vendor) then take their advice as they are the professionals in their specific field. Projects should be completed when they need to be completed regardless of our projections in the study. Note that this does not mean it would be appropriate to delay projects simply because funds are not available though as that is a budgeting decision not based on component specific Vendor recommendations. A common issue we see is the delay of projects simply because there is a lack of reserve funds available, only to have a much larger and more expensive project later due to collateral damage (e.g., not replacing a roof in a timely manner, which then leaks and causes siding damage).

#### **Ongoing Component Maintenance**

While this reserve study has been developed to disclose and inform the Client of the predictable larger longterm project costs related to site and building components, there is also a need to complete regular inspections and repairs to virtually all components on much shorter cycles. These costs would typically be covered in the annual and ongoing Operating Budget.

Virtually all the components should receive regular cycles of inspection and repairs by a qualified Vendor. Failure to complete ongoing maintenance typically leads to shorter useful lives and higher costs later. RSMeans provides a free link to common building and site component items to inspect at various corresponding time frames.



www.reservedataanalyst.com/RSmeans

#### **Recommendations Versus Projections**

In the reserve study the Reserve Analyst' <u>recommendations</u> for the allocation rates of the different funding models apply only to the year the reserve study is being developed for. All <u>projections</u> in the study are future educated guesses with assumptions about a significant number of variables (e.g., inflation rate, financials, component useful life, component remaining useful life, proper maintenance, etc.).

Projections can be accurate or extremely inaccurate based on these assumptions; because of this we do not suggest giving much consideration to projections in the decision making for overall reserve budgeting. This may sound counterintuitive, but this is due to recommendations for the allocation rates, in the initial year of the study, being based on predominantly current known factors (e.g., *current* costs, *current* inflation, *current* maintenance practices) versus projections which are based on future assumptions to a variety of variables (e.g., *future* costs, *future* inflation rates, and *future* maintenance practices). Follow the below link to our website to learn more about recommendations versus projections.



## You Have a Study Now What?... Goal Setting

Adequately budgeting for reserves is often one of the more difficult tasks our clients face. Reserve component projects are infrequent and often years down the line, making it very easy to just "deal with it later". We have found those that are most successful with reserve budgeting goals typically follow these simple ... ... rules when creating and implementing a reserve budget.

#### <u>Actionable</u>

Is your goal possible within the constraints & limitations of very important but often overlooked factors related to statutory requirements and the governing documents? What may seem very "Reasonable" to the Board may very well be illegal or against the governing documents.

#### **Comprehensive**

Your goal should be clear and specific, otherwise you won't be able to focus your efforts or feel truly motivated to achieve it. When drafting your goal, try to answer the four "W" questions - <u>What</u> do we want to accomplish? <u>Why</u> is this goal important? <u>Who</u> is involved? <u>When</u> is this goal set to occur?

#### <u>Equitable</u>

Your goal should be reasonable and attainable to be successful. In other words, it should stretch your abilities but remain possible. When you set an achievable goal, you may be able to identify previously overlooked opportunities or resources that can bring you closer to it. This often means that transitioning to a more stable financial track will take years of smaller goals being obtained. Severely underfunded reserve accounts typically develop after many years or decades; it's usually not reasonable for the answers to come quick or easily.

Follow the below link to our website to learn more about the ACE way to reserve budgeting.



https://www.reservedataanalyst.com/ace

#### Villages of Garrison Creek HOA Reserve Analyst Comments

#### **Reserve Study Update - For Fiscal Year 2023**

There has significant inflation in the construction industry in this region since the prior study was completed. Most recent data indicate a 12.4% inflation rate is appropriate for this region.

Note that a historical average of 3.5% inflation (per most recent data) has still been applied to the future projections in the reserve study as even though there will be periods of time with above average and below the average inflation rate of 3% in the construction industry, we assume the long-term average will fall in line with the historical long-term data in the United Stated going back over 100 years.

#### Comments on Assessment & Disclosure Form

Included in the fee for this reserve study is an Assessment & Disclosure Form which complies with statutory requirements for common interest communities. Please follow the following link to complete the request form on our website: https://www.reservedataanalyst.com/rad/

Note that this form can only be requested after the budget has been voted on and approved by the Board and/or Community Membership. This disclosure is a requirement for Boards to provide to the membership annually.

#### **Excluded Components**

Unless noted otherwise the below components have been excluded from funding in this reserve study. Note that the inclusion of any of these items later via a revision or update to this study will impact the funding strategies developed by the Reserve Analyst.

#### Long Life Components

If properly constructed the below components are long life components which, currently, have no predictable useful life, predictable remaining useful life, or predictable associated replacement costs. As these components age and a history of repair/replacement needs becomes evident or there are failures then we suggest reevaluating these systems and have them inspected by qualified vendors. Future updates to the reserve study should be revised accordingly.

- 1. Electrical Modernization
- 2. Rock & Concrete Retaining Walls
- 3. Storm Sewer System (catch basins/piping) With annual inspections and annual maintenance of this system there is no predictable useful life or remaining useful life associated with this component. If/when issues do develop, they can typically be funded for well in advance of a large-scale project if they are spotted during the advised regular annual maintenance.

#### Not Client's Responsibility

The below components are reportedly not the Client's responsibility per their interpretation of their governing documents. Note that the Reserve Analyst does not interpret governing documents and have excluded items based on the Client's request and their interpretation of their own governing documents. If there is ambiguity or questions as to what specific wording means in the governing documents, we recommend consulting with a qualified and experienced attorney.

- 1. Utility Main Lines Utility Company's Responsibility
- 2. Utility Lateral Lines Homeowner's Responsibility

#### Villages of Garrison Creek HOA Reserve Analyst Comments

- 3. Street Pole Lights (excluding Phase I & II) Utility Company's Responsibility
- 4. Fire Hydrants (24 count) City
- 5. Underground Irrigation at Private Lots Lot Owner's Responsibility (new for fiscal year 2023 Update)

#### **Operating Account Expense**

The below components are reportedly paid from the Operating Account and have not been included in this reserve study.

- 1. Storm Sewer System Maintenance We recommend setting up an annual contract with a qualified Vendor.
- 2. Landscape Lighting
- 3. Street Pole Light Painting
- 4. Pedestrian Bridge Repairs (small wood/composite replacement projects)

#### Villages of Garrison Creek HOA The Component List

Solution of the solution of th

Second Contraction of the second seco


Chits Struct Cost of the second

#### ID Description

Master								
1001 Benches - Repair/Replacement	2023	2048	25	0	25	8 ea	478.82	3,831
1002 Bridge Pond - Replace	1997	2026	25	4	3	105 sf	71.64	7,522
1004 Bridges 1, 2, 3 - Replace	1997	2026	25	4	3	1 ls	31,165.15	31,165
1005 Bridges Paint Wood Surfaces	2020	2023	5	-2	0	1 total	856.80	857
1008 Clock Tower Paint / Repair Continge	2020	2023	3	0	0	1 ls	1,203.80	1,204
1083-4 Common Sump Pump Components (	2021	2024	3	0	1	1 ea	3,372.00	3,372
1013 Creek Pump Creek - Refurbish	2014	2029	15	0	6	1 ls	16,075.14	16,075
1012 Creek Pump House Shed Repair Cont	2016	2023	6	0	0	1 ea	3,632.97	3,633
1015 Entry Sign & Monument - Refurbish	1997	2026	25	4	3	1 ls	1,953.51	1,954
1102 Fence & Gate (lions park) - Replace	1997	2027	30	0	4	40 lf	118.74	4,750
	nfunded							
1019 Fences Along Lions Park - Replace U	nfunded							
1103-0 GVW Concrete - Grinding	2022	2023	1	0	0	1 ls	3,473.16	3,473
1027-0 GVW Concrete - Replacement	2022	2027	5	0	4	1 ls	3,440.66	3,441
1086-0 GVW Tree Care	2022	2023	1	0	0	1 ls	5,620.00	5,620
1112b GVW Tree/Shrub (2027) - Refurbish	2027	2027	4	0	4	1 ls	3,372.00	3,372
1112 GVW Tree/Shrub/Other - Common A	2022	2023	1	0	0	1 ls	11,240.00	11,240
1024 Gazebo - Major Renovation	2018	2033	15	0	10	1 ls	13,538.70	13,539
1025 Gazebo - Paint	2021	2027	6	0	4	1 ls	2,299.22	2,299
1026 Gazebo Roof - Replace	2007	2030	23	0	7	6 square	es 595.93	3,576
1028 Irrigation Controllers 20% Replace	2021	2024	3	0	1	21 ea	3,926.60@20.0%	16,492
1029 Irrrigation Backflow Devices - 11% re	2021	2023	2	0	0	9 ea	1,001.83 @11.1%	1,003
1030 Lights Pole Fixtures Phases I & II - Re	2021	2041	20	0	18	6 ea	1,001.64	6,010
1031 Lights Pole Phases I & II - Replace	1997	2037	40	0	14	6 ea	2,370.16	14,221
1033 Mailbox Clusters (10 box) - Replace	2021	2046	25	0	23	10 ea	3,283.98	32,840
1033c Mailbox Clusters (Village 10) - Replace	2010	2035	25	0	12	1 ea	5,597.69	5,598
1033e Mailbox Clusters (Village 8) - Replace	2018	2043	25	0	20	1 ea	8,125.68	8,126
1033d Mailbox Clusters (Village 9) - Replace	2017	2042	25	0	19	1 ea	8,125.68	8,126
1040 Mailbox Wooden Structures (10 box)	2021	2036	15	0	13	10 ea	1,083.42	10,834
1040c Mailbox Wooden Structures (Village	2023	2023	15	0	0	1 ea	1,625.14	1,625
1114 Maintenance & Storage (Trail 1) She	2022	2042	20	0	19	1 ea	27,860.59	27,861
1113b Non GVW Tree/Shrub (2027) - Refur	2027	2027	4	0	4	1 ls	3,372.00	3,372
1113 Non GVW Tree/Shrub/Other - Comm	2022	2023	1	0	0	1 ls	11,240.00	11,240
1027-01Non-GVW Concrete (2022) - Replace	2022	2023	1	0	0	1 ls	18,057.06	18,057
1103-01Non-GVW Concrete - Grinding	2022	2023	1	0	0	1 total	3,473.16	3,473
1027-01Non-GVW Concrete - Replacement	2017	2028	10	0	5	1 ls	28,100.00	28,100
1086-01Non-GVW Tree Care	2022	2023	1	0	0	1 ls	5,620.00	5,620
1109 Pavement - Crack Sealing & Repair	2022	2023	1	0	0	1 ls	18,000.00	18,000
1041 Pavement Overlay Master	1997	2029	30	2	6	54,275 sf	2.96	160,654
1050 Pavement Seal Coat Master	2023	2029	6	0	6	54,275 sf	0.22	11,941
1062 Pond Large - De-muck & Maintenace	2022	2042	20	0	19	18,131 sf	4.65	84,309
1108 Pond Small - Liner - Replace	2020	2040	20	0	17	3,510 sf	13.86	48,649

#### Page 12

#### Villages of Garrison Creek HOA The Component List




#### ID Description


Master continued								
1245 Shed - Replace	2023	2063	40	0	40	392 sf	115.00	45,080
1065 Slope - Maintenance Un	funded							
1080 Storm Water System Drains & Catch Un	funded							
1081 Streetside Signs - Replace	2006	2031	25	0	8	1 ls	54,039.87	54,040
1083-3 Sump Pump 1 HP - (765 Heron) - Rep	2021	2033	12	0	10	1 ea	7,258.79	7,259
1082-1 Sump Pump 2 HP - High Water / Gro	2021	2033	12	0	10	1 ea	14,943.73	14,944
1082-2 Sump Pump 3/4 HP - Pond Fill - Repl	2021	2033	12	0	10	1 ea	6,723.77	6,724
1084 Sump Pump Backup Generator - Repl	2007	2027	20	0	4	1 ea	12,866.62	12,867
1095 UG Sprinkler Pipe Master Areas 4.8%	1997	2023	5	20	0	1 ls	2,063,964.08 @4.8%	99,483
1110 VGC Riding Mower - Replace	2022	2029	7	0	6	1 ea	7,868.00	7,868
1096 Walking Paths Bark Dust & Chip Rock	2022	2023	1	0	0	1 ls	4,630.88	4,631
1097 Well Clock Tower - Repair Contingency	2021	2027	6	0	4	1 ls	2,605.43	2,605
1099 Well Pump - Replace	2009	2023	12	0	0	1 ea	15,370.87	15,371
Master - Total:								\$917,940
Phase I								
1035 Mailbox Structures - Ph. I - Replace	1997	2023	24	0	0	2 ea	1,610.13	3,220
1042 Pavement Overlay Phase I	2023	2053	60	0	30	26,424 sf	2.96	78,215
1105 Pavement Replacement Phase I	2023	2023	30	0	0	26,424 sf	4.01	105,960
1051 Pavement Seal Coat Phase I	2023	2029	6	0	6	26,424 sf	0.22	5,813
Phase I - Total:			Ţ	-	-		•	\$193,209
								1 ,
Phase II								
1036 Mailbox Structures - Ph. II - Replace	1998	2023	24	0	0	3 ea	1,563.10	4,689
1043 Pavement Overlay Phase II	1998	2029	30	1	6	12,508 sf	2.96	37,024
1052 Pavement Seal Coat Phase II	2023	2029	6	0	6	12,508 sf	0.22	2,752
Phase II - Total:								\$44,465
Phase V								
1037 Mailbox Structures - Ph. V - Replace	2021	2045	24	0	22	2 ea	1,610.13	3,220
1045-0 Pavement Overlay Phase V	1999	2029	30	0	6	34,784 sf	2.96	102,961
1045-01Pavement Overlay Phase V Alley	2023	2053	60	0	30	4,800 sf	2.96	14,208
1111 Pavement Replacement Phase V Alley	2023	2023	30	0	0	4,800 sf	4.01	19,248
1054-0 Pavement Seal Coat Phase V	2023	2029	6	0	6	34,784 sf	0.22	7,652
1054-01Pavement Seal Coat Phase V Alley	2023	2029	6	0	6	4,800 sf	0.22	1,056
Phase V - Total:						,		\$148,345
Phase VI								
Phase VI	2000	2024	24	0	1	2	1 625 26	2 251
1038 Mailbox Structures - Ph. VI - Replace	2000	2024	24 30	0 -1	1	2 ea	1,625.26	3,251
1046 Pavement Overlay Phase VI 1055 Pavement Seal Coat Phase VI	2000 2023	2029 2029	30 6	-1	6 6	44,112 sf	2.96	130,572
Phase VI - Total:	2023	2029	6	U	б	44,112 sf	0.22	9,705
Fliase VI - TOLAI.								\$143,527

### Villages of Garrison Creek HOA The Component List

		to t	Hend Contraction	Les Los	Adi Life	Remaining		6000 000 000 000 000 000 000 000 000 00	
ID	Description	19 4 S	4 <sup>6</sup> 4 <sup>6</sup>	నో	40	e de	S. S.	Jan of	్ లో
Phase	e VII								
1039	Mailbox Structures - Ph. VII - Replace	2003	2027	24	0	4	3 ea	1,625.26	4,876
1047	Pavement Overlay Phase VII	2003	2029	30	-4	6	46,140 sf	2.96	136,574
1056	Pavement Seal Coat Phase VII	2023	2029	6	0	6	46,140 sf	0.22	10,151
Phase	e VII - Total:								\$151,601
Phase	e VIII								
1048	Pavement Overlay Phase VIII	2010	2041	30	1	18	44,380 sf	2.96	131,365
1057	Pavement Seal Coat Phase VIII	2023	2029	6	0	6	44,380 sf	0.22	9,764
Phase	e VIII - Total:								\$141,128
Phase	e IX								
1009	Concete - Curb Ph. IX - 10% Repair	2015	2035	5	15	12	327 lf	33.87 @10.0%	1,108
1044	Pavement Overlay Phase IX	2015	2041	30	-4	18	43,822 sf	2.96	129,713
1053	Pavement Seal Coat Phase IX	2023	2029	6	0	6	43,822 sf	0.22	9,641
Phase	e IX - Total:								\$140,462
Phase	e X								
1010	Concrete Surfaces - Ph. X - 3% Repair	2007	2027	5	15	4	4,085 sf	16.25@3.0%	1,991
1017	Fence - Metal/Brick - Ph. X - Replace	Unfunded							
1020	Gate Entry Access - Ph. X - Replace	Unfunded							
1021	Gate Operators - Ph. X - Replace	Unfunded							
1022	Gates - Ph. X - Refurbish	Unfunded							
1023	Gates - Ph. X - Replace	Unfunded					_		
1049	Pavement Overlay Phase X	2007	2035	30	-2	12	20,964 sf	2.96	62,053
1058	Pavement Seal Coat Phase X	2023	2029	6	0	6	20,964 sf	0.22	4,612
1064	Sign - Entry - Ph. X - Replace	Unfunded							
	e X - Total:								\$68,657
IULAI A	asset Summary:								\$1,949,334



The above chart illustrates the current cost breakdown percentage of the Component Categories in this reserve study (highest percentage components listed at top). Special attention should be given to those component categories which take up a bulk of the % of the current cost as these may require significant planning to adequately budget for their replacement. These large expenses may be well into the future during "Peak Year" cycles. Refer to the Cash Flow Projections and the Annual Expenditure Report for the projected timeline of expected expenditures.




The above chart compares the funding models by the percentage funded levels over the 30-year timeframe of this reserve study, as calculated at the end of each fiscal year.

The <u>Recommended Funding Model</u> increase the Client's reserve account Percent Funded Level to 100% funding within the timeframe of this study. Once this 100% funded level is reached it is a good indicator that the Client is on track to meet its future obligations with minimal risk of reliance on emergency financing or having to defer projects that come due.

The <u>Baseline Funding Model</u> has only a goal of keeping the reserve account cash positive within the timeframe of the reserve study. This model carries significant risk for reliance on emergency financing and/or having to defer projects due to the common occurrence of components failing earlier than projected or costs increasing more rapidly than projected.

The <u>100% Funded Model</u> assumes the reserve account is an average of 100% Funded in each year of the reserve study. This model minimizes risk for reliance on emergency financing and places the reserve account onto a low risk path for budgeting.

#### Villages of Garrison Creek HOA Projected Reserve Account Balance Chart



The chart above compares the annual year-end balance of the reserve account for the respective funding models over the 30 years covered in this reserve study. Projected reserve account balances will see large fluctuations from year to year due to projects occurring in any given year.

#### Villages of Garrison Creek HOA 100% Funded - Summary

Report Date	August 22, 2022
Account Number	16951
Version	Draft2
Budget Year Beginning	January 1, 2023
Budget Year Ending	December 31, 2023
Total Units	240

Report Parameters	
Inflation	3.50%
Annual Contribution Increase	3.50%
Interest Rate on Reserve Deposit	0.35%
Tax Rate Included in Interest Rate	
2023 Beginning Balance	\$422,061

This funding model has a goal of being a minimum of 100% funded, annually, over the timeframe of this reserve study. Allocation rates will fluctuate based on the expenditures projected in any given year. The initial year has a much higher allocation rate than subsequent years as the reserve account is currently underfunded and requires a significant cash injection in the initial fiscal year to elevate the reserve account to a 100% Funded track.

The following page provides the 30-year projections for this funding model.

#### Full Funding Model 30 Year Summary of Calculations

Required Annual Contribution Average Net Annual Interest Earned Total Annual Allocation to Reserves \$942,865.61 <u>\$3,595.48</u> \$946,461.09

### Villages of Garrison Creek HOA 100% Funded - Year End Projections

Begining Balance: \$422,061

	Beginin	g Balance	: \$422,061				5	.C	
Key.	S. S	h Making	Allogico Allogico Allogico	410 % 0,00 %	Net Net	to of of of the	100 100 100 100 100 100 100 100 100 100		rest from the second se
2023	1,949,334	3.5%	942,866		3,595	337,647	1,030,875	1,030,875	100%
2024	1,887,970	3.5%	229,901	-75.61%	4,034	108,125	1,156,685	1,153,632	100%
2025	1,954,049	3.5%	237,947	3.50%	4,572	88,223	1,310,982	1,308,234	100%
2026	2,022,441	3.5%	246,275	3.50%	4,972	136,593	1,425,636	1,425,636	100%
2027	2,093,226	3.5%	245,702	-0.23%	5,280	162,711	1,513,907	1,513,907	100%
2028	2,146,465	3.5%	234,670	-4.48%	5,290	237,155	1,516,712	1,516,712	100%
2029	2,199,394	3.5%	,226,783	-3.36%	2,988	, 889,777	856,707	850,382	101%
2030	2,276,373	3.5%	234,720	3.50%	, 3,479	, 97,483	997,423	987,806	101%
2031	2,356,046	3.5%	242,936	3.50%	3,842	142,510	1,101,691	1,090,737	101%
2032	2,438,508	3.5%	251,438	3.50%	4,451	81,525	1,276,056	1,267,945	101%
2033	2,523,855	3.5%	260,239	3.50%	4,143	352,448	1,187,990	1,178,769	101%
2034	2,612,190	3.5%	269,347	3.50%	4,829	77,643	1,384,523	1,378,988	100%
2035	2,703,617	3.5%	278,774	3.50%	4,678	326,748	1,341,227	1,336,796	100%
2036	2,798,244	3.5%	296,922	6.50%	5,231	143,488	1,499,892	1,491,472	101%
2037	2,896,182	3.5%	307,314	3.50%	5 <i>,</i> 907	119,519	1,693,593	1,685,342	100%
2038	2,997,548	3.5%	318,070	3.50%	5 <i>,</i> 959	309,018	1,708,604	1,699,156	101%
2039	3,102,463	3.5%	329,202	3.50%	6,653	136,902	1,907,558	1,901,206	100%
2040	3,211,049	3.5%	340,725	3.50%	7,222	184,739	2,070,766	2,070,766	100%
2041	3,323,436	3.5%	348,069	2.15%	5,871	741,499	1,683,207	1,679,304	100%
2042	3,439,756	3.5%	360,252	3.50%	5,815	382,140	1,667,133	1,656,701	101%
2043	3,560,147	3.5%	372,861	3.50%	5,757	395,207	1,650,544	1,630,777	101%
2044	3,684,752	3.5%	385,911	3.50%	6,620	145,108	1,897,967	1,874,178	101%
2045	3,813,719	3.5%	399,418	3.50%	7,204	239,169	2,065,419	2,040,523	101%
2046	3,947,199	3.5%	413,397	3.50%	8,012	189,772	2,297,056	2,276,006	101%
2047	4,085,351	3.5%	427,866	3.50%	8,149	396,582	2,336,490	2,318,299	101%
2048	4,228,338	3.5%	442,842	3.50%	7,891	524,887	2,262,334	2,242,335	101%
2049	4,376,330	3.5%	458,341	3.50%	9,059	132,531	2,597,203	2,583,315	101%
2050	4,529,501	3.5%	487,708	6.40%	10,236	160,401	2,934,745	2,921,373	100%
2051	4,688,034	3.5%	504,778	3.50%	10,798	354,517	3,095,804	3,084,831	100%
2052	4,852,115	3.5%	522,446	3.50%	12,108	158,952	3,471,405	3,471,405	100%

#### Villages of Garrison Creek HOA Recommended Funding - Summary

Report Date	August 22, 2022
Account Number	16951
Version	Draft2
Budget Year Beginning	January 1, 2023
Budget Year Ending	December 31, 2023
Total Units	240

Report Parameters	
Inflation	3.50%
Interest Rate on Reserve Deposit Tax Rate Included in Interest Rate	0.35%
2023 Beginning Balance	\$422,061

We have developed a funding plan which will help steer the reserve account into a high funded range within the 30-year timeframe of this reserve study. This Recommended Funding Model requires the Client to allocate the recommended allocation amount into the reserve account with annual increases thereafter. In the following pages you will find the recommended allocation rates to the reserve account, annual projected expenditures and the percent funded of the reserve account if following this Recommended Funding Model.

#### This Recommended Funding Plan Considers 4 Basic Principles:

- 1. There are adequate reserves when needed.
- 2. The budget should remain stable but increasing to offset inflationary factors.
- 3. The costs are fairly distributed over time.
- 4. The funding plan must allow the Client to be fiscally responsible.

Note that the Recommended Model is not a low risk, no risk or ideal model to follow. It simply has a goal of having the reserve account reach 100% funded by the end of a 30-year time period. In this reserve study the model's initial years remain in a "Low" funded range with a high risk for reliance on special assessments and or loans should something occur that is not projected (e.g., very high inflation of project costs, components failing earlier than projected, etc.). An "ideal" model to follow would be the 100% funded model as this model has the reserve account funded to a 100% funded level each year of the study and there would be low risk for reliance on special assessments and/or loans even if unexpected occurrences came to fruition.

The following page provides the 30-year projections for this funding model.

Recommended Funding Model Summary of Calculati	ons
Required Annual Contribution	\$225,000.00
Average Net Annual Interest Earned	\$1,082.95
Total Annual Allocation to Reserves	\$226,082.95

### Villages of Garrison Creek HOA Recommended Funding - Year End Projections

Begining Balance: \$422,061

Degining Datance. \$422,001						×	5	હ્ય	
to to	S. S	hnation Ration	Reserve	410 60,00 60,00	Net Net	to t	A C C C C C C C C C C C C C C C C C C C	Key End	rest from the set of t
2023	1,949,334	3.5%	225,000		1,083	337,647	310,497	1,030,875	30%
2024	1,887,970	3.5%	232,875	3.50%	, 1,523	108,125	436,770	1,153,632	38%
2025	1,954,049	3.5%	241,026	3.50%	2,064	88,223	591,637	1,308,234	45%
2026	2,022,441	3.5%	249,462	3.50%	2,466	136,593	706,971	1,425,636	50%
2027	2,093,226	3.5%	258,193	3.50%	2,809	162,711	805,261	1,513,907	53%
2028	2,146,465	3.5%	267,229	3.50%	2,924	237,155	838,259	1,516,712	55%
2029	2,199,394	3.5%	276,582	3.50%	788	889,777	225,853	850 <i>,</i> 382	27%
2030	2,276,373	3.5%	283,912	2.65%	1,443	97 <i>,</i> 483	413,725	987,806	42%
2031	2,356,046	3.5%	291,436	2.65%	1,969	142,510	564,620	1,090,737	52%
2032	2,438,508	3.5%	299,159	2.65%	2,738	81,525	784,992	1,267,945	62%
2033	2,523,855	3.5%	307 <i>,</i> 086	2.65%	2,589	352,448	742,219	1,178,769	63%
2034	2,612,190	3.5%	315,224	2.65%	3,429	77,643	983,229	1,378,988	71%
2035	2,703,617	3.5%	323,578	2.65%	3,430	326,748	983,489	1,336,796	74%
2036	2,798,244	3.5%	332,152	2.65%	4,103	143,488	1,176,256	1,491,472	79%
2037	2,896,182	3.5%	340,954	2.65%	4,892	119,519	1,402,583	1,685,342	83%
2038	2,997,548	3.5%	349,990	2.65%	5,052	309,018	1,448,607	1,699,156	85%
2039	3,102,463	3.5%	359,264	2.65%	5,848	136,902	1,676,817	1,901,206	88%
2040	3,211,049	3.5%	368,785	2.65%	6,513	184,739	1,867,376	2,070,766	90%
2041	3,323,436	3.5%	378,558	2.65%	5,266	741,499	1,509,700	1,679,304	90%
2042	3,439,756	3.5%	388,589	2.65%	5,307	382,140	1,521,456	1,656,701	92%
2043	3,560,147	3.5%	398,887	2.65%	5,338	395,207	1,530,474	1,630,777	94%
2044	3,684,752	3.5%	409,458	2.65%	6,282	145,108	1,801,106	1,874,178	96%
2045	3,813,719	3.5%	420,308	2.65%	6,938	239,169	1,989,183	2,040,523	97%
2046	3,947,199	3.5%	431,446	2.65%	7,808	189,772	2,238,665	2,276,006	98%
2047	4,085,351	3.5%	442,880	2.65%	7,997	396,582	2,292,961	2,318,299	99%
2048	4,228,338	3.5%	454,616	2.65%	7,779	524,887	2,230,469	2,242,335	99%
2049	4,376,330	3.5%	466,663	2.65%	8,976	132,531	2,573,577	2,583,315	100%
2050	4,529,501	3.5%	479,030	2.65%	10,123	160,401	2,902,328	2,921,373	99%
2051	4,688,034	3.5%	491,724	2.65%	10,638	354,517	3,050,173	3,084,831	99%
2052	4,852,115	3.5%	504,755	2.65%	11,886	158,952	3,407,862	3,471,405	98%

#### Villages of Garrison Creek HOA Alternate Recommended Model - Diff. Annual % Increase - Summary

	Report Parameters
Report DateAugust 22, 2022Account Number16951VersionDraft2Budget Year BeginningJanuary 1, 2023Budget Year EndingDecember 31, 2023	Inflation Interest Rate on Reserve Deposit Tax Rate Included in Interest Rate
Total Units 240	2023 Beginning Balance

This funding model has been included as an alternative to the regular Recommended Model (which utilizes an annual reserve contribution percentage increase rate that is similar to the inflation rate). This alternative model has a goal of reaching 100% funded by the end of a 30-year period but starts with a higher or lower reserve allocation rate and increases at a significantly higher or lower annual percentage increase (i.e., the annual reserve allocation percentage change is significantly higher or lower than the projected inflation rate) until the reserve account reaches the 100% funded level by the end of the 30-years of projections.

It is important to note that there is not a "right or wrong" Recommended Funding Model as mathematically it is a sliding scale between the reserve contribution rate and the annual increase/decrease percent (i.e., a higher initial annual reserve allocation rate will require a lower annual percentage increase and vice versa - a lower initial annual reserve allocation rate will require a higher annual percentage increase rate to the model to meet the same goal, in this case to be 100% funded by the end of a 30-year period). This type of funding model does not necessarily consider fairness to the membership as a projected allocation rate significantly different than the projected inflation rate, over time, will not follow the actual purchasing power of the dollar in any specific period.

Difficulties in following a model with a higher annual percentage increase can include limitations on the percentage increase outlined in the governing documents, limitations on the percentage increase outlined in statutory laws, changing Boards (with different ideas) over time, and getting a community to agree to a higher increase to the reserve allocation rate for an extended period.

The following page provides the 30-year projections for this funding model.

#### Diff. Annual % Allocation Model Summary of Calculations

Required Annual Contribution Average Net Annual Interest Earned Total Annual Allocation to Reserves \$177,000.00 <u>\$914.95</u> \$177,914.95

3.50%

0.35%

\$422,061

#### Villages of Garrison Creek HOA Alternate Recommended Model - Diff. Annual % Increase - Year End Projections

Begining Balance: \$422,061

Begining Balance: \$422,061							5	.Q	
les.	St.	hallon	Reserve	410 % 0,000 %	Net Net	CO C	10 10 10 10 10 10 10 10 10 10 10 10 10 1		12 12 12 12 12 12 12 12 12 12 12 12 12 1
2023	1,949,334	3.5%	177,000		915	337,647	262,329	1,030,875	25%
2024	1,887,970	3.5%	194,700	10.00%	1,221	108,125	350,125	1,153,632	30%
2025	1,954,049	3.5%	214,170	10.00%	1,666	88,223	477,739	1,308,234	37%
2026	2,022,441	3.5%	235,587	10.00%	2,019	136,593	578,751	1,425,636	41%
2027	2,093,226	3.5%	259,146	10.00%	2,363	162,711	677,549	1,513,907	45%
2028	2,146,465	3.5%	285,060	10.00%	2,539	237,155	727,993	1,516,712	48%
2029	2,199,394	3.5%	313,566	10.00%	531	889,777	152,314	850,382	18%
2030	2,276,373	3.5%	318,740	1.65%	1,308	97,483	374,879	987,806	38%
2031	2,356,046	3.5%	323,999	1.65%	1,947	142,510	558,316	1,090,737	51%
2032	2,438,508	3.5%	329 <i>,</i> 345	1.65%	2,821	81,525	808,958	1,267,945	64%
2033	2,523,855	3.5%	334,780	1.65%	2,770	352,448	794,059	1,178,769	67%
2034	2,612,190	3.5%	340,303	1.65%	3,699	77,643	1,060,418	1,378,988	77%
2035	2,703,617	3.5%	345 <i>,</i> 918	1.65%	3,779	326,748	1,083,367	1,336,796	81%
2036	2,798,244	3.5%	351,626	1.65%	4,520	143,488	1,296,025	1,491,472	87%
2037	2,896,182	3.5%	357,428	1.65%	5,369	119,519	1,539,303	1,685,342	91%
2038	2,997,548	3.5%	363 <i>,</i> 325	1.65%	5,578	309,018	1,599,188	1,699,156	94%
2039	3,102,463	3.5%	369 <i>,</i> 320	1.65%	6,411	136,902	1,838,017	1,901,206	97%
2040	3,211,049	3.5%	375,414	1.65%	7,100	184,739	2,035,792	2,070,766	98%
2041	3,323,436	3.5%	381,608	1.65%	5,866	741,499	1,681,767	1,679,304	100%
2042	3,439,756	3.5%	387,905	1.65%	5,906	382,140	1,693,438	1,656,701	102%
2043	3,560,147	3.5%	394,305	1.65%	5,924	395,207	1,698,461	1,630,777	104%
2044	3,684,752	3.5%	400,811	1.65%	6,840	145,108	1,961,004	1,874,178	105%
2045	3,813,719	3.5%	407,425	1.65%	7,452	239,169	2,136,712	2,040,523	105%
2046	3,947,199	3.5%	414,147	1.65%	8,264	189,772	2,369,351	2,276,006	104%
2047	4,085,351	3.5%	420,981	1.65%	8,378	396,582	2,402,128	2,318,299	104%
2048	4,228,338	3.5%	427,927	1.65%	8,068	524,887	2,313,236	2,242,335	103%
2049	4,376,330	3.5%	434,988	1.65%	9,155	132,531	2,624,847	2,583,315	102%
2050	4,529,501	3.5%	442,165	1.65%	10,173	160,401	2,916,784	2,921,373	100%
2051	4,688,034	3.5%	449,461	1.65%	10,541	354,517	3,022,269	3,084,831	98%
2052	4,852,115	3.5%	456,877	1.65%	11,621	158,952	3,331,814	3,471,405	96%

#### Villages of Garrison Creek HOA Baseline Funding - Summary

Report Date	August 22, 2022
Account Number	16951
Version	Draft2
Budget Year Beginning	January 1, 2023
Budget Year Ending	December 31, 2023
Total Units	240

#### **Report Parameters**

Inflation	3.50%
Annual Contribution Increase	3.50%
Interest Rate on Reserve Deposit	0.35%
Tax Rate Included in Interest Rate	
2023 Beginning Balance	\$422,061

The Baseline Funding Model is considered a bare minimum approach which has a goal of keeping the reserve account balance above \$0 within the 30-year timeframe of this reserve study and <u>does not</u> take into consideration projected expenses that fall outside of the 30-year timeframe of the reserve study (i.e. longer life components are simply ignored).

This funding model carries a higher risk for reliance on emergency financing specifically in years when large component expenses occur earlier than projected or costs see significant increases. Additionally, in the future when longer life components come into the 30-year timeframe of future reserve studies their projected expenditures will have a significant impact on the allocation requirements to keep the reserve account cash positive going forward.

Should the Client have an interest in not funding longer life component projects (i.e. projects that are set to occur after the 30 year projections in this study) at this time then we suggest setting a goal of at least funding to the Baseline Funding Model which has the goal of only staying cash positive for the 30 year time-frame of the projections in this study.

The following page provides the 30-year projections for this funding model.

#### Baseline Threshold Funding Model Summary of Calculations

Required Annual Contribution Average Net Annual Interest Earned Total Annual Allocation to Reserves \$196,357.87 \$982.70 \$197,340.57

### Villages of Garrison Creek HOA Baseline Funding - Year End Projections

Begining Balance: \$422,061

Begining Balance: \$422,001					x c	°	æ		
ka,	S. S	h Mation Adress	All	410 % Cotto	No. 100	o o o o o o o o o o o o o o o o o o o	Le la	ka k	rest from the set of t
2023	1,949,334	3.5%	196,358		983	337,647	281,754	1,030,875	27%
2023	1,887,970	3.5%	203,230	3.50%	1,319	108,125	378,179	1,153,632	33%
2024	1,887,970	3.5%	203,230 210,343	3.50%	1,751	88,223	502,051	1,308,234	33 <i>%</i>
2025	2,022,441	3.5% 3.5%	210,343 217,705	3.50%	2,041	88,225 136,593	502,051 585,204	1,308,234	58% 41%
2020	2,022,441 2,093,226	3.5%	225,325	3.50%	2,041	162,711	650,086	1,425,050	41%
2027	2,095,220 2,146,465	3.5%	223,323	3.50%	2,207 2,261	237,155	648,404	1,516,712	43 <i>%</i> 43%
2028	2,140,403 2,199,394	3.5%	233,212	3.50%	2,201	889,777	048,404 1	850,382	43 <i>%</i> 0%
2029	2,139,394 2,276,373	3.5%	196,730	-18.49%	347	97,483	99,596	987,806	0% 10%
2030	2,270,373 2,356,046	3.5%	203,616	3.50%	562	142,510	161,264	1,090,737	10%
2031	2,438,508	3.5%	203,010 210,742	3.50%	1,017	81,525	291,498	1,267,945	23%
2032	2,438,508	3.5%	218,118	3.50%	550	352,448	157,719	1,178,769	13%
2033	2,612,190	3.5%	225,752	3.50%	1,070	77,643	306,898	1,378,988	22%
2034	2,703,617	3.5%	233,654	3.50%	748	326,748	214,553	1,336,796	16%
2035	2,798,244	3.5%	241,832	3.50%	1,095	143,488	313,991	1,491,472	21%
2030	2,896,182	3.5%	250,296	3.50%	1,557	119,519	446,324	1,685,342	26%
2038	2,997,548	3.5%	259,056	3.50%	1,387	309,018	397,749	1,699,156	23%
2039	3,102,463	3.5%	268,123	3.50%	1,851	136,902	530,821	1,901,206	28%
2040	3,211,049	3.5%	277,507	3.50%	2,183	184,739	625,772	2,070,766	30%
2041	3,323,436	3.5%	287,220	3.50%	600	741,499	172,093	1,679,304	10%
2042	3,439,756	3.5%	297,273	3.50%	305	382,140	87,531	1,656,701	5%
2043	3,560,147	3.5%	307,677	3.50%		395,207	1	1,630,777	0%
2044	3,684,752	3.5%	318,446	3.50%	607	145,108	173,946	1,874,178	9%
2045	3,813,719	3.5%	329,592	3.50%	925	239,169	265,294	2,040,523	13%
2046	3,947,199	3.5%	, 341,127	3.50%	1,458	189,772	418,107	2,276,006	18%
2047	4,085,351	3.5%	353,067	3.50%	1,311	396,582	375,903	2,318,299	16%
2048	4,228,338	3.5%	365,424	3.50%	758	524,887	217,197	2,242,335	10%
2049	4,376,330	3.5%	378,214	3.50%	1,620	132,531	464,500	2,583,315	18%
2050	4,529,501	3.5%	391,451	3.50%	2,434	160,401	697,984	2,921,373	24%
2051	4,688,034	3.5%	405,152	3.50%	2,620	354,517	751,239	3,084,831	24%
2052	4,852,115	3.5%	419,332	3.50%	3,541	158,952	1,015,160	3,471,405	29%

#### Villages of Garrison Creek HOA Current Funding - Summary

	Report Parameters
Report DateAugust 22, 2022Account Number16951VersionDraft2Budget Year BeginningJanuary 1, 2023Budget Year EndingDecember 31, 2023	Inflation3.50%Annual Contribution Increase3.50%Interest Rate on Reserve Deposit0.35%Tax Rate Included in Interest Rate
Total Units 240	2023 Beginning Balance \$422,061

The Current Funding Model is based on the reserve allocation data supplied by the Client; it has not been independently verified and is assumed to be correct.

The following page provides the 30-year projections for this funding model. It is assumed the reserve allocation rate will have annual increases to offset inflationary factors.


#### Current Assessment Funding Model Summary of Calculations

Required Annual Contribution Average Net Annual Interest Earned Total Annual Allocation to Reserves \$177,987.00 \$918.40 \$178,905.40

### Villages of Garrison Creek HOA Current Funding - Year End Projections

Begining Balance: \$422,061

					×	ş	æ	
ost see	hy Mation Bate	Heser More	40000000000000000000000000000000000000	Nex 11/20		Pest Find	Как Насто Насто	rear find
								26%
			3 50%					30%
								34%
		,						36%
		•				•		36%
		•				•		35%
		•		,	•	•		
		•			•			
2,356,046	3.5%	234,375	3.50%	268	142,510	76,746	1,090,737	7%
2,438,508	3.5%	242,578	3.50%	832	81,525	238,631	1,267,945	19%
2,523,855	3.5%	251,068	3.50%	480	352,448	137,732	1,178,769	12%
2,612,190	3.5%	259 <i>,</i> 856	3.50%	1,120	77,643	321,065	1,378,988	23%
2,703,617	3.5%	268,951	3.50%	921	326,748	264,189	1,336,796	20%
2,798,244	3.5%	278,364	3.50%	1,397	143,488	400,461	1,491,472	27%
2,896,182	3.5%	288,107	3.50%	1,992	119,519	571,040	1,685,342	34%
2,997,548	3.5%	298,190	3.50%	1,961	309,018	562,173	1,699,156	33%
3,102,463	3.5%	308,627	3.50%	2,569	136,902	736,467	1,901,206	39%
3,211,049	3.5%	319,429	3.50%	3 <i>,</i> 049	184,739	874,205	2,070,766	42%
3,323,436	3.5%	330,609	3.50%	1,622	741,499	464,937	1,679,304	28%
3,439,756	3.5%	342,180	3.50%	1,487	382,140	426,464	1,656,701	26%
3,560,147	3.5%	354,157	3.50%	1,349	395,207	386,763	1,630,777	24%
3,684,752	3.5%	366,552	3.50%	2,129	145,108	610,336	1,874,178	33%
3,813,719	3.5%	379,381	3.50%	2,627	239,169	753,175	2,040,523	37%
3,947,199	3.5%	392 <i>,</i> 660	3.50%	3,346	189,772	959,409	2,276,006	42%
4,085,351	3.5%	406,403	3.50%	3,392	396,582	972,622	2,318,299	42%
4,228,338	3.5%	420,627	3.50%	3,039	524,887	871,401	2,242,335	39%
4,376,330	3.5%	435,349	3.50%	4,110	132,531	1,178,328	2,583,315	46%
4,529,501	3.5%	450,586	3.50%	5,140	160,401	1,473,653	2,921,373	50%
4,688,034	3.5%	466,357	3.50%	5,549	354,517	1,591,041	3,084,831	52%
4,852,115	3.5%	482,679	3.50%	6,702	158,952	1,921,470	3,471,405	55%
	1,949,334 1,887,970 1,954,049 2,022,441 2,093,226 2,146,465 2,199,394 2,276,373 2,356,046 2,438,508 2,523,855 2,612,190 2,703,617 2,798,244 2,896,182 2,997,548 3,102,463 3,211,049 3,323,436 3,439,756 3,560,147 3,684,752 3,813,719 3,947,199 4,085,351 4,228,338 4,376,330 4,529,501 4,688,034	1,949,3343.5%1,887,9703.5%1,954,0493.5%2,022,4413.5%2,093,2263.5%2,146,4653.5%2,199,3943.5%2,276,3733.5%2,356,0463.5%2,523,8553.5%2,612,1903.5%2,798,2443.5%2,798,2443.5%2,997,5483.5%3,102,4633.5%3,211,0493.5%3,560,1473.5%3,560,1473.5%3,560,1473.5%3,560,1473.5%3,560,1473.5%3,560,1473.5%3,947,1993.5%4,085,3513.5%4,228,3383.5%4,228,3383.5%4,529,5013.5%4,688,0343.5%	$\chi$	1,949,3343.5%177,9871,887,9703.5%184,2173.50%1,954,0493.5%190,6643.50%2,022,4413.5%197,3373.50%2,093,2263.5%204,2443.50%2,146,4653.5%211,3933.50%2,199,3943.5%218,7913.50%2,276,3733.5%226,4493.50%2,356,0463.5%234,3753.50%2,438,5083.5%242,5783.50%2,523,8553.5%251,0683.50%2,612,1903.5%259,8563.50%2,703,6173.5%268,9513.50%2,798,2443.5%278,3643.50%2,896,1823.5%288,1073.50%3,102,4633.5%308,6273.50%3,211,0493.5%319,4293.50%3,439,7563.5%342,1803.50%3,560,1473.5%354,1573.50%3,684,7523.5%366,5523.50%3,813,7193.5%379,3813.50%3,947,1993.5%392,6603.50%4,376,3303.5%420,6273.50%4,376,3303.5%450,5863.50%4,688,0343.5%466,3573.50%	$k^{0}$ $k^{0}$ $k^{0}$ $k^{0}$ $k^{0}$ $k^{0}$ $k^{0}$ $k^{0}$ $k^{0}$ 1,949,3343.5%177,9879181,887,9703.5%184,2173.50%1,1881,954,0493.5%190,6643.50%1,5512,022,4413.5%197,3373.50%1,7692,093,2263.5%204,2443.50%1,9202,146,4653.5%211,3933.50%1,8372,199,3943.5%218,7913.50%2,276,3733.5%226,4493.50%2,356,0463.5%234,3753.50%2,523,8553.5%251,0683.50%2,612,1903.5%259,8563.50%2,703,6173.5%268,9513.50%2,798,2443.5%278,3643.50%3,102,4633.5%308,6273.50%3,23,4363.5%308,6273.50%3,23,4363.5%342,1803.50%3,439,7563.5%342,1803.50%3,439,7563.5%342,1803.50%3,431,7193.5%379,3813.50%3,447,1993.5%392,6603.50%3,437,1993.5%420,6273.50%3,437,1993.5%420,6273.50%4,228,3383.5%420,6273.50%4,376,3303.5%450,5863.50%4,376,3303.5%450,5863.50%4,688,0343.5%466,3573.50% <td>1.949,334         3.5%         177,987         918         337,647           1,887,970         3.5%         184,217         3.50%         1,188         108,125           1,954,049         3.5%         190,664         3.50%         1,551         88,223           2,022,441         3.5%         197,337         3.50%         1,769         136,593           2,093,226         3.5%         204,244         3.50%         1,920         162,711           2,146,465         3.5%         211,393         3.50%         1,837         237,155           2,199,394         3.5%         218,791         3.50%         97,483           2,356,046         3.5%         234,375         3.50%         268         142,510           2,438,508         3.5%         242,578         3.50%         832         81,525           2,523,855         3.5%         251,068         3.50%         120         77,643           2,703,617         3.5%         268,951         3.50%         121         77,643           2,798,244         3.5%         298,190         3.50%         1,992         119,519           2,997,548         3.5%         298,190         3.50%         1,991</td> <td><math display="block">\begin{array}{cccccccccccccccccccccccccccccccccccc</math></td> <td><math display="block">\begin{array}{cccccccccccccccccccccccccccccccccccc</math></td>	1.949,334         3.5%         177,987         918         337,647           1,887,970         3.5%         184,217         3.50%         1,188         108,125           1,954,049         3.5%         190,664         3.50%         1,551         88,223           2,022,441         3.5%         197,337         3.50%         1,769         136,593           2,093,226         3.5%         204,244         3.50%         1,920         162,711           2,146,465         3.5%         211,393         3.50%         1,837         237,155           2,199,394         3.5%         218,791         3.50%         97,483           2,356,046         3.5%         234,375         3.50%         268         142,510           2,438,508         3.5%         242,578         3.50%         832         81,525           2,523,855         3.5%         251,068         3.50%         120         77,643           2,703,617         3.5%         268,951         3.50%         121         77,643           2,798,244         3.5%         298,190         3.50%         1,992         119,519           2,997,548         3.5%         298,190         3.50%         1,991	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	$\begin{array}{cccccccccccccccccccccccccccccccccccc$



The above chart provides a visual of the reserve account projected expenditures over the 30 years covered in this study. We suggest making a note of large expenditure years (peak years) when there will be significant projected expenditures related to one or more component projects that will require repair/replacement. These large but infrequent component expenses during "peak" years are typically the most difficult to budget for as they are often overlooked or ignored due to the perception that the expenses are far in the future and there will be time to budget for them later.

Description		Expenditures
Replacement	Year 2023	
1103-0	GVW Concrete - Grinding	3,473
1086-0	GVW Tree Care	5,620
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	11,240
1113	Non GVW Tree/Shrub/Other - Common Area Refurbishment	11,240
1027-01b	Non-GVW Concrete (2022) - Replacement	18,057
1103-01	Non-GVW Concrete - Grinding	3,473
1086-01	Non-GVW Tree Care	5,620
1109	Pavement - Crack Sealing & Repair	18,000
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	4,631
1029	Irrrigation Backflow Devices - 11% replace	1,003
1008	Clock Tower Paint / Repair Contingency	1,204
1005	Bridges Paint Wood Surfaces	857
1095	UG Sprinkler Pipe Master Areas 4.8%	99,483
1012	Creek Pump House Shed Repair Contingency	3,633
1099	Well Pump - Replace	15,371
1040c	Mailbox Wooden Structures (Village 9) - Replace	1,625
1035	Mailbox Structures - Ph. I - Replace	3,220
1036	Mailbox Structures - Ph. II - Replace	4,689
1105	Pavement Replacement Phase I	105,960
1111	Pavement Replacement Phase V Alley	19,248
Total for 2023	3	\$337,647

#### Replacement Year 2024

Total for 2024		\$108,125
1038	Mailbox Structures - Ph. VI - Replace	3,364
1028	Irrigation Controllers 20% Replace	17,069
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	3,490
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	4,793
1109	Pavement - Crack Sealing & Repair	18,630
1086-01	Non-GVW Tree Care	5,817
1103-01	Non-GVW Concrete - Grinding	3,595
1027-01b	Non-GVW Concrete (2022) - Replacement	18,689
1113	Non GVW Tree/Shrub/Other - Common Area Refurbishment	11,633
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	11,633
1086-0	GVW Tree Care	5,817
1103-0	GVW Concrete - Grinding	3 <i>,</i> 595

Description		Expenditures							
Replacement	Replacement Year 2025								
1103-0	GVW Concrete - Grinding	3,721							
1086-0	GVW Tree Care	6,020							
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	12,041							
1113	Non GVW Tree/Shrub/Other - Common Area Refurbishment	12,041							
1027-01b	Non-GVW Concrete (2022) - Replacement	19,343							
1103-01	Non-GVW Concrete - Grinding	3,721							
1086-01	Non-GVW Tree Care	6,020							
1109	Pavement - Crack Sealing & Repair	19,282							
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	4,961							
1029	Irrrigation Backflow Devices - 11% replace	1,074							
Total for 2025	5	\$88,223							
Replacement	Voor 2026								
1103-0	GVW Concrete - Grinding	3,851							
1086-0	GVW Concrete - Grinding GVW Tree Care	6,231							
1080-0	GVW Tree/Shrub/Other - Common Area Refurbishment	12,462							
1112	Non GVW Tree/Shrub/Other - Common Area Refurbishment	12,462							
	Non-GVW Concrete (2022) - Replacement	20,020							
1103-01	Non-GVW Concrete - Grinding	3,851							
1086-01	Non-GVW Tree Care	6,231							
1080-01									
1096	Pavement - Crack Sealing & Repair	19,957							
1098	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	5,134							
1008	Clock Tower Paint / Repair Contingency	1,335							
	Bridge Pond - Replace	8,340							
1004	Bridges 1, 2, 3 - Replace	34,553							
1015	Entry Sign & Monument - Refurbish	2,166							
Total for 2026	5	\$136,593							
Replacement	Year 2027								
1103-0	GVW Concrete - Grinding	3,986							
1086-0	GVW Tree Care	6,449							
1112b	GVW Tree/Shrub (2027) - Refurbishment	3,869							
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	12,898							
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	3,869							
1113	Non GVW Tree/Shrub/Other - Common Area Refurbishment	12,898							

Description		Expenditures
Replacement	Year 2027 continued	
1027-01b	Non-GVW Concrete (2022) - Replacement	20,721
1103-01	Non-GVW Concrete - Grinding	3,986
1086-01	Non-GVW Tree Care	6,449
1109	Pavement - Crack Sealing & Repair	20,655
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	5,314
1029	Irrrigation Backflow Devices - 11% replace	1,151
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	3,869
1028	Irrigation Controllers 20% Replace	18,925
1010	Concrete Surfaces - Ph. X - 3% Repair	2,285
1027-0	GVW Concrete - Replacement	3,948
1025	Gazebo - Paint	2,638
1097	Well Clock Tower - Repair Contingency	2,990
1084	Sump Pump Backup Generator - Replace	14,765
1039	Mailbox Structures - Ph. VII - Replace	5,595
1102	Fence & Gate (lions park) - Replace	5,450
Total for 202	7	\$162,711
Replacement	Vear 2028	
1103-0	GVW Concrete - Grinding	4,125
1103-0 1112b	GVW Tree/Shrub (2027) - Refurbishment	4,005
11125	GVW Tree/Shrub/Other - Common Area Refurbishment	13,350
1112 1113b	Non GVW Tree/Shrub (2027) - Refurbishment	4,005
	Non-GVW Concrete (2022) - Replacement	21,446
1103-01	Non-GVW Concrete - Grinding	4,125
1086-01	Non-GVW Tree Care	6,675
1109	Pavement - Crack Sealing & Repair	21,378
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	5,500
1005	Bridges Paint Wood Surfaces	1,018
1027-01	Non-GVW Concrete - Replacement	33,374
1095	UG Sprinkler Pipe Master Areas 4.8%	118,155
Total for 202		\$237,155
		3237,133
Replacement Year 2029		
1103-0	GVW Concrete - Grinding	4,269

1100 0		1,203
1112b	GVW Tree/Shrub (2027) - Refurbishment	4,145

Description		Expenditures
Replacement	Year 2029 continued	
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	13,817
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	4,145
1103-01	Non-GVW Concrete - Grinding	4,269
1086-01	Non-GVW Tree Care	6,908
1109	Pavement - Crack Sealing & Repair	22,127
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	5,693
1029	Irrrigation Backflow Devices - 11% replace	1,232
1008	Clock Tower Paint / Repair Contingency	1,480
1012	Creek Pump House Shed Repair Contingency	4,466
1050	Pavement Seal Coat Master	14,678
1051	Pavement Seal Coat Phase I	7,146
1052	Pavement Seal Coat Phase II	3,383
1053	Pavement Seal Coat Phase IX	11,851
1054-0	Pavement Seal Coat Phase V	9,407
1054-01	Pavement Seal Coat Phase V Alley	1,298
1055	Pavement Seal Coat Phase VI	11,929
1056	Pavement Seal Coat Phase VII	12,478
1057	Pavement Seal Coat Phase VIII	12,002
1058	Pavement Seal Coat Phase X	5,669
1110	VGC Riding Mower - Replace	9,672
1013	Creek Pump Creek - Refurbish	19,760
1041	Pavement Overlay Master	197,485
1043	Pavement Overlay Phase II	45,512
1045-0	Pavement Overlay Phase V	126,565
1046	Pavement Overlay Phase VI	160,506
1047	Pavement Overlay Phase VII	167,885
Total for 2029		\$889,777

#### Replacement Year 2030 **GVW** Concrete - Grinding 4,419 1103-0 1112b GVW Tree/Shrub (2027) - Refurbishment 4,290 1112 GVW Tree/Shrub/Other - Common Area Refurbishment 14,300 1113b Non GVW Tree/Shrub (2027) - Refurbishment 4,290 1103-01 Non-GVW Concrete - Grinding 4,419 7,150 1086-01 Non-GVW Tree Care 1109 Pavement - Crack Sealing & Repair 22,901

Description		Expenditures
Replacement	Year 2030 continued	
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	5 <i>,</i> 892
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	4,290
1028	Irrigation Controllers 20% Replace	20,982
1026	Gazebo Roof - Replace	4,549
Total for 2030		\$97,483
Replacement	Year 2031	
1103-0	GVW Concrete - Grinding	4,573
1112b	GVW Tree/Shrub (2027) - Refurbishment	4,440
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	14,801
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	4,440
1103-01	Non-GVW Concrete - Grinding	4,573
1086-01	Non-GVW Tree Care	7,400
1109	Pavement - Crack Sealing & Repair	23,703
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	6,098
1029	Irrrigation Backflow Devices - 11% replace	1,320
1081	Streetside Signs - Replace	71,160
Total for 2031		\$142,510
Replacement	Year 2032	
1103-0	GVW Concrete - Grinding	4,734
1112b	GVW Tree/Shrub (2027) - Refurbishment	4,596
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	15,319
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	4,596
1103-01	Non-GVW Concrete - Grinding	4,734
1086-01	Non-GVW Tree Care	7,659
1109	Pavement - Crack Sealing & Repair	24,532
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	6,311
1008	Clock Tower Paint / Repair Contingency	1,641
1010	Concrete Surfaces - Ph. X - 3% Repair	2,714
1027-0	GVW Concrete - Replacement	4,689
Total for 2032	2	\$81,525
Replacement	Year 2033	

Description		Expenditures
Replacement	Year 2033 continued	
1112b	GVW Tree/Shrub (2027) - Refurbishment	4,757
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	15,855
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	4,757
1103-01	Non-GVW Concrete - Grinding	4,899
1086-01	Non-GVW Tree Care	7,928
1109	Pavement - Crack Sealing & Repair	25,391
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	6,532
1029	Irrrigation Backflow Devices - 11% replace	1,414
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	4,757
1028	Irrigation Controllers 20% Replace	23,263
1005	Bridges Paint Wood Surfaces	1,209
1027-01	Non-GVW Concrete - Replacement	39,638
1095	UG Sprinkler Pipe Master Areas 4.8%	140,331
1025	Gazebo - Paint	3,243
1097	Well Clock Tower - Repair Contingency	3,675
1083-3	Sump Pump 1 HP - (765 Heron) - Replace	10,239
1082-1	Sump Pump 2 HP - High Water / Ground Water	21,080
1082-2	Sump Pump 3/4 HP - Pond Fill - Replace	9,485
1024	Gazebo - Major Renovation	19,098
Total for 2033		\$352,448
Replacement	Voor 2024	
1103-0	GVW Concrete - Grinding	5,071
1105 U 1112b	GVW Tree/Shrub (2027) - Refurbishment	4,923
11125	GVW Tree/Shrub/Other - Common Area Refurbishment	16,410
1112 1113b	Non GVW Tree/Shrub (2027) - Refurbishment	4,923
1103-01	Non-GVW Concrete - Grinding	5,071
1086-01	Non-GVW Tree Care	8,205
1109	Pavement - Crack Sealing & Repair	26,279
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	6,761
Total for 2034		\$77 <i>,</i> 643
Replacement	Year 2035	
1103-0	GVW Concrete - Grinding	5.248

1103-0	GVW Concrete - Grinding	5 <i>,</i> 248
1112b	GVW Tree/Shrub (2027) - Refurbishment	5 <i>,</i> 095

Description		Expenditures
Replacement	Year 2035 continued	
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	16,984
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	5,095
1103-01	Non-GVW Concrete - Grinding	5,248
1086-01	Non-GVW Tree Care	8,492
1109	Pavement - Crack Sealing & Repair	27,199
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	6,998
1029	Irrrigation Backflow Devices - 11% replace	1,515
1008	Clock Tower Paint / Repair Contingency	1,819
1009	Concete - Curb Ph. IX - 10% Repair	1,674
1012	Creek Pump House Shed Repair Contingency	5,490
1050	Pavement Seal Coat Master	18,043
1051	Pavement Seal Coat Phase I	8,784
1052	Pavement Seal Coat Phase II	4,158
1053	Pavement Seal Coat Phase IX	14,568
1054-0	Pavement Seal Coat Phase V	11,563
1054-01	Pavement Seal Coat Phase V Alley	1,596
1055	Pavement Seal Coat Phase VI	14,664
1056	Pavement Seal Coat Phase VII	15,339
1057	Pavement Seal Coat Phase VIII	14,753
1058	Pavement Seal Coat Phase X	6,969
1099	Well Pump - Replace	23,226
1033c	Mailbox Clusters (Village 10) - Replace	8,458
1049	Pavement Overlay Phase X	93,767
Total for 2035		\$326,748

#### Replacement Year 2036

GVW Concrete - Grinding	5,432
GVW Tree/Shrub (2027) - Refurbishment	5,274
GVW Tree/Shrub/Other - Common Area Refurbishment	17,579
Non GVW Tree/Shrub (2027) - Refurbishment	5,274
Non-GVW Concrete - Grinding	5,432
Non-GVW Tree Care	8,789
Pavement - Crack Sealing & Repair	28,151
Walking Paths Bark Dust & Chip Rock Refurbish/Replace	7,242
Common Sump Pump Components (765 Heron) - Repair/Replace	5,274
Irrigation Controllers 20% Replace	25,792
	GVW Tree/Shrub (2027) - Refurbishment GVW Tree/Shrub/Other - Common Area Refurbishment Non GVW Tree/Shrub (2027) - Refurbishment Non-GVW Concrete - Grinding Non-GVW Tree Care Pavement - Crack Sealing & Repair Walking Paths Bark Dust & Chip Rock Refurbish/Replace Common Sump Pump Components (765 Heron) - Repair/Replace

Description		Expenditures
Replacement	Year 2036 continued	
1110	VGC Riding Mower - Replace	12,305
1040	Mailbox Wooden Structures (10 box) - Replace	16,944
Total for 203	6	\$143,488
Replacement	Year 2037	
1103-0	GVW Concrete - Grinding	5,622
1112b	GVW Tree/Shrub (2027) - Refurbishment	5,458
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	18,194
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	5,458
1103-01	Non-GVW Concrete - Grinding	5,622
1086-01	Non-GVW Tree Care	9,097
1109	Pavement - Crack Sealing & Repair	29,137
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	7,496
1029	Irrrigation Backflow Devices - 11% replace	1,623
1010	Concrete Surfaces - Ph. X - 3% Repair	3,224
1027-0	GVW Concrete - Replacement	5,569
1031	Lights Pole Phases I & II - Replace	23,019
Total for 203	7	\$119,519
Replacement	Year 2038	
1103-0	GVW Concrete - Grinding	5,819
1112b	GVW Tree/Shrub (2027) - Refurbishment	5,649
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	18,831
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	5,649
1103-01	Non-GVW Concrete - Grinding	5,819
1086-01	Non-GVW Tree Care	9,415
1109	Pavement - Crack Sealing & Repair	30,156
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	7,758
1008	Clock Tower Paint / Repair Contingency	2,017
1005	Bridges Paint Wood Surfaces	1,435
1027-01	Non-GVW Concrete - Replacement	47,077
1095	UG Sprinkler Pipe Master Areas 4.8%	166,669
1040c	Mailbox Wooden Structures (Village 9) - Replace	2,723
Total for 2038		\$309,018

Description		Expenditures
Replacement	Year 2039	
1103-0	GVW Concrete - Grinding	6,022
1112b	GVW Tree/Shrub (2027) - Refurbishment	5,847
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	19,490
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	5,847
1103-01	Non-GVW Concrete - Grinding	6,022
1086-01	Non-GVW Tree Care	9,745
1109	Pavement - Crack Sealing & Repair	31,212
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	8,030
1029	Irrrigation Backflow Devices - 11% replace	1,739
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	5,847
1028	Irrigation Controllers 20% Replace	28,596
1025	Gazebo - Paint	3,987
1097	Well Clock Tower - Repair Contingency	4,518
Total for 2039	) )	\$136,902
Replacement		
1103-0	GVW Concrete - Grinding	6,233
1112b	GVW Tree/Shrub (2027) - Refurbishment	6,052
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	20,172
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	6,052
1103-01	Non-GVW Concrete - Grinding	6,233
1086-01	Non-GVW Tree Care	10,086
1109	Pavement - Crack Sealing & Repair	32,304
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	8,311
1009	Concete - Curb Ph. IX - 10% Repair	1,988
1108	Pond Small - Liner - Replace	87,308
Total for 2040	)	\$184,739
Replacement	Year 2041	
1103-0	GVW Concrete - Grinding	6,451
1112b	GVW Tree/Shrub (2027) - Refurbishment	6,263
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	20,878
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	6,263
1103-01	Non-GVW Concrete - Grinding	6,451
1086-01	Non-GVW Tree Care	10,439

Description	Expenditures	
Replacement	Year 2041 continued	
1109	Pavement - Crack Sealing & Repair	33,435
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	8,602
1029	Irrrigation Backflow Devices - 11% replace	1,862
1008	Clock Tower Paint / Repair Contingency	2,236
1012	Creek Pump House Shed Repair Contingency	6,748
1050	Pavement Seal Coat Master	22,179
1051	Pavement Seal Coat Phase I	10,798
1052	Pavement Seal Coat Phase II	5,111
1053	Pavement Seal Coat Phase IX	17,908
1054-0	Pavement Seal Coat Phase V	14,214
1054-01	Pavement Seal Coat Phase V Alley	1,962
1055	Pavement Seal Coat Phase VI	18,026
1056	Pavement Seal Coat Phase VII	18,855
1057	Pavement Seal Coat Phase VIII	18,136
1058	Pavement Seal Coat Phase X	8,567
1030	Lights Pole Fixtures Phases I & II - Replace	11,163
1044	Pavement Overlay Phase IX	240,941
1048	Pavement Overlay Phase VIII	244,009
Total for 204	1	\$741,499
Replacement	Year 2042	
1103-0	GVW Concrete - Grinding	6,677
1112b	GVW Tree/Shrub (2027) - Refurbishment	6,483
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	21,609
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	6,483
1103-01	Non-GVW Concrete - Grinding	6.677

Total for 2042		\$382,140
1033d	Mailbox Clusters (Village 9) - Replace	15,622
1062	Pond Large - De-muck & Maintenace	162,084
1114	Maintenance & Storage (Trail 1) Shed - Replace	53,562
1027-0	GVW Concrete - Replacement	6,615
1010	Concrete Surfaces - Ph. X - 3% Repair	3,829
1028	Irrigation Controllers 20% Replace	31,705
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	6,483
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	8,903
1109	Pavement - Crack Sealing & Repair	34,605
1086-01	Non-GVW Tree Care	10,804
1103-01	Non-GVW Concrete - Grinding	6,677
11120	Non GVW hee/shidb (2027) - Refurbishinent	0,403

Replacement Year 2043           1103-0         GVW Concrete - Grinding         6,911           1112b         GVW Tree/Shrub (2027) - Refurbishment         6,710           1112         GVW Tree/Shrub (2027) - Refurbishment         2,365           1113b         Non GVW Tree/Shrub (2027) - Refurbishment         2,365           1113b         Non GVW Tree/Shrub (2027) - Refurbishment         2,361           103-01         Non-GVW Concrete - Grinding         6,911           1036-01         Non-GVW Concrete - Grinding         6,911           1036-01         Non-GVW Tree Care         11,183           1109         Pavement - Crack Sealing & Repair         35,816           1029         Irrrigation Backflow Devices - 11% replace         9,921           1005         Bridges Paint Wood Surfaces         1,705           1007-01         Non-GVW Concrete - Replacement         55,913           1005         UG Sprinkler Pipe Master Areas 4.8%         197,950           110         VGC Riding Mower - Replace         16,168           Total for 2043         \$395,207           Replacement Year 2044           1103-0         GVW Tree/Shrub (2027) - Refurbishment         6,944           1112         GVW Tree/Shrub (2027) - Refurbishment	Description		Expenditures
1112b       GVW Tree/Shrub/2027) - Refurbishment       6,710         1112       GVW Tree/Shrub/Other - Common Area Refurbishment       22,365         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,911         108-01       Non-GVW Tree Care       11,183         109       Pavement - Crack Sealing & Repair       35,816         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,214         1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043       \$395,207         Replacement Year 2044         1112       GVW Tree/Shrub (2027) - Refurbishment       6,944         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       23,148         1112b       GVW Tree/Shrub (2027) - Refurbishment       23,148         1112b       GVW Tree/Shrub (2027) - Refurbishment       23,148         1103-01       Non-GVW Concrete - Grinding	Replacement	Year 2043	
1112       GVW Tree/Shrub/Other - Common Area Refurbishment       22,365         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,710         1103-01       Non-GVW Concrete - Grinding       6,911         1086-01       Non-GVW Tree Care       11,183         1109       Pavement - Crack Sealing & Repair       35,816         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,214         1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043       \$395,207         Replacement Year 2044         1112       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112       GVW Tree/Shrub (2027) - Refurbishment       2,178         1086-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree Care       11,574	1103-0	GVW Concrete - Grinding	6,911
1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,710         1103-01       Non-GVW Concrete - Grinding       6,911         1086-01       Non-GVW Tree Care       11,183         1109       Pavement - Crack Sealing & Repair       35,816         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,214         1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       16,168         Total for 2043       Total for 2043       \$395,207         Replacement Vear 2044         1112       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112b       GVW Tree/Shrub (2027) - Refurbishment       23,148         1113b       Non GVW Tree Care       11,574         1103-01       Non-GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       23,148         1113b       Non GVW Tree Care       37,070         109       Pavement - Crack Sealing & Repair       37,070	1112b	GVW Tree/Shrub (2027) - Refurbishment	6,710
1103-01       Non-GVW Concrete - Grinding       6,911         1086-01       Non-GVW Tree Care       11,183         1109       Pavement - Crack Sealing & Repair       35,816         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,214         1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       16,6168         Total for 2043       \$395,207         Replacement Year 2044         1103-0       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1113b       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree Care       11,574         1109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1	1112	GVW Tree/Shrub/Other - Common Area Refurbishment	22,365
1086-01       Non-GVW Tree Care       11,183         1109       Pavement - Crack Sealing & Repair       35,816         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,214         1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043       \$395,207         Replacement Year 2044       6,944         1112       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Concrete - Grinding & 7,153       10,574         1009       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2	1113b	Non GVW Tree/Shrub (2027) - Refurbishment	6,710
1109       Pavement - Crack Sealing & Repair       35,816         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,214         1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1007-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       16,168         1033e       Mailbox Clusters (Village 8) - Replace       16,168         103-0       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112       GVW Tree/Shrub (2027) - Refurbishment       23,148         1113b       Non-GVW Concrete - Grinding       7,153         1120       GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-0       GVW Concrete - Grinding       7,153         1112b       Non-GVW Concrete - Grinding       7,153         1103-0       Non-GVW Tree Care       11,574         1103-0       Non-GVW Tree Care       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish	1103-01	Non-GVW Concrete - Grinding	6,911
1096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,2141029Irrrigation Backflow Devices - 11% replace1,9951005Bridges Paint Wood Surfaces1,7051027-01Non-GVW Concrete - Replacement55,9131095UG Sprinkler Pipe Master Areas 4.8%197,9501110VGC Riding Mower - Replace15,6561033eMailbox Clusters (Village 8) - Replace16,168Total for 2043\$395,207Replacement Year 20441102GVW Concrete - Grinding7,1531112bGVW Tree/Shrub (2027) - Refurbishment6,9441113bNon GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Concrete - Grinding7,1531086-01Non-GVW Tree Care11,574109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044\$103-0GWW Concrete - Grinding1103-0GVW Concrete - Grinding1112GVW Tree/Shrub (2027) - Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044\$1103-0GVW Concrete - Grinding1112bGVW Tree/Shrub (2027) - Refurbishment7,1871112bG	1086-01	Non-GVW Tree Care	11,183
1029       Irrrigation Backflow Devices - 11% replace       1,995         1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043       \$395,207         Replacement Year 2044         1103-0       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-0       Kalking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106         Total for 2044         Replacement Year 2045         1103-0       GVW Concrete - Grinding       7,403         1103-0       GVW Concrete - Grinding       7,403	1109	Pavement - Crack Sealing & Repair	35,816
1005       Bridges Paint Wood Surfaces       1,705         1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043       \$395,207         Replacement Year 2044         1103-0       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Tree Care       11,574         1109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106         Total for 2044         Replacement Year 2045         1103-0       GVW Concrete - Grinding       7,403	1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	9,214
1027-01       Non-GVW Concrete - Replacement       55,913         1095       UG Sprinkler Pipe Master Areas 4.8%       197,950         1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043       \$395,207         Replacement Year 2044       \$395,207         Replacement Year 2044       7,153         1112b       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Tree Care       11,574         109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106         Total for 2044       \$145,108         Replacement Year 2045       \$	1029	Irrrigation Backflow Devices - 11% replace	1,995
1095UG Sprinkler Pipe Master Areas 4.8%197,9501110VGC Riding Mower - Replace15,6561033eMailbox Clusters (Village 8) - Replace16,168Total for 2043\$395,207Replacement Year 20441103-0GVW Concrete - Grinding7,1531112bGVW Tree/Shrub (2027) - Refurbishment6,9441113bNon GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Tree Care11,5741086-01Non-GVW Tree Care11,574109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Free/Strub (2027) - Refurbishment7,4031112bGVW Concrete - Grinding7,4031112bGVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub (2027) - Refurbishment7,1871112bNon GVW Tree/Shrub (2027) - Refurbishment7,1871112bNon GVW Tree/Shrub (2027) - Refurbishment7,1871112bNon GVW Tree/Shrub (2027) - Refurbishment7,1871	1005	Bridges Paint Wood Surfaces	1,705
1110       VGC Riding Mower - Replace       15,656         1033e       Mailbox Clusters (Village 8) - Replace       16,168         Total for 2043         Replacement Year 2044         1103-0       GVW Concrete - Grinding       7,153         1112       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112       GVW Tree/Shrub/Other - Common Area Refurbishment       23,148         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree Care       11,574         1109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106         Total for 2044         Replacement Year 2045         1103-0       GVW Concrete - Grinding       7,403         1112b       GVW Tree/Shrub (2027) - Refurbishment       7,187         1103-0       GVW Concrete - Grinding       7,403 <t< td=""><td>1027-01</td><td>Non-GVW Concrete - Replacement</td><td>55,913</td></t<>	1027-01	Non-GVW Concrete - Replacement	55,913
1033eMailbox Clusters (Village 8) - Replace16,168Total for 2043\$\$395,207Replacement Year 20441103-0GVW Concrete - Grinding7,1531112bGVW Tree/Shrub (2027) - Refurbishment6,9441112GVW Tree/Shrub/Other - Common Area Refurbishment23,1481113bNon GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Concrete - Grinding7,1531086-01Non-GVW Tree Care11,5741109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Replacement Year 2045Replacement Year 2045\$\$145,108Replacement Year 20457,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1095	UG Sprinkler Pipe Master Areas 4.8%	197,950
Total for 2043         \$395,207           Replacement Year 2044         1103-0         GVW Concrete - Grinding         7,153           1112b         GVW Tree/Shrub (2027) - Refurbishment         6,944           1112         GVW Tree/Shrub/Other - Common Area Refurbishment         23,148           1113b         Non GVW Tree/Shrub/Other - Common Area Refurbishment         23,148           1103-01         Non-GVW Concrete - Grinding         7,153           1086-01         Non-GVW Tree Care         11,574           1109         Pavement - Crack Sealing & Repair         37,070           1096         Walking Paths Bark Dust & Chip Rock Refurbish/Replace         9,537           1008         Clock Tower Paint / Repair Contingency         2,479           1013         Creek Pump Creek - Refurbish         33,106           Total for 2044         \$145,108           Replacement Year 2045         \$145,108           Replacement Year 2045         7,403           1112b         GVW Tree/Shrub (2027) - Refurbishment         7,187           1112         GVW Tree/Shrub (2027) - Refurbishment         7,187           1112b         GVW Tree/Shrub (2027) - Refurbishment         7,187           1113b         Non GVW Tree/Shrub (2027) - Refurbishment         7,187	1110	VGC Riding Mower - Replace	15,656
Replacement Year 20441103-0GVW Concrete - Grinding7,1531112bGVW Tree/Shrub (2027) - Refurbishment6,9441112GVW Tree/Shrub/Other - Common Area Refurbishment23,1481113bNon GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Concrete - Grinding7,1531086-01Non-GVW Tree Care11,5741109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub (2027) - Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1033e	16,168	
1103-0       GVW Concrete - Grinding       7,153         1112b       GVW Tree/Shrub (2027) - Refurbishment       6,944         1112       GVW Tree/Shrub/Other - Common Area Refurbishment       23,148         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree Care       11,574         1109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106         Total for 2044         Replacement Year 2045         1103-0       GVW Concrete - Grinding       7,403         1112b       GVW Tree/Shrub (2027) - Refurbishment       7,187         1112b       GVW Tree/Shrub (2027) - Refurbishment       23,958         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       7,187         1112b       Non GVW Tree/Shrub (2027) - Refurbishment       7,187         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       7,187	Total for 204	3	\$395,207
1112bGVW Tree/Shrub (2027) - Refurbishment6,9441112GVW Tree/Shrub/Other - Common Area Refurbishment23,1481113bNon GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Concrete - Grinding7,1531086-01Non-GVW Tree Care11,5741109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044FReplacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub (2027) - Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	Replacement	Year 2044	
1112GVW Tree/Shrub/Other - Common Area Refurbishment23,1481113bNon GVW Tree/Shrub (2027) - Refurbishment6,9441103-01Non-GVW Concrete - Grinding7,1531086-01Non-GVW Tree Care11,5741109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Feplacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1103-0	GVW Concrete - Grinding	7,153
1113b       Non GVW Tree/Shrub (2027) - Refurbishment       6,944         1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree Care       11,574         1109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106 <b>Total for 2044 Replacement Year 2045</b> 1103-0       GVW Concrete - Grinding       7,403         1112b       GVW Tree/Shrub (2027) - Refurbishment       7,187         1112       GVW Tree/Shrub/Other - Common Area Refurbishment       23,958         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       7,187	1112b	GVW Tree/Shrub (2027) - Refurbishment	6,944
1103-01       Non-GVW Concrete - Grinding       7,153         1086-01       Non-GVW Tree Care       11,574         1109       Pavement - Crack Sealing & Repair       37,070         1096       Walking Paths Bark Dust & Chip Rock Refurbish/Replace       9,537         1008       Clock Tower Paint / Repair Contingency       2,479         1013       Creek Pump Creek - Refurbish       33,106 <b>Total for 2044 Replacement Year 2045</b> 1103-0       GVW Concrete - Grinding       7,403         1112b       GVW Tree/Shrub (2027) - Refurbishment       7,187         1112       GVW Tree/Shrub/Other - Common Area Refurbishment       23,958         1113b       Non GVW Tree/Shrub (2027) - Refurbishment       7,187	1112	GVW Tree/Shrub/Other - Common Area Refurbishment	23,148
1086-01Non-GVW Tree Care11,5741109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1113b	Non GVW Tree/Shrub (2027) - Refurbishment	6,944
1109Pavement - Crack Sealing & Repair37,0701096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106 <b>Total for 2044Replacement Year 2045</b> 1103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1103-01	Non-GVW Concrete - Grinding	7,153
1096Walking Paths Bark Dust & Chip Rock Refurbish/Replace9,5371008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1086-01	Non-GVW Tree Care	11,574
1008Clock Tower Paint / Repair Contingency2,4791013Creek Pump Creek - Refurbish33,106Total for 2044Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1109	Pavement - Crack Sealing & Repair	37,070
1013Creek Pump Creek - Refurbish33,106Total for 2044\$145,108Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	9,537
Total for 2044\$145,108Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1008	Clock Tower Paint / Repair Contingency	2,479
Replacement Year 20451103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	1013	Creek Pump Creek - Refurbish	33,106
1103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	Total for 204	4	\$145,108
1103-0GVW Concrete - Grinding7,4031112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	Replacement	Year 2045	
1112bGVW Tree/Shrub (2027) - Refurbishment7,1871112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187	•		7.403
1112GVW Tree/Shrub/Other - Common Area Refurbishment23,9581113bNon GVW Tree/Shrub (2027) - Refurbishment7,187		C C	
1113bNon GVW Tree/Shrub (2027) - Refurbishment7,187			
			•

Description		Expenditures
Replacement	Year 2045 continued	
1086-01	Non-GVW Tree Care	11,979
1109	Pavement - Crack Sealing & Repair	38,367
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	9,871
1029	Irrrigation Backflow Devices - 11% replace	2,137
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	7,187
1028	Irrigation Controllers 20% Replace	35,152
1009	Concete - Curb Ph. IX - 10% Repair	2,361
1025	Gazebo - Paint	4,901
1097	Well Clock Tower - Repair Contingency	5,554
1083-3	Sump Pump 1 HP - (765 Heron) - Replace	15,472
1082-1	Sump Pump 2 HP - High Water / Ground Water	31,853
1082-2	Sump Pump 3/4 HP - Pond Fill - Replace	14,332
1037	Mailbox Structures - Ph. V - Replace	6,864
Total for 204	5	\$239,169
Doulocomout	Verat 2046	
Replacement 1103-0		7 660
1103-0 1112b	GVW Concrete - Grinding	7,662
11120	GVW Tree/Shrub (2027) - Refurbishment GVW Tree/Shrub/Other - Common Area Refurbishment	7,439 24,797
1112 1113b	Non GVW Tree/Shrub (2027) - Refurbishment	7,439
1103-01	Non-GVW Concrete - Grinding	7,439
103-01	Non-GVW Tree Care	12,398
1080-01	Pavement - Crack Sealing & Repair	39,710
109	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	10,216
1030	Mailbox Clusters (10 box) - Replace	72,448
Total for 2046	5	\$189,772
Replacement	Year 2047	
1103-0	GVW Concrete - Grinding	7,930
1112b	GVW Tree/Shrub (2027) - Refurbishment	7,699
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	25,665
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	7,699
1103-01	Non-GVW Concrete - Grinding	7,930
1086-01	Non-GVW Tree Care	12,832
1109	Pavement - Crack Sealing & Repair	41,100

Description		Expenditures
Replacement	Year 2047 continued	
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	10,574
1029	Irrrigation Backflow Devices - 11% replace	2,289
1008	Clock Tower Paint / Repair Contingency	2,749
1010	Concrete Surfaces - Ph. X - 3% Repair	4,547
1027-0	GVW Concrete - Replacement	7,856
1012	Creek Pump House Shed Repair Contingency	8,295
1050	Pavement Seal Coat Master	27,264
1051	Pavement Seal Coat Phase I	13,274
1052	Pavement Seal Coat Phase II	6,283
1053	Pavement Seal Coat Phase IX	22,013
1054-0	Pavement Seal Coat Phase V	17,473
1054-01	Pavement Seal Coat Phase V Alley	2,411
1055	Pavement Seal Coat Phase VI	22,159
1056	Pavement Seal Coat Phase VII	23,178
1057	Pavement Seal Coat Phase VIII	22,294
1058	Pavement Seal Coat Phase X	10,531
1099	Well Pump - Replace	35,097
1084	Sump Pump Backup Generator - Replace	29,379
1035	Mailbox Structures - Ph. I - Replace	7,353
1036	Mailbox Structures - Ph. II - Replace	10,707
Total for 2047	7	\$396,582

## Replacement Year 2048

1103-0	GVW Concrete - Grinding	8,208
1112b	GVW Tree/Shrub (2027) - Refurbishment	7,969
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	26,563
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	7,969
1103-01	Non-GVW Concrete - Grinding	8,208
1086-01	Non-GVW Tree Care	13,281
1109	Pavement - Crack Sealing & Repair	42,538
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	10,944
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	7,969
1028	Irrigation Controllers 20% Replace	38,974
1005	Bridges Paint Wood Surfaces	2,025
1027-01	Non-GVW Concrete - Replacement	66,407
1095	UG Sprinkler Pipe Master Areas 4.8%	235,103

Description		Expenditures
Replacement	Year 2048 continued	
1024	Gazebo - Major Renovation	31,995
1038	Mailbox Structures - Ph. VI - Replace	7,682
1001	Benches - Repair/Replacement	9,053
Total for 204	8	\$524,887
Replacement	Year 2049	
1103-0	GVW Concrete - Grinding	8,495
1112b	GVW Tree/Shrub (2027) - Refurbishment	8,248
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	27,493
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	8,248
1103-01	Non-GVW Concrete - Grinding	8,495
1086-01	Non-GVW Tree Care	13,746
1109	Pavement - Crack Sealing & Repair	44,027
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	11,327
1029	Irrrigation Backflow Devices - 11% replace	2,452
Total for 204	9	\$132,531
Replacement	Year 2050	
1103-0	GVW Concrete - Grinding	8,793
1112b	GVW Tree/Shrub (2027) - Refurbishment	8,536
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	28,455
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	8,536
1103-01	Non-GVW Concrete - Grinding	8,793
1086-01	Non-GVW Tree Care	14,227
1109	Pavement - Crack Sealing & Repair	45,568
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	11,723
1008	Clock Tower Paint / Repair Contingency	3,047
1009	Concete - Curb Ph. IX - 10% Repair	2,804
1110	VGC Riding Mower - Replace	19,918
Total for 205	0	\$160,401
Replacement	Year 2051	
1103-0	GVW Concrete - Grinding	9,100
1112b	GVW Tree/Shrub (2027) - Refurbishment	8,835
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	29,451

Description		Expenditures
Replacement	Year 2051 continued	
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	8,835
1103-01	Non-GVW Concrete - Grinding	9,100
1086-01	Non-GVW Tree Care	14,725
1109	Pavement - Crack Sealing & Repair	47,163
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	12,134
1029	Irrrigation Backflow Devices - 11% replace	2,627
1083-4	Common Sump Pump Components (765 Heron) - Repair/Replace	8,835
1028	Irrigation Controllers 20% Replace	43,211
1025	Gazebo - Paint	6,024
1097	Well Clock Tower - Repair Contingency	6,827
1040	Mailbox Wooden Structures (10 box) - Replace	28,387
1039	Mailbox Structures - Ph. VII - Replace	12,775
1002	Bridge Pond - Replace	19,709
1004	Bridges 1, 2, 3 - Replace	81,658
1015	Entry Sign & Monument - Refurbish	5,119
Total for 205	L	\$354,517
Replacement	Year 2052	
1103-0		9,419
1112b	GVW Tree/Shrub (2027) - Refurbishment	9,144
1112	GVW Tree/Shrub/Other - Common Area Refurbishment	30,482
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	9,144
1103-01	Non-GVW Concrete - Grinding	9,419
1086-01	Non-GVW Tree Care	15,241
1109	Pavement - Crack Sealing & Repair	48,814
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Replace	12,558
1010	Concrete Surfaces - Ph. X - 3% Repair	5,401
1027-0	GVW Concrete - Replacement	9,331
Total for 2052	2	\$158,952

	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
Beginning Balance	422,061	310,497	436,770	591,637	706,971	805,261	838,259	225,853	413,725	564,620
Annual Reserve Account Contribution	225,000	232,875	241,026	249,462	258,193	267,229	276,582	283,912	291,436	299,159
Interest Earned	1,083	1,523	2,064	2,466	2,809	2,924	788	1,443	1,969	2,738
Expenditures	337,647	108,125	88,223	136,593	162,711	237,155	889,777	97,483	142,510	81,525
Fully Funded Balance	1,030,875	1,153,632	1,308,234	1,425,636	1,513,907	1,516,712	850,382	987,806	1,090,737	1,267,945
Percent Funded	30%	38%	45%	50%	53%	55%	27%	42%	52%	62%
Ending Reserve Account Balance	310,497	436,770	591,637	706,971	805,261	838,259	225,853	413,725	564,620	784,992
ID Description										
Master										
1001 Benches - Repair/Replacement										
1002 Bridge Pond - Replace				8,340						
1004 Bridges 1, 2, 3 - Replace				34,553						
1005 Bridges Paint Wood Surfaces	857					1,018				
1008 Clock Tower Paint / Repair Contingency	1,204			1,335			1,480			1,641
1012 Creek Pump House Shed Repair Contingency	3,633						4,466			
1013 Creek Pump Creek - Refurbish							19,760			
1015 Entry Sign & Monument - Refurbish				2,166						
1018 Fence (wood) - Paint/Stain	Unfunded									
1019 Fences Along Lions Park - Replace	Unfunded									
1024 Gazebo - Major Renovation										
1025 Gazebo - Paint					2,638					
1026 Gazebo Roof - Replace								4,549		
1027-0 GVW Concrete - Replacement					3,948					4,689
1027-01 Non-GVW Concrete - Replacement						33,374				
1027-01b Non-GVW Concrete (2022) - Replacemer	nt 18,057	18,689	19,343	20,020	20,721	21,446				
1028 Irrigation Controllers 20% Replace		17,069			18,925			20,982		
1029 Irrrigation Backflow Devices - 11% replace	1,003		1,074		1,151		1,232		1,320	
1030 Lights Pole Fixtures Phases I & II - Replace										
1031 Lights Pole Phases I & II - Replace										
1033 Mailbox Clusters (10 box) - Replace										
1033c Mailbox Clusters (Village 10) - Replace										
1033d Mailbox Clusters (Village 9) - Replace										

	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
ID Description										
Master continued										
1033e Mailbox Clusters (Village 8) - Replace										
1040 Mailbox Wooden Structures (10 box) - Replace										
1040c Mailbox Wooden Structures (Village 9) - Repl	1,625									
1041 Pavement Overlay Master							197,485			
1050 Pavement Seal Coat Master							14,678			
1062 Pond Large - De-muck & Maintenace										
1065 Slope - Maintenance U	nfunded									
1080 Storm Water System Drains & Catch Basins MU	nfunded									
1081 Streetside Signs - Replace									71,160	
1082-1 Sump Pump 2 HP - High Water / Ground W										
1082-2 Sump Pump 3/4 HP - Pond Fill - Replace										
1083-3 Sump Pump 1 HP - (765 Heron) - Replace										
1083-4 Common Sump Pump Components (765 He		3,490			3,869			4,290		
1084 Sump Pump Backup Generator - Replace					14,765					
1086-0 GVW Tree Care	5,620	5,817	6,020	6,231	6,449					
1086-01 Non-GVW Tree Care	5,620	5,817	6,020	6,231	6,449	6,675	6,908	7,150	7,400	7,659
1095 UG Sprinkler Pipe Master Areas 4.8%	99,483					118,155				
1096 Walking Paths Bark Dust & Chip Rock Refurbis	4,631	4,793	4,961	5,134	5,314	5,500	5 <i>,</i> 693	5,892	6,098	6,311
1097 Well Clock Tower - Repair Contingency					2,990					
1099 Well Pump - Replace	15,371									
1102 Fence & Gate (lions park) - Replace					5,450					
1103-0 GVW Concrete - Grinding	3,473	3,595	3,721	3,851	3,986	4,125	4,269	4,419	4,573	4,734
1103-01 Non-GVW Concrete - Grinding	3,473	3,595	3,721	3,851	3,986	4,125	4,269	4,419	4,573	4,734
1108 Pond Small - Liner - Replace										
1109 Pavement - Crack Sealing & Repair	18,000	18,630	19,282	19,957	20,655	21,378	22,127	22,901	23,703	24,532
1110 VGC Riding Mower - Replace							9,672			
1112 GVW Tree/Shrub/Other - Common Area Refu	11,240	11,633	12,041	12,462	12,898	13,350	13,817	14,300	14,801	15,319
1112b GVW Tree/Shrub (2027) - Refurbishment					3,869	4,005	4,145	4,290	4,440	4,596
1113 Non GVW Tree/Shrub/Other - Common Area	11,240	11,633	12,041	12,462	12,898					
1113b Non GVW Tree/Shrub (2027) - Refurbishment					3,869	4,005	4,145	4,290	4,440	4,596
1114 Maintenance & Storage (Trail 1) Shed - Replace										

1114 Maintenance & Storage (Trail 1) Shed - Replace

	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
ID Description										
Master continued										
1245 Shed - Replace										
Master Total:	204,530	104,761	88,223	136,593	154,831	237,155	314,146	97,483	142,510	78,810
Phase I										
1035 Mailbox Structures - Ph. I - Replace	3,220									
1042 Pavement Overlay Phase I	0)0									
1051 Pavement Seal Coat Phase I							7,146			
1105 Pavement Replacement Phase I	105,960									
Phase I Total:	109,180						7,146			
Phase II										
1036 Mailbox Structures - Ph. II - Replace	4,689									
1043 Pavement Overlay Phase II							45,512			
1052 Pavement Seal Coat Phase II							3,383			
Phase II Total:	4,689						48,894			
Phase V										
1037 Mailbox Structures - Ph. V - Replace										
1045-0 Pavement Overlay Phase V							126,565			
1045-01 Pavement Overlay Phase V Alley										
1054-0 Pavement Seal Coat Phase V							9,407			
1054-01 Pavement Seal Coat Phase V Alley							1,298			
1111 Pavement Replacement Phase V Alley	19,248									
Phase V Total:	19,248						137,270			
Phase VI										
1038 Mailbox Structures - Ph. VI - Replace		3,364								
1046 Pavement Overlay Phase VI							160,506			
1055 Pavement Seal Coat Phase VI							11,929			
Phase VI Total:		3,364					172,435			

	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
ID Description										
Phase VII										
1039 Mailbox Structures - Ph. VII - Replace					5,595					
1047 Pavement Overlay Phase VII							167,885			
1056 Pavement Seal Coat Phase VII							12,478			
Phase VII Total:					5,595		180,363			
Phase VIII										
1048 Pavement Overlay Phase VIII										
1057 Pavement Seal Coat Phase VIII							12,002			
Phase VIII Total:							12,002			
Phase IX										
1009 Concete - Curb Ph. IX - 10% Repair										
1044 Pavement Overlay Phase IX										
1053 Pavement Seal Coat Phase IX							11,851			
Phase IX Total:							11,851			
Phase X										
1010 Concrete Surfaces - Ph. X - 3% Repair					2,285					2,714
1017 Fence - Metal/Brick - Ph. X - Replace	Unfunded									
1020 Gate Entry Access - Ph. X - Replace	Unfunded									
1021 Gate Operators - Ph. X - Replace	Unfunded									
1022 Gates - Ph. X - Refurbish	Unfunded									
1023 Gates - Ph. X - Replace	Unfunded									
1049 Pavement Overlay Phase X										
1058 Pavement Seal Coat Phase X							5,669			
1064 Sign - Entry - Ph. X - Replace	Unfunded									
Phase X Total:					2,285		5,669			2,714
Year Total:	337,647	108,125	88,223	136,593	162,711	237,155	889,777	97,483	142,510	81,525

	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042
Beginning Balance	784,992	742,219	983,229	983,489	1,176,256	1,402,583	1,448,607	1,676,817	1,867,376	1,509,700
Annual Reserve Account Contribution	307,086	315,224	323,578	332,152	340,954	349,990	359,264	368,785	378,558	388,589
Interest Earned	2,589	3,429	3,430	4,103	4,892	5,052	5,848	6,513	5,266	5,307
Expenditures	352,448	77,643	326,748	143,488	119,519	309,018	136,902	184,739	741,499	382,140
Fully Funded Balance	1,178,769	1,378,988	1,336,796	1,491,472	1,685,342	1,699,156	1,901,206	2,070,766	1,679,304	1,656,701
Percent Funded	63%	71%	74%	79%	83%	85%	88%	90%	90%	92%
Ending Reserve Account Balance	742,219	983,229	983,489	1,176,256	1,402,583	1,448,607	1,676,817	1,867,376	1,509,700	1,521,456
ID Description										
Master										
1001 Benches - Repair/Replacement										
1002 Bridge Pond - Replace										
1004 Bridges 1, 2, 3 - Replace										
1005 Bridges Paint Wood Surfaces	1,209					1,435				
1008 Clock Tower Paint / Repair Contingency			1,819			2,017			2,236	
1012 Creek Pump House Shed Repair Contingency			5,490						6,748	
1013 Creek Pump Creek - Refurbish										
1015 Entry Sign & Monument - Refurbish										
1018 Fence (wood) - Paint/Stain	Unfunded									
1019 Fences Along Lions Park - Replace	Unfunded									
1024 Gazebo - Major Renovation	19,098									
1025 Gazebo - Paint	3,243						3,987			
1026 Gazebo Roof - Replace										
1027-0 GVW Concrete - Replacement					5,569					6,615
1027-01 Non-GVW Concrete - Replacement	39,638					47,077				
1027-01b Non-GVW Concrete (2022) - Replacemen										
1028 Irrigation Controllers 20% Replace	23,263			25,792			28,596			31,705
1029 Irrrigation Backflow Devices - 11% replace	1,414		1,515		1,623		1,739		1,862	
1030 Lights Pole Fixtures Phases I & II - Replace									11,163	
1031 Lights Pole Phases I & II - Replace					23,019					
1033 Mailbox Clusters (10 box) - Replace			_							
1033c Mailbox Clusters (Village 10) - Replace			8,458							
1033d Mailbox Clusters (Village 9) - Replace										15,622

	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042
ID Description										
Master continued										
1033e Mailbox Clusters (Village 8) - Replace										
1040 Mailbox Wooden Structures (10 box) - Replace				16,944						
1040c Mailbox Wooden Structures (Village 9) - Repl						2,723				
1041 Pavement Overlay Master										
1050 Pavement Seal Coat Master			18,043						22,179	
1062 Pond Large - De-muck & Maintenace										162,084
•	Infunded									
1080 Storm Water System Drains & Catch Basins ML	Infunded									
1081 Streetside Signs - Replace										
1082-1 Sump Pump 2 HP - High Water / Ground W.	21,080									
1082-2 Sump Pump 3/4 HP - Pond Fill - Replace	9,485									
1083-3 Sump Pump 1 HP - (765 Heron) - Replace	10,239									
1083-4 Common Sump Pump Components (765 He	4,757			5,274			5,847			6,483
1084 Sump Pump Backup Generator - Replace										
1086-0 GVW Tree Care										
1086-01 Non-GVW Tree Care	7,928	8,205	8,492	8,789	9,097	9,415	9,745	10,086	10,439	10,804
1095 UG Sprinkler Pipe Master Areas 4.8%	140,331	6 764	6 9 9 9		7 406	166,669				0.000
1096 Walking Paths Bark Dust & Chip Rock Refurbis.	6,532	6,761	6,998	7,242	7,496	7,758	8,030	8,311	8,602	8,903
1097 Well Clock Tower - Repair Contingency	3,675						4,518			
1099 Well Pump - Replace			23,226							
1102 Fence & Gate (lions park) - Replace	4 000	F 074	5 3 4 9	F 422	F (22)	F 010	6 0 2 2	6 2 2 2	C 454	C C 77
1103-0 GVW Concrete - Grinding	4,899	5,071	5,248	5,432	5,622	5,819	6,022	6,233	6,451	6,677
1103-01 Non-GVW Concrete - Grinding	4,899	5,071	5,248	5,432	5,622	5,819	6,022	6,233	6,451	6,677
1108 Pond Small - Liner - Replace	25 201	26.270	27 100	20 1 5 1	20 127	20.450	21 212	87,308	22 425	24.005
1109 Pavement - Crack Sealing & Repair	25,391	26,279	27,199	28,151	29,137	30,156	31,212	32,304	33,435	34,605
1110 VGC Riding Mower - Replace	15.055	16 410	10.004	12,305	10 10 4	10.021	10.400	20 172	20.070	21.000
1112 GVW Tree/Shrub/Other - Common Area Refu 1112b GVW Tree/Shrub (2027) - Refurbishment	15,855 4,757	16,410	16,984	17,579	18,194	18,831	19,490	20,172 6,052	20,878	21,609
11120 GVW Tree/Shrub/Other - Common Area	4,/3/	4,923	5,095	5,274	5,458	5,649	5,847	0,052	6,263	6,483
1113b Non GVW Tree/Shrub (2027) - Refurbishment	4,757	4,923	5,095	5,274	5,458	5,649	5,847	6,052	6,263	6,483
11130 Non GVW free/shrub (2027) - Refurbishment 1114 Maintenance & Storage (Trail 1) Shed - Replace	4,757	4,923	5,095	5,274	5,458	5,049	5,047	0,052	0,203	
1114 Maintenance & Storage (Iraii 1) Shed - Replace										53,562

	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042
ID Description										
Master continued										
1245 Shed - Replace										
Master Total:	352,448	77,643	138,912	143,488	116,296	309,018	136,902	182,751	142,973	378,312
Phase I										
1035 Mailbox Structures - Ph. I - Replace										
1042 Pavement Overlay Phase I										
1051 Pavement Seal Coat Phase I			8,784						10,798	
1105 Pavement Replacement Phase I										
Phase I Total:			8,784						10,798	
Phase II										
1036 Mailbox Structures - Ph. II - Replace										
1043 Pavement Overlay Phase II										
1052 Pavement Seal Coat Phase II			4,158						5,111	
Phase II Total:			4,158						5,111	
Phase V										
1037 Mailbox Structures - Ph. V - Replace										
1045-0 Pavement Overlay Phase V										
1045-01 Pavement Overlay Phase V Alley										
1054-0 Pavement Seal Coat Phase V			11,563						14,214	
1054-01 Pavement Seal Coat Phase V Alley			1,596						1,962	
1111 Pavement Replacement Phase V Alley										
Phase V Total:			13,159						16,176	
Phase VI										
1038 Mailbox Structures - Ph. VI - Replace										
1046 Pavement Overlay Phase VI										
1055 Pavement Seal Coat Phase VI			14,664						18,026	
Phase VI Total:			14,664						18,026	

	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042
ID Description										
Phase VII										
1039 Mailbox Structures - Ph. VII - Replace 1047 Pavement Overlay Phase VII										
1056 Pavement Seal Coat Phase VII			15,339						18,855	
Phase VII Total:			15,339						18,855	
Phase VIII										
1048 Pavement Overlay Phase VIII									244,009	
1057 Pavement Seal Coat Phase VIII			14,753						18,136	
Phase VIII Total:			14,753						262,144	
Phase IX										
1009 Concete - Curb Ph. IX - 10% Repair			1,674					1,988		
1044 Pavement Overlay Phase IX									240,941	
1053 Pavement Seal Coat Phase IX			14,568						17,908	
Phase IX Total:			16,242					1,988	258,848	
Phase X										
1010 Concrete Surfaces - Ph. X - 3% Repair					3,224					3,829
1017 Fence - Metal/Brick - Ph. X - Replace	Unfunded									
1020 Gate Entry Access - Ph. X - Replace	Unfunded									
1021 Gate Operators - Ph. X - Replace	Unfunded									
1022 Gates - Ph. X - Refurbish	Unfunded									
1023 Gates - Ph. X - Replace	Unfunded									
1049 Pavement Overlay Phase X			93,767							
1058 Pavement Seal Coat Phase X			6,969						8,567	
1064 Sign - Entry - Ph. X - Replace	Unfunded									
Phase X Total:			100,736		3,224				8,567	3,829
Year Total:	352,448	77,643	326,748	143,488	119,519	309,018	136,902	184,739	741,499	382,140

	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052
Beginning Balance	1,521,456	1,530,474	1,801,106	1,989,183	2,238,665	2,292,961	2,230,469	2,573,577	2,902,328	3,050,173
Annual Reserve Account Contribution	398,887	409,458	420,308	431,446	442,880	454,616	466,663	479,030	491,724	504,755
Interest Earned	5,338	6,282	6,938	7,808	7,997	7,779	8,976	10,123	10,638	11,886
Expenditures	395,207	145,108	239,169	189,772	396,582	524,887	132,531	160,401	354,517	158,952
Fully Funded Balance	1,630,777	1,874,178	2,040,523	2,276,006	2,318,299	2,242,335	2,583,315	2,921,373	3,084,831	3,471,405
Percent Funded	94%	96%	97%	98%	99%	99%	100%	99%	99%	98%
Ending Reserve Account Balance	1,530,474	1,801,106	1,989,183	2,238,665	2,292,961	2,230,469	2,573,577	2,902,328	3,050,173	3,407,862
ID Description										
Master										
1001 Benches - Repair/Replacement						9,053				
1002 Bridge Pond - Replace									19,709	
1004 Bridges 1, 2, 3 - Replace									81,658	
1005 Bridges Paint Wood Surfaces	1,705					2,025				
1008 Clock Tower Paint / Repair Contingency		2,479			2,749			3,047		
1012 Creek Pump House Shed Repair Contingency					8,295					
1013 Creek Pump Creek - Refurbish		33,106								
1015 Entry Sign & Monument - Refurbish									5,119	
1018 Fence (wood) - Paint/Stain	Unfunded									
1019 Fences Along Lions Park - Replace	Unfunded									
1024 Gazebo - Major Renovation						31,995				
1025 Gazebo - Paint			4,901						6,024	
1026 Gazebo Roof - Replace										
1027-0 GVW Concrete - Replacement					7,856					9,331
1027-01 Non-GVW Concrete - Replacement	55,913					66,407				
1027-01b Non-GVW Concrete (2022) - Replacemer	nt									
1028 Irrigation Controllers 20% Replace			35,152			38,974			43,211	
1029 Irrrigation Backflow Devices - 11% replace	1,995		2,137		2,289		2,452		2,627	
1030 Lights Pole Fixtures Phases I & II - Replace										
1031 Lights Pole Phases I & II - Replace										
1033 Mailbox Clusters (10 box) - Replace				72,448						
1033c Mailbox Clusters (Village 10) - Replace										
1033d Mailbox Clusters (Village 9) - Replace										

	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052
ID Description										
Master continued										
1033e Mailbox Clusters (Village 8) - Replace	16,168									
1040 Mailbox Wooden Structures (10 box) - Replace									28,387	
1040c Mailbox Wooden Structures (Village 9) - Repl										
1041 Pavement Overlay Master										
1050 Pavement Seal Coat Master					27,264					
1062 Pond Large - De-muck & Maintenace										
•	Infunded									
1080 Storm Water System Drains & Catch Basins M.L	Infunded									
1081 Streetside Signs - Replace										
1082-1 Sump Pump 2 HP - High Water / Ground W			31,853							
1082-2 Sump Pump 3/4 HP - Pond Fill - Replace			14,332							
1083-3 Sump Pump 1 HP - (765 Heron) - Replace			15,472							
1083-4 Common Sump Pump Components (765 He			7,187			7,969			8,835	
1084 Sump Pump Backup Generator - Replace					29,379					
1086-0 GVW Tree Care										
1086-01 Non-GVW Tree Care	11,183	11,574	11,979	12,398	12,832	13,281	13,746	14,227	14,725	15,241
1095 UG Sprinkler Pipe Master Areas 4.8%	197,950	0 5 0 7	0.074	10.010		235,103	44.007	44 799		40.550
1096 Walking Paths Bark Dust & Chip Rock Refurbis.	9,214	9,537	9,871	10,216	10,574	10,944	11,327	11,723	12,134	12,558
1097 Well Clock Tower - Repair Contingency			5,554						6,827	
1099 Well Pump - Replace					35,097					
1102 Fence & Gate (lions park) - Replace	C 011	7 1 5 2	7 400	7 ( ( )	7 0 2 0	0.200	0.405	0 702	0.100	0.410
1103-0 GVW Concrete - Grinding	6,911	7,153	7,403	7,662	7,930	8,208	8,495	8,793	9,100	9,419
1103-01 Non-GVW Concrete - Grinding	6,911	7,153	7,403	7,662	7,930	8,208	8,495	8,793	9,100	9,419
1108 Pond Small - Liner - Replace	35,816	37,070	38,367	39,710	41,100	12 520	44,027	45,568	47,163	48,814
1109 Pavement - Crack Sealing & Repair 1110 VGC Riding Mower - Replace	-	57,070	50,507	59,/10	41,100	42,538	44,027	-	47,103	40,814
1110 VGC Riding Mower - Replace 1112 GVW Tree/Shrub/Other - Common Area Refu	15,656 22,365	23,148	23,958	24,797	25,665	26,563	27,493	19,918 28,455	29,451	30,482
1112 GVW Tree/Shrub/Other - Common Area Refu. 1112b GVW Tree/Shrub (2027) - Refurbishment	22,365 6,710	23,148 6,944	23,958 7,187	7,439	25,665 7,699	20,303 7,969	27,495 8,248	28,435 8,536	8,835	50,482 9,144
1112 OVW Tree/Shrub/Other - Common Area	0,710	0,944	7,107	7,433	1,035	1,303	0,240	0,000	0,000	5,144
1113b Non GVW Tree/Shrub/Other - Common Area 1113b Non GVW Tree/Shrub (2027) - Refurbishment	6,710	6,944	7,187	7,439	7,699	7,969	8,248	8,536	8,835	9,144
1114 Maintenance & Storage (Trail 1) Shed - Replace	0,710	0,544	7,107	7,455	1,055	1,505	0,240	0,550	0,000	5,144

1114 Maintenance & Storage (Trail 1) Shed - Replace

	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052
ID Description										
Master continued										
1245 Shed - Replace										
Master Total:	395,207	145,108	229,944	189,772	234,359	517,206	132,531	157,598	341,742	153,552
Phase I										
1035 Mailbox Structures - Ph. I - Replace 1042 Pavement Overlay Phase I					7,353					
1051 Pavement Seal Coat Phase I 1105 Pavement Replacement Phase I					13,274					
Phase I Total:					20,627					
Phase II										
1036 Mailbox Structures - Ph. II - Replace 1043 Pavement Overlay Phase II					10,707					
1052 Pavement Seal Coat Phase II					6,283					
Phase II Total:					16,990					
Phase V										
1037 Mailbox Structures - Ph. V - Replace 1045-0 Pavement Overlay Phase V			6,864							
1045-01 Pavement Overlay Phase V Alley										
1054-0 Pavement Seal Coat Phase V					17,473					
1054-01 Pavement Seal Coat Phase V Alley					2,411					
1111 Pavement Replacement Phase V Alley										
Phase V Total:			6,864		19,884					
Phase VI										
1038 Mailbox Structures - Ph. VI - Replace						7,682				
1046 Pavement Overlay Phase VI										
1055 Pavement Seal Coat Phase VI					22,159					
Phase VI Total:					22,159	7,682				

	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052
ID Description										
Phase VII										
1039 Mailbox Structures - Ph. VII - Replace									12,775	
1047 Pavement Overlay Phase VII										
1056 Pavement Seal Coat Phase VII					23,178					
Phase VII Total:					23,178				12,775	
Phase VIII										
1048 Pavement Overlay Phase VIII										
1057 Pavement Seal Coat Phase VIII					22,294					
Phase VIII Total:					22,294					
Phase IX										
1009 Concete - Curb Ph. IX - 10% Repair			2,361					2,804		
1044 Pavement Overlay Phase IX										
1053 Pavement Seal Coat Phase IX					22,013					
Phase IX Total:			2,361		22,013			2,804		
Phase X										
1010 Concrete Surfaces - Ph. X - 3% Repair					4,547					5,401
1017 Fence - Metal/Brick - Ph. X - Replace	Unfunded									
1020 Gate Entry Access - Ph. X - Replace	Unfunded									
1021 Gate Operators - Ph. X - Replace	Unfunded									
1022 Gates - Ph. X - Refurbish	Unfunded									
1023 Gates - Ph. X - Replace	Unfunded									
1049 Pavement Overlay Phase X										
1058 Pavement Seal Coat Phase X					10,531					
1064 Sign - Entry - Ph. X - Replace	Unfunded									
Phase X Total:					15,078					5,401
Year Total:	395,207	145,108	239,169	189,772	396,582	524,887	132,531	160,401	354,517	158,952

		Current	х	Age	1	Useful	_	Fully
Asset ID	Description	Cost	^	Age	/	Life	-	Funded
Master								
1001	Benches - Repair/Replacement	\$3,831	х	0	/	25	=	\$0
1002	Bridge Pond - Replace		х	26		29	=	\$6,744
1004	Bridges 1, 2, 3 - Replace		х	26		29	=	\$27,941
1005	Bridges Paint Wood Surfaces		х	3		3	=	\$857
1008	Clock Tower Paint / Repair C	\$1,204	х	3		3	=	\$1,204
1012	Creek Pump House Shed Rep	\$3,633	х	6		6	=	\$3,633
1013	Creek Pump Creek - Refurbish	\$16,075	х	9	1	15	=	\$9,645
1015	Entry Sign & Monument - Re	\$1,954	х	26	1	29	=	\$1,751
1018	Fence (wood) - Paint/Stain	. ,	Th	is is U	nfu	nded		. ,
1019	Fences Along Lions Park - Re		Th	is is U	nfu	nded		
1024	Gazebo - Major Renovation	\$13,539	х	5	/	15	=	\$4,513
1025	Gazebo - Paint	\$2,299	х	2	1	6	=	\$766
1026	Gazebo Roof - Replace	\$3,576	х	16	1	23	=	\$2,487
1027-0	GVW Concrete - Replacement	\$3,441	х	1	1	5	=	\$688
1027-01	Non-GVW Concrete - Replac	\$28,100	х	5	1	10	=	\$14,050
1027-01b	Non-GVW Concrete (2022)	\$18,057	х	1	1	1	=	\$18,057
1028	Irrigation Controllers 20% Re	\$16,492	х	2	/	3	=	\$10,994
1029	Irrrigation Backflow Devices	\$1,003	х	2	/	2	=	\$1,003
1030	Lights Pole Fixtures Phases I	\$6,010	х	2	/	20	=	\$601
1031	Lights Pole Phases I & II - Re	\$14,221	х	26	/	40	=	\$9,244
1033	Mailbox Clusters (10 box) - R	\$32,840	х	2	/	25	=	\$2,627
1033c	Mailbox Clusters (Village 10)	\$5,598	х	13	/	25	=	\$2,911
1033d	Mailbox Clusters (Village 9)	\$8,126	х	6	/	25	=	\$1,950
1033e	Mailbox Clusters (Village 8)	\$8,126	х	5	/	25	=	\$1,625
1040	Mailbox Wooden Structures	\$10,834	х	2	/	15	=	\$1,445
1040c	Mailbox Wooden Structures	\$1,625	х	15	/	15	=	\$1,625
1041	Pavement Overlay Master	\$160,654	х	26	/	32	=	\$130,531
1050	Pavement Seal Coat Master	\$11,941	х	0	/	6	=	\$0
1062	Pond Large - De-muck & Mai	\$84,309	х	1	/	20	=	\$4,215
1065	Slope - Maintenance		Th	is is U	nfu	nded		
1080	Storm Water System Drains		Th	is is U	nfu	nded		
1081	Streetside Signs - Replace	\$54,040	х	17	/	25	=	\$36,747
1082-1	Sump Pump 2 HP - High Wat	\$14,944	х	2	/	12	=	\$2,491
1082-2	Sump Pump 3/4 HP - Pond Fi	\$6,724	х	2	/	12	=	\$1,121


		Current				Useful		Fully
Asset ID	Description	Cost	х	Age	/	Life	=	Funded
Master con	tinued							
1083-3	Sump Pump 1 HP - (765 Her	\$7,259	Х	2	/	12	=	\$1,210
1083-4	Common Sump Pump Comp	\$3,372	Х	2	/	3	=	\$2,248
1084	Sump Pump Backup Generat		Х	16	/	20	=	\$10,293
1086-0	GVW Tree Care	\$5,620	Х	1	/	1	=	\$5 <i>,</i> 620
1086-01	Non-GVW Tree Care	\$5,620	Х	1	/	1	=	\$5 <i>,</i> 620
1095	UG Sprinkler Pipe Master Ar	\$99 <i>,</i> 483	Х	25	/	25	=	\$99 <i>,</i> 483
1096	Walking Paths Bark Dust & C	\$4,631	Х	1	/	1	=	\$4 <i>,</i> 631
1097	Well Clock Tower - Repair Co	\$2 <i>,</i> 605	Х	2	/	6	=	\$868
1099	Well Pump - Replace	\$15,371	Х	12	/	12	=	\$15,371
1102	Fence & Gate (lions park) - R	\$4 <i>,</i> 750	Х	26	/	30	=	\$4,116
1103-0	GVW Concrete - Grinding	\$3 <i>,</i> 473	Х	1	/	1	=	\$3 <i>,</i> 473
1103-01	Non-GVW Concrete - Grinding	\$3,473	х	1	/	1	=	\$3,473
1108	Pond Small - Liner - Replace	\$48 <i>,</i> 649	х	3	/	20	=	\$7,297
1109	Pavement - Crack Sealing &	\$18,000	х	1	/	1	=	\$18,000
1110	VGC Riding Mower - Replace	\$7 <i>,</i> 868	х	1	/	7	=	\$1,124
1112	GVW Tree/Shrub/Other - Co	\$11,240	х	1	/	1	=	\$11,240
1112b	GVW Tree/Shrub (2027) - Re	\$3,372	х	0	/	4	=	\$0
1113	Non GVW Tree/Shrub/Other	\$11,240	х	1	/	1	=	\$11,240
1113b	Non GVW Tree/Shrub (2027)	\$3,372	х	0	/	4	=	\$0
1114	Maintenance & Storage (Trai	\$27,861	х	1	/	20	=	\$1,393
1245	Shed - Replace	\$45 <i>,</i> 080	х	0	/	40	=	\$0
Master - T	lotal:							\$508,168
Phase I								
1035	Mailbox Structures - Ph. I - R	\$3,220	х	24	7	24	=	\$3,220
1042	Pavement Overlay Phase I	\$78,215			1		=	\$39,108
1051	Pavement Seal Coat Phase I	\$5,813		0	'/	6	=	\$0
1105	Pavement Replacement Pha				1	30	=	\$105,960
Phase I - 1	-	+/			,			\$148,288
Phase II								·
1036	Mailbox Structures - Ph. II - R	\$4,689	¥	24	/	24	=	\$4,689
1030	Pavement Overlay Phase II	\$4,089			/	31	=	\$29,858
1045	Pavement Seal Coat Phase II	\$2,752		25	',	6	=	\$2 <i>9</i> ,858 \$0
Phase II -		עני, גע	^	U	/	0	-	\$34,547
1 11030 11 -	iotai.							,+C,+CÇ

 Asset ID	Description	Current Cost	x	Age	/	Useful Life	=	Fully Funded
Phase V								
1037	Mailbox Structures - Ph. V	\$3,220	х	2	/	24	=	\$268
1045-0	Pavement Overlay Phase V	\$102,961	х	24	/	30	=	\$82 <i>,</i> 369
1045-01	Pavement Overlay Phase V A	\$14,208	х	30	/	60	=	\$7,104
1054-0	Pavement Seal Coat Phase V	\$7 <i>,</i> 652	х	0	/	6	=	\$0
1054-01	Pavement Seal Coat Phase V	\$1,056	х	0	/	6	=	\$0
1111	Pavement Replacement Pha	\$19,248	х	30	/	30	=	\$19,248
Phase V -	Fotal:							\$108,989
Phase VI								
1038	Mailbox Structures - Ph. VI	\$3,251	v	23	/	24	=	\$3,115
1038		\$3,231		23	/		=	\$103,557
1040	Pavement Seal Coat Phase VI	\$9,705		23	/	6	=	\$0
Phase VI -		<i>,,,,,</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	^	0	/	0	_	\$106,672
								<i>9100,072</i>
Phase VII								
1039	Mailbox Structures - Ph. VII	. ,		20	/	24	=	\$4,063
1047	-	\$136,574		20	/	26	=	\$105,057
1056	Pavement Seal Coat Phase VII	\$10,151	Х	0	/	6	=	\$0
Phase VII -	Total:							\$109,120
Phase VIII								
1048	Pavement Overlay Phase VIII	\$131,365	х	13	/	31	=	\$55 <i>,</i> 088
1057	Pavement Seal Coat Phase VIII	\$9,764	х	0	/	6	=	\$0
Phase VIII	- Total:							\$55,088
Phase IX								
	Concoto - Curb Ph IV 10%	\$1 100	v	o	7	20	_	¢110
1009	Concete - Curb Ph. IX - 10%	\$1,108		8	1	20 26	=	\$443
1044 1053	Pavement Overlay Phase IX Pavement Seal Coat Phase IX	\$129,713 \$9,641		8 0	1	26 6	=	\$39,912 \$0
Phase IX -		ג <u>ק</u> יפר,041	X	0	/	U		\$0 \$40,355
FIIdSE IA -	iotai.							ş40,555
Phase X								
1010	Concrete Surfaces - Ph. X - 3	\$1,991	х	16	/	20	=	\$1 <i>,</i> 593
1017	Fence - Metal/Brick - Ph. X			is is Ur				
1020	Gate Entry Access - Ph. X - R			is is Ur				
1021	Gate Operators - Ph. X - Repl		Th	is is Ur	nfu	nded		

Asset ID	Description	Current Cost	x	Age	/	Jseful Life	=	Fully Funded	
Phase X co	ntinued								
1022	Gates - Ph. X - Refurbish		Thi	is is U	nfur	ded			
1023	Gates - Ph. X - Replace		Th	is is U	nfur	ded			
1049	Pavement Overlay Phase X	\$62,053	х	16	/	28	=	\$35,459	
1058	Pavement Seal Coat Phase X	\$4,612	х	0	1	6	=	\$0	
1064	Sign - Entry - Ph. X - Replace		Thi	is is U	nfur	ded			
Phase X -	- Total:							\$37,052	
Total Ass	et Summary:							\$1,148,280	

## Villages of Garrison Creek HOA About the Component Detail Reports Section

In the following Component Details Section of this reserve study you will find each component that has been listed within the Component List. This section has more detailed information for each component and reviewing it will often answer questions that arise regarding specific components within this reserve study. Below you will find an explanation of what and where this information is located.



- 1. Component Name and next Replacement Year as well as a unique Asset ID to cross reference with other sections within this reserve study.
- 2. This area has the category of the component, estimated placed in-service date (when last installed), the estimated useful life of the component (estimate of how long the component will last), the next replacement year in this reserve study and the remaining useful life (how many years before replacement is estimated to occur).
- 3. The area has the total measurement/unit count of the component, the cost per unit, the total asset cost (unit count X unit cost), the percent replacement (amount funded to be replaced in a cycle), and the future cost (estimated cost at the next replacement date).
- 4. Pictures of the component are included for Level I studies unless the Client has requested fewer pages in the study in which case we will omit them.
- 5. Specific comments about this component which can include explanations for adjustments to the useful life, phasing, maintenance of the component, Vendor recommendations, etc.

Benches - Repair/Re	eplacement	8 ea	@ \$478.82
Asset ID	1001	Asset Actual Cost	\$3,830.56
	Master	Percent Replacement	100%
	Grounds Components	Future Cost	\$9 <i>,</i> 052.55
Placed in Service	January 2023		
Useful Life	25		
Replacement Year	2048		
Remaining Life	25		

Wood benches appear to be deteriorating at a rate in line with their age. Expect for eventual replacement due to deterioration from constant exposure to the elements. We recommend inspecting annually and painting regularly (from operating account) to maximize the useful life of these wood benches.

\*Note that there is also one concrete bench along one of the walking paths. This bench has not been included in the replacement count as it is a long life component with no predictable useful life at this time.

#### Cost provided by the Client.

Bridge Pond - Replace		105 sf	@ \$71.64
Asset ID	1002	Asset Actual Cost	\$7,522.20
	Master	Percent Replacement	100%
	Bridges	Future Cost	\$8,340.00
Placed in Service	June 1997		
Useful Life	25		
Adjustment	4		
Replacement Year	2026		
Remaining Life	3		

Pedestrian bridges were all reportedly refurbished in 2014. Current bridges are a mix of composite and wood built on a wood frame. We recommend budgeting for replacement at the timeframe indicated due to deterioration from constant exposure to the elements. This component includes replacement of the railing on the bridges as well. Cost estimate based on total replacement of these bridges and not just refurbishment as deterioration to the bridges is likely to be too great to safely and cost effectively refurbish (concrete footing/foundation excluded). Cost estimate includes disposal and installation of the new bridges.

Positive life adjustment given as the Client stated repairs were made in 2020 which has extended the useful life. Cost provided by the Client.

Bridges 1, 2, 3 - Replace		1 ls	@ \$31,165.15
Asset ID	1004	Asset Actual Cost	\$31,165.15
	Master	Percent Replacement	100%
	Bridges	Future Cost	\$34,553.36
Placed in Service	June 1997		
Useful Life	25		
Adjustment	4		
Replacement Year	2026		
Remaining Life	3		

Pedestrian bridges were all reportedly refurbished in 2014. Current bridges are a mix of composite and wood built on a wood frame. We recommend budgeting for replacement at the timeframe indicated due to deterioration from constant exposure to the elements. This component includes replacement of the railing on the bridges as well. Cost estimate based on total replacement of these bridges and not just refurbishment as deterioration to the bridges is likely to be too great to safely and cost effectively refurbish (concrete footing/foundation excluded). Cost estimate includes disposal and installation of the new bridges.

# Cost provided by the Client. Positive life adjustment given as the Client stated repairs were made in 2020 which has extended the useful life.

- 330 square foot bridge 1 with 32 lf railing
- 80 square foot bridge 2 with 40 lf railing
- 115 square foot bridge 4 with 42 lf railing

Bridges Paint Wood Surfa	aces	1 total	@ \$856.80
Asset ID	1005	Asset Actual Cost	\$856.80
	Master	Percent Replacement	100%
	Bridges	Future Cost	\$856.80
Placed in Service	June 2020		
Useful Life	5		
Adjustment	-2		
Replacement Year	2023		
Remaining Life	0		

Pedestrian bridges were all reportedly refurbished/painted in 2014. Current bridges and railings are a mix of composite and wood built on a wood frame. We recommend regularly painting/staining the wood surfaces of these bridges to maximize their useful life.

#### Cost provided by the Client based on recent records. Life adjustment given so this cycles with

Bridges Paint Wood Surfaces continued...

the next bridge replacement cycle.	330- sf E	Bridge 1 with 3	32 lf railing
@ \$1.36	\$448.80		
80 - sf Bridge 2 with 40 lf railing	a	\$1.36	\$108.80
105 - sf Bridge 3 with 42 lf railing	a	\$1.36	\$142.80
115 - sf Bridge 4 with 42 lf railing	a	\$1.36	<u>\$156.40</u>
		Total =	\$856.80

Clock Tower Paint / Repa	air Contingency	) 1 ls	@ \$1,203.80
Asset ID	1008	Asset Actual Cost	\$1,203.80
	Master	Percent Replacement	100%
	Structures	Future Cost	\$1,203.80
Placed in Service	June 2020		
Useful Life	3		
Replacement Year	2023		
Remaining Life	0		

This component is for a repair contingency for the clock tower which has roofing, paint, siding, a door and clock components which will require ongoing maintenance and upkeep. We suggest budgeting at the amount and timeframe indicated to make ongoing repairs and maintenance of this component. If properly cared for we currently have no estimation for full replacement of this component. As a history of expenses occur over time we suggest incorporating these costs into future reserve studies.

## Cost provided by the Client based on recent records.

Creek Pump House Shed	Repair Contingency		
		1 ea	@ \$3,632.97
Asset ID	1012	Asset Actual Cost	\$3 <i>,</i> 632.97
	Master	Percent Replacement	100%
	Structures	Future Cost	\$3 <i>,</i> 632.97
Placed in Service	June 2016		
Useful Life	6		
Replacement Year	2023		
Remaining Life	0		

This component is for a repair contingency for the shed which has roofing, paint, siding and a

## Creek Pump House Shed Repair Contingency continued...

door which will require ongoing maintenance and upkeep. We suggest budgeting at the amount and timeframe indicated to make ongoing repairs and maintenance of this component. If properly cared for we currently have no estimation for full replacement of this component. As a history of expenses occur over time we suggest incorporating these costs into future reserve studies.

Cost and date of last Creek House repairs has been obtained from the Client.

Creek Pump Creek - Refu	rbish	1 ls	@ \$16,075.14
Asset ID	1013	Asset Actual Cost	\$16,075.14
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$19,760.45
Placed in Service	June 2014		
Useful Life	15		
Replacement Year	2029		
Remaining Life	6		

This component is for the refurbishment of the irrigation system in Garrison Creek. This system includes a deep well and a system to pump the water to irrigation zones in the community. The cost estimate and useful life of this component has been obtained from the Client records.

Entry Sign & Monument	- Refurbish	1 ls	@ \$1,953.51
Asset ID	1015	Asset Actual Cost	\$1,953.51
	Master	Percent Replacement	100%
	Signs	Future Cost	\$2,165.89
Placed in Service	June 1997		
Useful Life	25		
Adjustment	4		
Replacement Year	2026		
Remaining Life	3		

This component is for the refurbishment of the cement/mortar and replacement of the plastic/fiberglass sign on the entry monument. Most of the monument is concrete (faux rock) and is a long life component which has no predictable remaining useful life but which will require cement/mortar repairs . Note that these long life entry monument are most often replaced after vehicle damage (accidents) rather than deterioration. We recommend cleaning the monument annually to retain the aesthetic appeal of the monument.

## Entry Sign & Monument - Refurbish continued...

Cost provided by the Client. Positive life adjustment given as the Client stated repairs were made in 2020 which has extended the useful life.

Fence (wood) - Paint/Stain		1,657 lf	@ \$9.82
Asset ID	1018	Asset Actual Cost	\$16,271.74
	Master	Percent Replacement	100%
	Fencing	Future Cost	\$16,841.25
Placed in Service	June 2019		
Useful Life	5		
Replacement Year	2024		
Remaining Life	1		

Currently there is no stain/paint/seal on the wood fence. Regular cycles of stain/paint will help to maintain appearance and maximize life (longer than current useful life estimate). Cost estimate includes 1 primer coat and 1 top coat.

#### Measurement Include:

1118 If along Lions Park323 If along Larch Ave (South of entry is Owner Responsibility per the Board)216 If along Larch Ave (North of Entry is Owner Responsibility per the Board)

\*\*Board has requested this component not be funded for as they have historically not painted or stained/sealed the wood fencing.

Fences Along Lions Park	- Replace	1,118 lf	@ \$60.33
Asset ID	1019	Asset Actual Cost	\$67,448.94
	Master	Percent Replacement	100%
	Fencing	Future Cost	\$67,448.94
Placed in Service	June 1997		
Useful Life	25		
Replacement Year	2023		
Remaining Life	0		

Wood fencing appears to be deteriorating at a rate typical of its age and is nearing the end of its useful life. There are numerous areas of failure and warping wood but no large-scale instability observed at this time. As routine maintenance, inspect regularly for any damage, repair as needed. Avoid contact with ground and surrounding vegetation. Regular cycles of stain/paint will help to maintain appearance and maximize life (longer than current useful life

## Fences Along Lions Park - Replace continued...

estimate). Plan to replace at roughly the time frame indicated.

#### Measurement includes:

1118 If along Lions Park

323 If along Larch Ave (South of entry is Owner Responsibility per the Board)

216 If along Larch Ave (North of Entry is Owner Responsibility per the Board)

#### Cost provided by the Client.

FY 2022 Update - This component has been Unfunded (removed from the mathematical models) as it is reportedly the lot owner's/city's responsibility per the current Boards interpretation of the community governing documents. We have left it in the component list as this was a component in prior years; if there is ambiguity or vagueness in the governing documents verbiage we suggest consulting with council to make a conclusive determination.

Gazebo - Major Renovation	)	1 ls	@ \$13,538.70
Asset ID	1024	Asset Actual Cost	\$13,538.70
	Master	Percent Replacement	100%
	Structures	Future Cost	\$19,097.67
Placed in Service	June 2018		
Useful Life	15		
Replacement Year	2033		
Remaining Life	10		

This component is for a major refurbishment of the gazebo which, with time, will see significant deterioration due to exposure to the elements. Currently the structure appears to have been well maintained and has received regular cycles of paint/sealing. With continued regular cycles of maintenance/painting/sealing this component will likely have a useful life of 30 years.

- -Wood surfaces (eaves, ceiling)
- 6 wood benches
- 544 sf composite decking over wood

Gazebo renovation cost estimate has been obtained from the Client based on their actual project cost.

Gazebo - Paint		1 ls	@ \$2,299.22
Asset ID	1025	Asset Actual Cost	\$2,299.22
	Master	Percent Replacement	100%
	Structures	Future Cost	\$2,638.41
Placed in Service	June 2021		
Useful Life	6		
Replacement Year	2027		
Remaining Life	4		

This component is for the painting and sealing (caulking where needed) of the gazebo which we recommend regular paint cycles of every 6 years to maintain the aesthetic appeal of the community as well as extend the useful life of this component.

#### Cost provided by the Client.

Gazebo Roof - Replace		6 squares	@ \$595.93
Asset ID	1026	Asset Actual Cost	\$3 <i>,</i> 575.58
	Master	Percent Replacement	100%
	Structures	Future Cost	\$4,549.14
Placed in Service	June 2007		
Useful Life	23		
Replacement Year	2030		
Remaining Life	7		

Appears to be deteriorating at a rate typical of its age based our limited scope visual inspection. Reportedly installed in 2007. As routine maintenance, we recommend professional inspections at least twice annually and after windstorms. Promptly replace any damaged/missing shingles or any other repair needed to ensure waterproof integrity of roof. Keep gutters and downspouts clear and free of debris. Plan for replacement at roughly the time frame indicated. Cost estimates include removal of old roofing materials and replacement of flashing.

Roof replacement has been timed to coincide with the major refurbishment project of this component.

\*1 square = 100 Square Feet

GVW Concrete - Repla	acement	1 ls	@ \$3,440.66
Asset ID	1027-0	Asset Actual Cost	\$3,440.66
	Master	Percent Replacement	100%
	Concrete / Pavers	Future Cost	\$3 <i>,</i> 948.23
Placed in Service	June 2022		
Useful Life	5		
Replacement Year	2027		
Remaining Life	4		

5% Repair contingency for the concrete walkways, curbs and paver path-(only 108 sf). Amount and cycle to be reviewed annually. Widespread areas of cracking and numerous areas of repairs noted. Due to root intrusion it is likely that this is going to be on ongoing expense into the foreseeable future. We recommend repairing trip hazards immediately to minimize liability for the Association.

We suggest consulting with a licensed arborist to develop an appropriate plan for tree care to minimize further damage to concrete and maximize cost efficiencies.

Total of 39,498 sf feet of concrete surfaces at the walkways and other concrete areas in the plat. the current mulp sump estimate is based on the Client jistorical records and ongoing consultation with the concrete Vendor.

Cost provided by the Client.

Non-GVW Concrete - Replacement		1 ls	@ \$28,100.00
Asset ID	1027-01	Asset Actual Cost	\$28,100.00
	Master	Percent Replacement	100%
	Concrete / Pavers	Future Cost	\$33 <i>,</i> 373.98
Placed in Service	June 2017		
Useful Life	5		
Replacement Year	2028		
Remaining Life	5		

5% Repair contingency for the concrete walkways, curbs and paver path-(only 108 sf). Amount and cycle to be reviewed annually. Widespread areas of cracking and numerous areas of repairs noted. Due to root intrusion it is likely that this is going to be on ongoing expense into the foreseeable future. We recommend repairing trip hazards immediately to minimize liability for the Association.

We suggest consulting with a licensed arborist to develop an appropriate plan for tree care to minimize further damage to concrete and maximize cost efficiencies.

Non-GVW Concrete - Replacement continued...

Total of 39,498 sf feet of concrete surfaces at the walkways and other concrete areas in the plat. The current cost estimate and useful life cycle is based on the Client historical records and ongoing consultation with the concrete Vendor.

Cost provided by the Client.

Non-GVW Concrete (2	2022) - Replacement	) 1 ls	@ \$18,057.06
Asset ID	1027-01b	Asset Actual Cost	\$18,057.06
	Master	Percent Replacement	100%
	Concrete / Pavers	Future Cost	\$18,057.06
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

5% Repair contingency for the concrete walkways, curbs and paver path-(only 108 sf). Amount and cycle to be reviewed annually. Widespread areas of cracking and numerous areas of repairs noted. Due to root intrusion it is likely that this is going to be on ongoing expense into the foreseeable future. We recommend repairing trip hazards immediately to minimize liability for the Association.

We suggest consulting with a licensed arborist to develop an appropriate plan for tree care to minimize further damage to concrete and maximize cost efficiencies.

Irrigation Controllers 209	% Replace	21 ea	@ \$3,926.60
Asset ID	1028	Asset Actual Cost	\$16,491.72
	Master	Percent Replacement	20%
	Landscaping	Future Cost	\$17,068.93
Placed in Service	June 2021		
Useful Life	3		
Replacement Year	2024		
Remaining Life	1		

Total of 39,498 sf feet of concrete surfaces at the walkways and other concrete areas in the plat.

Reported to be functioning properly with no significant repair/replacement history. It is not

## Irrigation Controllers 20% Replace continued...

known when each controller was last replaced so this component has been set for 20% of them to be replaced every 3 years; there will be a full cycle of replacement every 15 years which is the typical useful life of irrigation controllers.

## Cost provided by the Client.

Irrrigation Backflow Devices - 11% replace		9 ea	@ \$1,001.83
Asset ID	1029	Asset Actual Cost	\$1,002.63
	Master	Percent Replacement	11.12%
	Plumbing	Future Cost	\$1,002.63
Placed in Service	June 2021		
Useful Life	2		
Replacement Year	2023		
Remaining Life	0		

Board reports functional and in operating condition. As routine maintenance, inspect regularly, test system, repair as needed from operating budget. Follow proper winterization and spring start up procedures. Since we have no historical record of installation dates or replacement we suggest budgeting for replacement of one backflow device every 2 years which will so that all backflow devices are replaced every 18 years which is the approximate useful life of this component.

## Cost provided by the Client.

Lights Pole Fixtures Phas	es I & II - Replace	6 ea	@ \$1,001.64
Asset ID	1030	Asset Actual Cost	\$6,009.86
	Master	Percent Replacement	100%
	Lighting	Future Cost	\$11,163.25
Placed in Service	June 2021		
Useful Life	20		
Replacement Year	2041		
Remaining Life	18		

Pole light fixtures appear to be deteriorating at a rate typical of a component of this age. This component is for replacement of the ballast and pole mounted fixtures which will typically deteriorate with time.

The pole light replacement project supersedes the pole light fixture replacement as the cost of

## Lights Pole Fixtures Phases I & II - Replace continued...

the fixture is already included in this replacement project.

Cost provided by the Client.

Lights Pole Phases I & II	- Replace	6 ea	@ \$2,370.16
Asset ID	1031	Asset Actual Cost	\$14,220.96
	Master	Percent Replacement	100%
	Lighting	Future Cost	\$23,019.39
Placed in Service	June 1997		
Useful Life	40		
Replacement Year	2037		
Remaining Life	14		

Pole lights appear to be deteriorating at a rate typical of a component of this age. The exterior paint on the lights have significant fading and wear. This component is for full replacement of the metal poles and fixtures which will typically deteriorate with time due to constant exposure to the elements.

This pole light replacement project supersedes the pole light fixture replacement as the cost of the fixture is already included in this replacement project.

Mailbox Clusters (10 box) - Replace		10 ea	@ \$3,283.98
Asset ID	1033	Asset Actual Cost	\$32,839.80
	Master	Percent Replacement	100%
	Mailboxes	Future Cost	\$72,448.36
Placed in Service	June 2021		
Useful Life	25		
Replacement Year	2046		
Remaining Life	23		

Appears to be deteriorating at a rate typical of its age based on our visual inspection of this component. As routine maintenance, inspect regularly, clean by wiping down for appearance, change lock cylinders, lubricate hinges and repair as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

Mailbox Clusters (Village 10) - Replace		1 ea	@ \$5,597.69
Asset ID	1033c	Asset Actual Cost	\$5,597.69
	Master	Percent Replacement	100%
	Mailboxes	Future Cost	\$8,458.49
Placed in Service	June 2010		
Useful Life	25		
Replacement Year	2035		
Remaining Life	12		

Appears to be deteriorating at a rate typical of its age based on our visual inspection of this component. As routine maintenance, inspect regularly, clean by wiping down for appearance, change lock cylinders, lubricate hinges and repair as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

Mailbox Clusters (Village 9) - Replace		1 ea	@ \$8,125.68
Asset ID	1033d	Asset Actual Cost	\$8,125.68
	Master	Percent Replacement	100%
	Mailboxes	Future Cost	\$15,621.63
Placed in Service	June 2017		
Useful Life	25		
Replacement Year	2042		
Remaining Life	19		

Appears to be deteriorating at a rate typical of its age based on our visual inspection of this component. As routine maintenance, inspect regularly, clean by wiping down for appearance, change lock cylinders, lubricate hinges and repair as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

Mailbox Clusters (Village 8) - Replace		1 ea	@ \$8,125.68
Asset ID	1033e	Asset Actual Cost	\$8,125.68
	Master	Percent Replacement	100%
	Mailboxes	Future Cost	\$16,168.39
Placed in Service	June 2018		
Useful Life	25		
Replacement Year	2043		
Remaining Life	20		

Appears to be deteriorating at a rate typical of its age based on our visual inspection of this

# Mailbox Clusters (Village 8) - Replace continued...

component. As routine maintenance, inspect regularly, clean by wiping down for appearance, change lock cylinders, lubricate hinges and repair as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

# Mailbox Wooden Structures (10 box) - Replace

		10 ea	@ \$1,083.42
Asset ID	1040	Asset Actual Cost	\$10,834.20
	Master	Percent Replacement	100%
	Mailboxes	Future Cost	\$16,944.21
Placed in Service	June 2021		
Useful Life	15		
Replacement Year	2036		
Remaining Life	13		

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

\*Note this component is for replacement of the wood mailbox roof structures only. To rebuild all 10 box stations.

Mailbox Wooden Str	ructures (Village 9) -	Replace	
Asset ID	1040c	1 ea Asset Actual Cost	@ \$1,625.14 \$1,625.14
	Master	Percent Replacement	100%
	Mailboxes	Future Cost	\$1 <i>,</i> 625.14
Placed in Service	June 2023		
Useful Life	15		
Replacement Year	2023		
Remaining Life	0		

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

### Mailbox Wooden Structures (Village 9) - Replace continued...

\*Note this component is for replacement of the wood mailbox roof structures only. To rebuild in Village 9 (larger station).

Pavement Overlay Master		54,275 sf	@ \$2.96
Asset ID	1041	Asset Actual Cost	\$160,654.00
	Master	Percent Replacement	100%
	Asphalt	Future Cost	\$197 <i>,</i> 484.78
Placed in Service	June 1997		
Useful Life	30		
Adjustment	2		
Replacement Year	2029		
Remaining Life	6		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

Cost estimate obtained from the Client based on their own bids obtained from a vendor they are working with. It is assumed the scope of work includes minor repairs, 2 inch overlay, cleaning, crack sealing, etc. It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Master	)	54,275 sf	@ \$0.22
Asset ID	1050	Asset Actual Cost	\$11,940.50
	Master	Percent Replacement	100%
	Asphalt	Future Cost	\$14,677.92
Placed in Service Ja	nuary 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt surfaces might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Proper drainage is vital for the longevity of the road. Standing water can seep through the asphalt and get into the subbase and subgrade below, significantly weakening the structural integrity of the road and causing premature failure.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

\*\*Life Adjustment of -2 years to coincide with the regular sealcoat cycle for cost efficiency.

Cost estimate has been obtained from recent Client vendor bids.

Pond Large - De-muck & Maintenace		18,131 sf	@ \$4.65
Asset ID	1062	Asset Actual Cost	\$84,309.15
	Master	Percent Replacement	100%
	Ponds	Future Cost	\$162,084.45
Placed in Service	January 2022		
Useful Life	20		
Replacement Year	2042		
Remaining Life	19		

We recommend a pond assessment be conducted on each pond to determine the most appropriate and costefficient method to replace these liners which complying with all required government regulations. The cost estimate in this study is based on removal of the old liner and replacement with a new one in each pond.

The Client has stated they drained the water from the large pond and have determined that there is no pond liner in this pond. Refurbishment of the pond would be for sediment removal. It is assumed that this is accurate and the liner is not below sediment in the bottom of the pond.

Pond Large - De-muck & Maintenace continued...

Cost estimate provided by the Client based on Vendor bid.

Slope - Maintenance		1 ls	
Asset ID	1065	Asset Actual Cost	
	Master	Percent Replacement	100%
	Landscaping	Future Cost	
Placed in Service No Useful Life	June 1997		

The parcel maps indicate areas of the slope South of Garrison Creek are the responsibility of the Association. Currently there is no historical record of expenses or issues with this slope so there is no current recommendation for funding in this reserve study. We suggest inspecting annually and should it appear there are slope issues (drainage, slippage, etc.) we recommend consulting with a qualified professional and incorporating bids into future reserve studies.

Storm Water System Drains & Catch Basins Maintenance				
		1 ls	@ \$10,835.06	
Asset ID	1080	Asset Actual Cost	\$10,835.06	
	Master	Percent Replacement	100%	
	Plumbing	Future Cost	\$10,835.06	
Placed in Service	June 1997			
Useful Life	3			
Replacement Year	2023			
Remaining Life	0			

We suggest consulting with a qualified and licensed vendor to set up an annual maintenance paid for from the Operating Account. Currently the Board has stated there has been no maintenance (debris/sediment removal) from the storm water systems in the community. We have given an estimate for this first time service but actual costs may be higher if there is significant amounts of debris/sediment which requires removal.

We also suggest that these systems be inspected annually at the time of service to make sure the components are functioning as designed. Update future reserve studies with either actual costs or remove from the study if the community decides to set up an annual contract.

The Client has stated this is being funded from the Operating Account and has requested it be Unfunded (removed from he mathematical models) from the reserve study. With proper maintenance there is no predictable useful life or remaining useful life for this component. With annual inspections and maintenance any issues that do develop over time can be adequately budgeted for well in advance of project date.

Streetside Signs - Replace		1 ls	@ \$54,039.87
Asset ID	1081	Asset Actual Cost	\$54,039.87
	Master	Percent Replacement	100%
	Signs	Future Cost	\$71,160.19
Placed in Service	June 2006		
Useful Life	25		
Replacement Year	2031		
Remaining Life	8		

The street signs in the community are deteriorating at a rate in line with their age. We recommend funding for replacement of the signs as the timeframe indicated due to constant exposure to the elements.

36 - street signs	@	\$812.64	\$29,255.07
26 - medium signs (stop/community)	@	\$406.31	\$10,564.18
70 - small signs (parking, etc.	@	\$203.15	<u>\$14,220.62</u>
		Total =	\$54,039.87

Sump Pump 2 HP - High Water / Ground Water				
		1 ea	@ \$14,943.73	
Asset ID	1082-1	Asset Actual Cost	\$14,943.73	
	Master	Percent Replacement	100%	
	Mechanical	Future Cost	\$21,079.61	
Placed in Service	June 2021			
Useful Life	12			
Replacement Year	2033			
Remaining Life	10			

Sump pumps reportedly in working order. Replacement year and cost obtained form client records. We recommend budgeting for replacement of these sump pumps at the timeframe indicated.

Cost provided by the Client.

Sump Pump 3/4 HP -	- Pond Fill - Replace	1 ea	@ \$6,723.77
Asset ID	1082-2	Asset Actual Cost	\$6,723.77
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$9,484.54
Placed in Service	June 2021		
Useful Life	12		
Replacement Year	2033		
Remaining Life	10		

Sump pump reportedly in working order. Replacement year and cost obtained form client records. We recommend budgeting for replacement of these sump pumps at the timeframe indicated.

### Cost estimate obtained from the Client.

Sump Pump 1 HP - (76	5 Heron) - Replace	1 ea	@ \$7,258.79
Asset ID	1083-3	Asset Actual Cost	\$7,258.79
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$10,239.24
Placed in Service	June 2021		
Useful Life	12		
Replacement Year	2033		
Remaining Life	10		

Sump pump reportedly in working order. Replacement year and cost obtained form client records. We recommend budgeting for replacement of these sump pumps at the timeframe indicated.

The Client has stated they will repair as needed (paid from the Operating Account) and have elected to defer the replacement until fiscal year 2022; a life adjustment has been given to reflect this.

Common Sump Pump	Components (765	Heron) - Repair/Replace	
		1 ea	@ \$3,372.00
Asset ID	1083-4	Asset Actual Cost	\$3,372.00
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$3 <i>,</i> 490.02
Placed in Service	June 2021		
Useful Life	3		
Replacement Year	2024		
Remaining Life	1		

Sump pump reportedly in working order. Replacement year and cost obtained form client records. We recommend budgeting for replacement of these sump pumps at the timeframe indicated.

### Cost estimate obtained from the Client.

Sump Pump Backup Ger	nerator - Replace	) 1 ea	@ \$12,866.62
Asset ID	1084	Asset Actual Cost	\$12,866.62
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$14,764.74
Placed in Service	June 2007		
Useful Life	20		
Replacement Year	2027		
Remaining Life	4		

Gas generator reportedly in working condition and was installed in 2007. We recommend planning for replacement at the timeframe indicated.

GVW Tree Care		1 ls	@ \$5,620.00
Asset ID	1086-0	Asset Actual Cost	\$5 <i>,</i> 620.00
	Master	Percent Replacement	100%
	Tree Care	Future Cost	\$5 <i>,</i> 620.00
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

This component is for tree care of the overgrown/overcrowded trees and in the community. These large trees require regular trimming/thinning/root control to prevent damage to nearby walkways, roads and underground piping. The provided cost estimate is based on our estimation for the total expected cost for all the trees in the

#### GVW Tree Care continued...

community and is based on the historical records provided by the Board.

We recommend consulting with a qualified arborist to determine an appropriate long term strategy for adequate tree care as well as develop a plan which is most cost efficient for the Association. We suggest updating future reserve studies with actual cost figures and timeframes for projects.

Note that there is likely going to be a significant amount of tree care for the trees along Garrison Village Way and there are already areas in need of repair. As these trees continue to grow with age they will become more costly to maintain and will likely continue to cause damage to other common area components.

Cost provided by the Client based on historical records. Reportedly for thinning, trimming, root care and tree replacement.

Non-GVW Tree Care		1 ls	@ \$5,620.00
Asset ID	1086-01	Asset Actual Cost	\$5,620.00
	Master	Percent Replacement	100%
	Tree Care	Future Cost	\$5 <i>,</i> 620.00
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

This component is for tree care of the large trees in the community. These large trees require regular trimming/thinning/root control to prevent damage to nearby walkways, roads and underground piping. The provided cost estimate is based on our estimation for the total expected cost for all the trees in the community and is based on the historical records provided by the Board.

We recommend consulting with a qualified arborist to determine an appropriate long term strategy for adequate tree care as well as develop a plan which is most cost efficient for the Association. We suggest updating future reserve studies with actual cost figures and timeframes for projects.

Note that there is likely going to be a significant amount of tree care for the trees along Garrison Village Way and there are already areas in need of repair. As these trees continue to grow with age they will become more costly to maintain and will likely continue to cause damage to other common area components.

Cost provided by the Client based on historical records. Reportedly for thinning, trimming, root care and tree replacement.

### UG Sprinkler Pipe Master Areas 4.8%

Asset ID	1095
	Master
l	<b>Jnderground Sprinklers</b>
Placed in Service	June 1997
Useful Life	5
Adjustment	20
Replacement Year	2023
Remaining Life	0

 1 Is@ \$2,063,964.08

 Asset Actual Cost
 \$99,483.07

 Percent Replacement
 4.82%

 Future Cost
 \$99,483.07

Underground sprinkler piping, over time, will deteriorate as well as become damaged from root intrusion by trees and shrubs. Due to the age of the community and likelihood of underground sprinkler issues in the near future we recommend for replacement of these pipes at the timeframe indicated which is typical of this type of component. There have reportedly been some areas of repair already required due to root intrusion issues. This cost estimate includes replacement of the underground piping and the landscaping which will be torn up in the process. Since this type of component does not typically fail all at once we recommend funding for a repair contingency of 5% per cycle so that over time the whole system will be replaced as each begins to fail.

We suggest consulting with a qualified landscaping company to create a long term plan which covers the communities needs while being as cost efficient as possible. Update future reserve studies with the actual cost estimates and timeframes of projects.

\*\*Useful life has been adjusted +20 years so this component begins cycles of 5 year intervals at the component's age of 25 years from installation date. Cost estimate includes refurbishment of the landscaping which will need to be torn up in the process.

11748 - Park Ph I	<i>(a)</i>	\$5.16	\$60,609.11
7326 - Park Ph. II	<u>a</u>	\$5.16	\$37,795.57
21583 - Park Ph. V	@	\$5.16	\$111,348.86
7104 - Park Ph. VI	a	\$5.16	\$36,650.25
10880 - Park Ph VII	@	\$5.16	\$56,131.01
47004 - Five Parks Ph. VIII	a	\$5.16	\$242,498.34
23280 - Gazebo	a	\$5.16	\$120,103.85
23280 - Clock Tower	@	\$5.16	\$120,103.85
20466 - Garrison Village Way	a	\$5.16	\$105,586.14
196608 - Garrison Creek Parcel - Above Ground	@	\$0.10	\$19,877.07
146211 - Ponds and Concrete Walkway Area	@	\$5.16	\$754,317.17
71928 - North of Phase	@	\$5.16	\$371,083.74
5400 - Along Larch Avenue	@	\$5.16	<u>\$27,859.14</u>
		Total =	\$2,063,964.08

Walking Paths Bark Du	ust & Chip Rock Re	furbish/Replace	
		1 ls	@ \$4,630.88
Asset ID	1096	Asset Actual Cost	\$4,630.88
	Master	Percent Replacement	100%
	Landscaping	Future Cost	\$4,630.88
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

This component is for the replacement of the bark and chip rock in the common areas of the community. The cost figures have been provide by the Board and the timeframe of the useful life is based on their estimation to retain the aesthetic appeal of these landscaped areas. While landscaping is often paid for from the Operating Account these large scale projects that do to occur annually can be include in the reserve study.

### Cost obtained from Client based on actual invoice for the last completed project.

Well Clock Tower - Repai	r Contingency	1 ls	@ \$2,605.43
Asset ID	1097	Asset Actual Cost	\$2,605.43
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$2,989.79
Placed in Service	June 2021		
Useful Life	6		
Replacement Year	2027		
Remaining Life	4		

This component is for a repair contingency to the 400' deep well (located in clock tower) that services the community. While this component has no predictable useful life and is reportedly in operational condition wells with typically require repairs over time. We recommend inspecting annually and should the well require replacement or large scale refurbishment to update future reserve studies.

#### Cost provided by the Client.

Well Pump - Replace	)	1 ea	@ \$15,370.87
Asset ID	1099	Asset Actual Cost	\$15,370.87
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$15 <i>,</i> 370.87
Placed in Service	June 2009		
Useful Life	12		
Replacement Year	2023		
Remaining Life	0		

10HP well pump reportedly in working order and last replaced in 2009. We recommend budgeting for replacement at the timeframe indicated. Cost and useful life provided by Client and Vendor (Lee's Pump).

Fence & Gate (lions park)	- Replace	40 lf	@ \$118.74
Asset ID	1102	Asset Actual Cost	\$4,749.53
	Master	Percent Replacement	100%
	Fencing	Future Cost	\$5,450.20
Placed in Service	June 1997		
Useful Life	30		
Replacement Year	2027		
Remaining Life	4		

Fence and gate to Lions Park reportedly installed in 2017. Cost provided by the Client and inflated to current estimate.

GVW Concrete - Grinding		1 ls	@ \$3,473.16
Asset ID	1103-0	Asset Actual Cost	\$3,473.16
	Master	Percent Replacement	100%
Cor	ncrete / Pavers	Future Cost	\$3 <i>,</i> 473.16
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

Repair contingency for grinding the concrete walkways. Amount and cycle to be reviewed annually. Widespread areas of cracking and numerous areas of repairs noted. Due to root intrusion it is likely that this is going to be on ongoing expense into the foreseeable future. We

GVW Concrete - Grinding continued...

recommend repairing trip hazards immediately to minimize liability for the Association.

We suggest consulting with a licensed arborist to develop an appropriate plan for tree care to minimize further damage to concrete and maximize cost efficiencies. The Client has stated they would like to treat grinding as a reserve expense (as opposed to Operational) going forward.

Total of 39,498 sf feet of concrete surfaces in the community. Cost estimate provided by the Client based on historical records and consultation with the concrete Vendor.

Non-GVW Concrete -	Grinding	1 total	@ \$3,473.16
Asset ID	1103-01	Asset Actual Cost	\$3,473.16
	Master	Percent Replacement	100%
	Concrete / Pavers	Future Cost	\$3,473.16
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

Repair contingency for grinding the concrete walkways. Amount and cycle to be reviewed annually. Widespread areas of cracking and numerous areas of repairs noted. Due to root intrusion it is likely that this is going to be on ongoing expense into the foreseeable future. We recommend repairing trip hazards immediately to minimize liability for the Association.

We suggest consulting with a licensed arborist to develop an appropriate plan for tree care to minimize further damage to concrete and maximize cost efficiencies. The Client has stated they would like to treat grinding as a reserve expense (as opposed to Operational) going forward.

Total of 39,498 sf feet of concrete surfaces in the community. Cost estimate provided by the Client based on historical records and consultation with the concrete Vendor.

Pond Small - Liner - Replace	)	3,510 sf	@ \$13.86
Asset ID	1108	Asset Actual Cost	\$48,648.60
	Master	Percent Replacement	100%
	Ponds	Future Cost	\$87 <i>,</i> 308.45
Placed in Service	June 2020		
Useful Life	20		
Replacement Year	2040		
Remaining Life	17		

Pond liner at the small pond is in poor condition with numerous areas of rips and tears visible. We recommend a pond assessment be conducted on each pond to determine the most appropriate and cost efficient method to replace these liners which complying with all required government regulations. The cost estimate in this study is based on removal of the old liner and replacement with a new one in each pond.

We suggest obtaining bids and replacing these liners per the pond assessment recommendations and incorporating actual costs and useful life estimates, which will depend on the mill (thickness) of the new membrane liner, into future reserve studies.

Cost provided by Client Vendor estimate. The pond is reportedly going to be resized and renovated with new landscaping. We have utilized the Vendor dollar per square foot cost for this pond liner which includes removing sediment on top of the liner.

Pavement - Crack Sealing	& Repair	1 ls	@ \$18,000.00
Asset ID	1109	Asset Actual Cost	\$18,000.00
	Master	Percent Replacement	100%
	Asphalt	Future Cost	\$18,000.00
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

A lump sum component (estimate based on historical records and consultation with the pavement Vendor) has been included for pavement crack sealing a the Client has requested this be included in the reserve study due to the amount which is making it difficult to budget for from the operational account. This is for all crack sealing throughout the payment that are maintained by the Master Association.

VGC Riding Mower - Replace	ce	1 ea	@ \$7,868.00
Asset ID	1110	Asset Actual Cost	\$7,868.00
	Master	Percent Replacement	100%
	Mechanical	Future Cost	\$9,671.78
Placed in Service	March 2022		
Useful Life	7		
Replacement Year	2029		
Remaining Life	6		

The cost estimate has been provided by the Client based on the model of mower they are choosing.

Cost provided by the Client per invoice.

GVW Tree/Shrub/Other	- Common Area Ro	efurbishment	
Asset ID	1112 Master	1 ls Asset Actual Cost Percent Replacement	@ \$11,240.00 \$11,240.00 100%
	Landscaping	Future Cost	\$11,240.00
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

Although ongoing maintenance is funded from the Operating Account, this component may be utilized for setting aside funds for larger expenses, such as: weed barrier replacement, large scale plantings, common area drainage projects, resodding lawn areas, landscape improvement projects, etc.

Cost Source: Client Historical Records – Inflated to Current Estimate

GVW Tree/Shrub (2027) - Refurbishment		1 ls	@ \$3,372.00
Asset ID	1112b	Asset Actual Cost	\$3,372.00
	Master	Percent Replacement	100%
	Landscaping	Future Cost	\$3 <i>,</i> 869.45
Placed in Service	June 2027		
Useful Life	1		
Replacement Year	2027		
Remaining Life	4		

Although ongoing maintenance is funded from the Operating Account, this component may be utilized

GVW Tree/Shrub (2027) - Refurbishment continued...

for setting aside funds for larger expenses, such as: weed barrier replacement, large scale plantings, common area drainage projects, resodding lawn areas, landscape improvement projects, etc.

Cost Source: Client Historical Records – Inflated to Current Estimate

Non GVW Tree/Shrub/Other - Common Area Refurbishment			
		1 ls	@ \$11,240.00
Asset ID	1113	Asset Actual Cost	\$11,240.00
	Master	Percent Replacement	100%
	Landscaping	Future Cost	\$11,240.00
Placed in Service	June 2022		
Useful Life	1		
Replacement Year	2023		
Remaining Life	0		

Although ongoing maintenance is funded from the Operating Account, this component may be utilized for setting aside funds for larger expenses, such as: weed barrier replacement, large scale plantings, common area drainage projects, resodding lawn areas, landscape improvement projects, etc.

This component has been included and set to cycle annually per the request of the Board for the inclusion of a landscape refurbishment component. Landscape refurbishment has reportedly been very expensive and difficult to budget for out of the operational account so the inclusion of this gong forward will help to stabilize the operational budget while adequately budgeting for it from the reserve account.

Cost Source: Client Historical Records – Inflated to Current Estimate

Non GVW Tree/Shrub (2	027) - Refurbishment		
		1 ls	@ \$3,372.00
Asset ID	1113b	Asset Actual Cost	\$3,372.00
	Master	Percent Replacement	100%
	Landscaping	Future Cost	\$3 <i>,</i> 869.45
Placed in Service	June 2027		
Useful Life	1		
Replacement Year	2027		
Remaining Life	4		

Although ongoing maintenance is funded from the Operating Account, this component may be utilized for setting aside funds for larger expenses, such as: weed barrier replacement, large scale plantings, common area drainage projects, resodding lawn areas, landscape improvement projects, etc.

This component has been included and set to cycle annually per the request of the Board for the inclusion of a landscape refurbishment component. Landscape refurbishment has reportedly been very expensive and difficult to budget for out of the operational account so the inclusion of this gong forward will help to stabilize the operational budget while adequately budgeting for it from the reserve account.

Cost Source: Client Historical Records – Inflated to Current Estimate

# Maintenance & Storage (Trail 1) Shed - Replace

Asset ID	1114
	Master
	Structures
Placed in Service	June 2022
Useful Life	20
Replacement Year	2042
Remaining Life	19

 1 ea
 @ \$27,860.59

 Asset Actual Cost
 \$27,860.59

 Percent Replacement
 100%

 Future Cost
 \$53,562.02

We recommend budgeting for replacement at the timeframe indicated. Some areas of damages observed but appear to be stable structure overall.

\*Cost Source: Client Historical Records – Inflated to Current Estimate

Shed - Replace		392 sf	@ \$115.00
Asset ID	) 1245	Asset Actual Cost	\$45,080.00
	Master	Percent Replacement	100%
	Structures	Future Cost	\$178,483.42
Placed in Service	e January 2023		
Useful Life	e 40		
Replacement Year	2063		
Remaining Life	e 40		

We recommend budgeting for replacement at the timeframe indicated. Some areas of damages observed but appear to be stable structure overall.

#### Shed was not yet installed at the date of the site inspection.

\*Cost Source: Client Historical Records – Inflated to Current Estimate

Mailbox Structures -	Ph. I - Replace		2 ea	@ \$1,610.13
Asset ID	103	35	Asset Actual Cost	\$3,220.26
	Phase	e I	Percent Replacement	100%
	Mailbox	es	Future Cost	\$3,220.26
Placed in Service	June 199	<del>)</del> 7		
Useful Life		24		
Replacement Year	202	23		
Remaining Life		0		

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

\*Note this component is for replacement of the wood mailbox structures only. The Board has stated the metal mailboxes are the responsibility of each owner.

Pavement Overlay Phase I		26,424 sf	@ \$2.96
Asset ID	1042	Asset Actual Cost	\$78,215.04
	Phase I	Percent Replacement	100%
	Asphalt	Future Cost	\$219,533.48
Placed in Service	June 2023		
Useful Life	30		
Replacement Year	2053		
Remaining Life	30		

### Cost provided by the Client.

As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

Pavement Overlay Phase I continued ...

\*\*Life Adjustment given so component coincides with the regular sealcoat cycle for cost efficiency.

Cost estimate obtained from the Client based on their own bids obtained from a vendor they are working with. It is assumed the scope of work includes minor repairs, 2 inch overlay, cleaning, crack sealing, etc.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Phase I	)	26,424 sf	@ \$0.22
Asset ID	1051	Asset Actual Cost	\$5 <i>,</i> 813.28
	Phase I	Percent Replacement	100%
	Asphalt	Future Cost	\$7,146.01
Placed in Service Ja	nuary 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Life adjustment given so this component coincides with future Replacement/Overlay projects. Cost estimate has been obtained from recent Client vendor bids.

Pavement Replaceme	ent Phase I	26,424 sf	@ \$4.01
Asset ID	1105	Asset Actual Cost	\$105,960.24
	Phase I	Percent Replacement	100%
	Asphalt	Future Cost	\$105 <i>,</i> 960.24
Placed in Service	June 2023		
Useful Life	30		
Replacement Year	2023		
Remaining Life	0		

This component has been included to cycle once as the Phase I roads are in below average condition at this time and are likely suffering from an installation issue at the time of construction. Cost estimate has been provided by the Client Vendor.

This component has superceded the Overlay project for Phase I and has been set to occur only once.

Mailbox Structures - Ph. II - Replace		3 ea		@ \$1,563.10	
Asset ID	103	6	Asset Actual Cost	\$4,689.30	
	Phase	П	Percent Replacement	100%	
	Mailboxe	es	Future Cost	\$4,689.30	
Placed in Service	June 199	8			
Useful Life	2	4			
Replacement Year	202	3			
Remaining Life		0			

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

\*Note this component is for replacement of the wood mailbox structures only. The Board has stated the metal mailboxes are the responsibility of each owner.

Pavement Overlay Phase I		12,508 sf	@ \$2.96
Asset ID	1043	Asset Actual Cost	\$37,023.68
	Phase II	Percent Replacement	100%
	Asphalt	Future Cost	\$45,511.56
Placed in Service	June 1998		
Useful Life	30		
Adjustment	1		
Replacement Year	2029		
Remaining Life	6		

### Cost provided by the Client.

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt

Pavement Overlay Phase II continued...

surfaces at the time of the overlay.

\*\*Life Adjustment given to coincide with the regular sealcoat cycle for cost efficiency.

Cost estimate obtained from the Client based on their own bids obtained from a vendor they are working with. It is assumed the scope of work includes minor repairs, 2 inch overlay, cleaning, crack sealing, etc.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Life adjustment given so this cycles with a sealcoat project.

Pavement Seal Coat Phase II		12,508 sf	@ \$0.22
Asset ID	1052	Asset Actual Cost	\$2,751.76
	Phase II	Percent Replacement	100%
	Asphalt	Future Cost	\$3,382.62
Placed in Service	January 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Cost estimate has been obtained from recent Client vendor bids.

Mailbox Structures -	Ph. V - Replace		2 ea	@ \$1,610.13
Asset ID	103	7	Asset Actual Cost	\$3,220.26
	Phase	V	Percent Replacement	100%
	Mailboxe	S	Future Cost	\$6,864.02
Placed in Service	June 202	1		
Useful Life	2	4		
Replacement Year	204	5		
Remaining Life	2	2		

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

\*Note this component is for replacement of the wood mailbox structures only. The Board has stated the metal mailboxes are the responsibility of each owner.

Pavement Overlay Phase V		34,784 sf	@ \$2.96
Asset ID	1045-0	Asset Actual Cost	\$102,960.64
	Phase V	Percent Replacement	100%
	Asphalt	Future Cost	\$126,564.91
Placed in Service	June 1999		
Useful Life	30		
Replacement Year	2029		
Remaining Life	6		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

Pavement Overlay Phase V continued...

\*\*Life Adjustment of given to coincide with the regular sealcoat cycle for cost efficiency.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Overlay Phase	V Alley	4,800 sf	@ \$2.96
Asset ID	1045-01	Asset Actual Cost	\$14,208.00
	Phase V	Percent Replacement	100%
	Asphalt	Future Cost	\$39,878.92
Placed in Service	June 2023		
Useful Life	30		
Replacement Year	2053		
Remaining Life	30		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

\*\*Life Adjustment of given to coincide with the replacement project for this area of Phase V.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Pha	ase V	34,784 sf	@ \$0.22
Asset ID	1054-0	Asset Actual Cost	\$7,652.48
	Phase V	Percent Replacement	100%
	Asphalt	Future Cost	\$9 <i>,</i> 406.85
Placed in Service	January 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Pavement Seal Coat Pha	ase V Alley	4,800 sf	@ \$0.22
Asset ID	1054-01	Asset Actual Cost	\$1,056.00
	Phase V	Percent Replacement	100%
	Asphalt	Future Cost	\$1,298.09
Placed in Service	January 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

Cost estimate has been obtained from recent Client vendor bids.

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is

#### Pavement Seal Coat Phase V Alley continued...

recommended annually and treated as an operating expense.

Cost estimate has been obtained from recent Client vendor bids. Life adjustment given so this cycle with the planned replacement component for this area.

Pavement Replacement Phase V Alley		4,800 sf	@ \$4.01
Asset ID	1111	Asset Actual Cost	\$19,248.00
	Phase V	Percent Replacement	100%
	Asphalt	Future Cost	\$19,248.00
Placed in Service	June 2023		
Useful Life	30		
Replacement Year	2023		
Remaining Life	0		

This component has been included to cycle once as the Phase V alley is reportedly in in below average condition at this time and are likely suffering from an installation issue at the time of construction. Cost estimate has been provided by the Client Vendor for replacement (similar to Phase 1 replacement).

This component has superseded the Overlay project for Phase V Valley and has been set to occur only once.

Mailbox Structures - Ph. VI - Replace		2 ea	@ \$1,625.26
Asset ID	1038	3 Asset Actual Cost	\$3,250.52
	Phase V	I Percent Replacement	100%
	Mailboxes	s Future Cost	\$3,364.29
Placed in Service	June 2000	)	
Useful Life	24	1	
Replacement Year	2024	1	
Remaining Life	1	L	

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

\*Note this component is for replacement of the wood mailbox structures only. The Board has stated the metal mailboxes are the responsibility of each owner.

Pavement Overlay Phase V	1	44,112 sf	@ \$2.96
Asset ID	1046	Asset Actual Cost	\$130,571.52
	Phase VI	Percent Replacement	100%
	Asphalt	Future Cost	\$160,505.74
Placed in Service	June 2000		
Useful Life	30		
Adjustment	-1		
Replacement Year	2029		
Remaining Life	6		

Reportedly areas which were not installed to appropriately. We have reduced the useful life of the asphalt roads in this phase as it is not likely this will last a full 30 years. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

Life Adjustment given due to a a poor install and to coincide with the regular sealcoat cycle for cost efficiency.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Phase VI		44,112 sf	@ \$0.22
Asset ID	1055	Asset Actual Cost	\$9,704.64
	Phase VI	Percent Replacement	100%
	Asphalt	Future Cost	\$11,929.48
Placed in Service Janu	uary 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Cost estimate has been obtained from recent Client vendor invoice for this phase.

Mailbox Structures -	Ph. VII - Replace	3 еа	@ \$1,625.26
Asset ID	1039	Asset Actual Cost	\$4,875.78
	Phase VII	Percent Replacement	100%
	Mailboxes	Future Cost	\$5 <i>,</i> 595.07
Placed in Service	June 2003		
Useful Life	24		
Replacement Year	2027		
Remaining Life	4		

Appears to be deteriorating at a rate typical of their age based on our visual inspection of this component. As routine maintenance, inspect regularly, paint/stain and complete minor repairs as needed from operating budget. Best to plan for total replacement at roughly the time frame indicated due to constant usage, exposure to the elements and wear over time.

\*Note this component is for replacement of the wood mailbox structures only. The Board has stated the metal mailboxes are the responsibility of each owner.

Pavement Overlay Phase	VII	46,140 sf	@ \$2.96
Asset ID	1047	Asset Actual Cost	\$136,574.40
	Phase VII	Percent Replacement	100%
	Asphalt	Future Cost	\$167 <i>,</i> 884.81
Placed in Service	June 2003		
Useful Life	30		
Adjustment	-4		
Replacement Year	2029		
Remaining Life	6		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

#### Pavement Overlay Phase VII continued...

Life Adjustment given to coincide with the regular sealcoat cycle for cost efficiency.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Pha	ase VII	46,140 sf	@ \$0.22
Asset ID	1056	Asset Actual Cost	\$10,150.80
	Phase VII	Percent Replacement	100%
	Asphalt	Future Cost	\$12,477.92
Placed in Service	January 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Cost estimate has been obtained from recent Client vendor bids.

Pavement Overlay Phase VIII		44,380 sf	@ \$2.96
Asset ID	1048	Asset Actual Cost	\$131,364.80
	Phase VIII	Percent Replacement	100%
	Asphalt	Future Cost	\$244,008.70
Placed in Service	June 2010		
Useful Life	30		
Adjustment	1		
Replacement Year	2041		
Remaining Life	18		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

Life Adjustment given to coincide with the regular sealcoat cycle for cost efficiency.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Phase VIII		44,380 sf	@ \$0.22
Asset ID	1057	Asset Actual Cost	\$9,763.60
	Phase VIII	Percent Replacement	100%
	Asphalt	Future Cost	\$12,001.96
Placed in Service	January 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

#### Pavement Seal Coat Phase VIII continued...

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Cost estimate has been obtained from recent Client vendor bids.

Concete - Curb Ph. IX -	- 10% Repair	327 lf	@ \$33.87
Asset ID	1009	Asset Actual Cost	\$1,107.55
	Phase IX	Percent Replacement	10%
	Concrete / Pavers	Future Cost	\$1,673.58
Placed in Service	June 2015		
Useful Life	5		
Adjustment	15		
Replacement Year	2035		
Remaining Life	12		

Good condition with no areas of cracking or damage noted. No instability observed at this time. Inspect regularly, pressure wash for appearance and repair as needed from operating budget. No expectation for large scale replacement at this time, if patterns of deterioration emerge, incorporate funding into future reserve study updates as conditions merit.

A life adjustment has been given so this component begins to cycle at 5-year increments after 20 years of age when vehicles and roots have typically caused significant damage.

Pavement Overlay Phase IX		43,822 sf	@ \$2.96
Asset ID	1044	Asset Actual Cost	\$129,713.12
	Phase IX	Percent Replacement	100%
	Asphalt	Future Cost	\$240,940.72
Placed in Service	June 2015		
Useful Life	30		
Adjustment	-4		
Replacement Year	2041		
Remaining Life	18		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

#### Pavement Overlay Phase IX continued...

\*\*Measurements include the 4,300 square foot asphalt walking path in this phase.

Cost estimate obtained from the Client based on their own bids obtained from a vendor they are working with. It is assumed the scope of work includes minor repairs, 2 inch overlay, cleaning, crack sealing, etc. Life adjustment so this coincides with the Sealoating schedule.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Phase	e IX	43,822 sf	@ \$0.22
Asset ID	1053	Asset Actual Cost	\$9,640.84
	Phase IX	Percent Replacement	100%
	Asphalt	Future Cost	\$11,851.05
Placed in Service	January 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

\*Measurements include the 4,300 square foot asphalt walking path in this phase.

Cost estimate has been obtained from recent Client vendor bids for this phase.

. X - 3% Repair	4,085 sf	@ \$16.25
1010	Asset Actual Cost	\$1,991.44
Phase X	Percent Replacement	3%
Concrete / Pavers	Future Cost	\$2,285.22
June 2007		
5		
15		
2027		
4		
	1010 Phase X Concrete / Pavers June 2007 5 15 2027	1010Asset Actual CostPhase XPercent ReplacementConcrete / PaversFuture CostJune 20075152027

3% Repair contingency for the concrete walkways, curbs in this phase (at both entrances). Amount and cycle to be reviewed annually. We recommend repairing trip hazards immediately to minimize liability for the Association.

The useful life has been adjusted 15 years as concrete rarely requires repairs until approximately 20 years old (vehicle damage and root intrusion). this component has it's first cycle start in 2027.

Fence - Metal/Brick - Ph. X - Replace		1 total	@ \$16,862.75
Asset ID	1017	Asset Actual Cost	\$16,862.75
	Phase X	Percent Replacement	100%
	Fencing	Future Cost	\$27,295.64
Placed in Service	June 1997		
Useful Life	40		
Replacement Year	2037		
Remaining Life	14		

The metal and brick pillar fence at both entrances to Phase X appears to be deteriorating at a rate in line with its age. The metal over time will deteriorate due to constant exposure so we recommend planning for replacement at the timeframe indicated. If properly installed the brick pillars are a long life component but which will likely require repointing of some of the brickwork in areas over time. We recommend planning for repointing/repairing a portion of the brickwork on these pillars at the amount indicated below. Over time should it appear thee pillars are deteriorating more rapidly than expected we suggest updating future reserve studies according to actual cost and on site inspection estimates.

We recommend inspecting annually and painting the metal surfaces as needed (paid for from the operating account). A

The Client has requested this be Unfunded (removed from he mathematical models) as they have deemed this not to be the Master Association's responsibility. This is per their own interpretation of their governing

Fence - Metal/Brick - Ph. X - Replace continued...

documents.

82 - If metal fencing	@	\$101.59	\$8,330.14
21 - brick posts	@	\$406.31	<u>\$8,532.61</u>
		Total =	\$16,862.75

Gate Entry Access - P	h. X - Replace	2 ea	@ \$3,792.27
Asset ID	1020	Asset Actual Cost	\$7,584.54
	Phase X	Percent Replacement	100%
	Gate	Future Cost	\$9,987.39
Placed in Service	June 2007		
Useful Life	24		
Replacement Year	2031		
Remaining Life	8		

Fair appearance with no significant damage observed and no reported problems at this time. We recommend professional inspections and maintenance. Wipe down surfaces periodically with an appropriate cleaner, being careful to avoid control buttons. Plan for replacement at approximately the typical life expectancy interval indicated, due to constant usage and exposure to weather elements.

Typically right about 20-25 year these components will begin to have issues and will require replacement along with some wiring upgrades/repairs. The replacement cycles has been timed to coincide with the gate replacement.

The Client has requested this be Unfunded (removed from he mathematical models) as they have deemed this not to be the Master Association's responsibility. This is per their own interpretation of their governing documents.

Gate Operators - Ph. X - F	Replace	4 ea	@ \$5,417.52
Asset ID	1021	Asset Actual Cost	\$21,670.08
	Phase X	Percent Replacement	100%
	Gate	Future Cost	\$29,534.09
Placed in Service	June 2020		
Useful Life	12		
Replacement Year	2032		
Remaining Life	9		

Fair, operating condition of gate observed during our inspection, however they do appear to

## Gate Operators - Ph. X - Replace continued...

be near the end of their useful life . The life of these operators can vary significantly based on usage, bumps, etc. and that typically the entry/exit operators don't always fail at the same time. A useful life of 10-12 years is a rough estimate for replacement (entire unit assumed). Regular maintenance should continue through the operating budget which includes annual inspections, service and maintenance which can extend useful life. We are funding here for regular replacements of gate operators at 12 year intervals as has been our experience with similar operators and since the current operators are still in service since this phase was constructed in 2007.

Replacement cost estimate assumes some minor electrical rewiring and as it typical of our experience with past operator replacement bids and invoices.

The Client has requested this be Unfunded (removed from he mathematical models) as they have deemed this not to be the Master Association's responsibility. This is per their own interpretation of their governing documents.

Gates - Ph. X - Refurbish		1 ls	@ \$1,760.70
Asset ID	1022	Asset Actual Cost	\$1,760.70
	Phase X	Percent Replacement	100%
	Gate	Future Cost	\$1,760.70
Placed in Service	June 2019		
Useful Life	1		
Adjustment	1		
Replacement Year	2023		
Remaining Life	0		

Vehicle and pedestrian entry gates currently have areas in need of paint. This annual refurbishment contingency component has been included based on estimated costs associated with the ongoing repair expenses related to these entry gates. Due to constant usage and exposure to the elements we recommend for funding of regular cycles of refurbishment to the gates and their mechanical/electrical/sensor systems. Inspect annually and clean/paint/repair covered under this repair contingency component.

Gates expenses are very specific to a community due to usage differences and we recommend updated future reserve studies with cost estimated based on actual repair costs for this component.

A positive life adjustment has been made to this component at the request of the Client as there is current litigation as to who is responsible for this component at this time (Association

Gates - Ph. X - Refurbish continued...

or Phase X Lot Owners). This is expected to be definitively determined in fiscal year 2020 so this item can be either removed or left in in the reserve study at that time.

The Client has requested this be Unfunded (removed from he mathematical models) as they have deemed this not to be the Master Association's responsibility. This is per their own interpretation of their governing documents.

Gates - Ph. X - Replace		2 ea	@ \$16,252.57
Asset ID	1023	Asset Actual Cost	\$32,505.14
	Phase X	Percent Replacement	100%
	Gate	Future Cost	\$42,803.06
Placed in Service	June 2007		
Useful Life	24		
Replacement Year	2031		
Remaining Life	8		

Fair condition with areas of rust and peeling paint noted at the time of the site inspection. We recommend regular professional inspections, maintenance and repairs to help extend useful life cycles and paid for from the operating account. Metal gates are typically durable, however, we recommend setting aside funding for intervals of replacement due to constant usage and the typical damage not covered by insurance seen in similar associations.

\*Cost estimate includes vehicle and pedestrian gates at the two entrances to this phase.

The Client has requested this be Unfunded (removed from he mathematical models) as they have deemed this not to be the Master Association's responsibility. This is per their own interpretation of their governing documents.

Pavement Overlay Phase X		20,964 sf	@ \$2.96
Asset ID	1049	Asset Actual Cost	\$62,053.44
	Phase X	Percent Replacement	100%
	Asphalt	Future Cost	\$93,767.01
Placed in Service	June 2007		
Useful Life	30		
Adjustment	-2		
Replacement Year	2035		
Remaining Life	12		

Appears to be deteriorating at a rate typical of its age. As routine maintenance, keep surface clean, ensure that

## Pavement Overlay Phase X continued...

drains are clean and free flowing, repair cracks and clean oils stains promptly. Best to plan for eventual intervals of resurface (overlay).

Most asphalt areas can be expected to last approximately 25-30 years before it will become necessary for an overlay to be applied or other major rehabilitation to be completed. It will be necessary to adjust manhole and valve covers at the time the overlay is applied or other major rehabilitation is completed.

If properly built, the road or parking lot deteriorates from the top down, which only requires the replacement of a layer of asphalt, or preferably the application of a thin layer on top of the existing asphalt (overlay). The asphalt overlay not only provides a new paving surface for a fraction of the cost of rebuilding the entire roadway, but it is the only preventive maintenance technique that adds structural value while extending a pavement's service life.

\*Cost estimate based on a 2 inch overlay and includes expectation for minor repairs to areas of the asphalt surfaces at the time of the overlay.

Life Adjustment given to coincide with the regular sealcoat cycle for cost efficiency.

It is assumed that an Overlay will be possible and appropriate, we suggest annual consultation with the Asphalt Vendor and incorporating their recommendations and cost into updates to this reserve study.

Pavement Seal Coat Phase X		20,964 sf	@ \$0.22
Asset ID	1058	Asset Actual Cost	\$4,612.08
	Phase X	Percent Replacement	100%
	Asphalt	Future Cost	\$5,669.42
Placed in Service Ja	nuary 2023		
Useful Life	6		
Replacement Year	2029		
Remaining Life	6		

The primary reason to sealcoat is to protect the pavement from the deteriorating effects of sun and water, which causes the asphalt to harden, or oxidize. The pavement turns brittle. The sealcoat provides a waterproof membrane which slows the oxidation process and helps the pavement shed water, preventing the water to infiltrate the base material.

Without regular applications of a seal coat, an asphalt parking lot might need an overlay in 15 years. If the lot is regularly sealed, asphalt areas can last as much as 25-30 years if properly installed.

Seal coats should be installed on warm sunny day with low humidity with a minimum of 50 degrees Fahrenheit and rising.

Oil spills eat through the asphalt seal and should be cleaned up between seal coats. Power washing is recommended annually and treated as an operating expense.

Cost estimate has been obtained from recent Client vendor bids.

Sign - Entry - Ph. X - Replace	)	2 ea	@ \$1,218.94
Asset ID	1064	Asset Actual Cost	\$2,437.88
	Phase X	Percent Replacement	100%
	Signs	Future Cost	\$2,437.88
Placed in Service	June 2007		
Useful Life	13		
Adjustment	1		
Replacement Year	2023		
Remaining Life	0		

Entry signs (with interior light) appear faded and the plastic/fiberglass interior has come unglued inside one of the signs. It is assumed both of these signs are operational as it was daylight hours. We recommend replacement at the timeframe indicated due to constant exposure.

A positive life adjustment has been made to this component at the request of the Client as there is current litigation as to who is responsible for this component at this time (Association or Phase X Lot Owners). This is expected to be definitively determined in fiscal year 2020 so this item can be either removed or left in in the reserve study at that time.

The Client has requested this be Unfunded (removed from he mathematical models) as they have deemed this not to be the Master Association's responsibility. This is per their own interpretation of their governing documents.

## **Definitions Index**

### Abbreviations

ea = each	FY = fiscal year	lf or lin ft = lineal feet	ls = lump sum
RL = remaining life	sf or sq ft = square feet	sy or sq yd= square yard	
UL = useful life	100 sq ft = 1 square)	% = percent	

### 1. Allocation %

A percentage of the total Reserve Allocation. See - Calculations Appendix

### 2. Allocation Increase Rate

Expressed as a percentage rate that reflects the increase of a given year's Reserve Allocation over the previous year's Reserve Allocation and utilized only in the Cash Flow Analysis.

### 3. Base Year

The year in which the governing documents were recorded and/or the buildings constructed (average year may be used for phases built over a period) and utilized to determine the approximate complex age. This parameter is provided for information only.

### 4. Common Interest Development (CID)

Defined by shared property and restrictions in the deed on use of the property. A CID is governed by a mandatory Association of homeowners which administers the property and enforces its restrictions. The following are two typical CID subdivision types:

- Condominium- In general, the recorded owner has title to the unit (or airspace). They are typically responsible for the interior of their individual unit/garage, all utilities that service their unit and any exclusive use common area associated with their unit.
- Planned Development- In general, the recorded owner has title to the lot. They are typically responsible for the maintenance and repair of any structure or improvement located on their respective lot.

\*Note- CIDs & subdivision types are general and may not apply or may vary, based on your local.

## 5. Component Inventory

The task of selecting and quantifying reserve items. This task can be accomplished through on-site visual observations, review of association design and organizational documents, review of established association precedents, and discussion with appropriate association representatives.

### 6. Condition Assessment

The task of evaluating the current condition of the component based on observed or reported characteristics and normal documented in the field report for a Level 1 or Level 2 Reserve Study.

### 7. Contingency Rate

Expressed as a percentage rate that reflects a factor added to the unit cost to prepare for an event that is liable to occur, but not with certainty.

### 8. Current Cost

The current fiscal year's estimated cost to maintain, replace, repair, or restore a reserve component to its original functional condition. Sources utilized to obtain estimates may include: the association, its contractors, other contractors, specialists and independent consultants, the State department of Real Estate (or other state department as applicable), construction pricing and estimating manuals, and the preparer's own experience and/or database of costs formulated in the preparation of other reserve study reports. See - Calculations Appendix.

### 9. Disbursement / Expenditures

The funds expected to be paid or expended from the Reserve Balance. 10. Extended Cost

See - Calculations Appendix.

## 11. Fiscal Year (FY)

A twelve-month period for which an organization plans the use of its

funds. There are two distinct types:

- Calendar Fiscal Year (ends December 31)
- Non-Calendar Fiscal Year (does not end December 31)

### 12. Full Funded Balance (FFB)

Total Accrued Depreciation. An indicator against which the FY Start Balance can be compared. The balance that is in direct proportion to the fraction of life "used up" of the cost. See - Calculations Appendix.

#### 13. Funding Goal

Independent of methodology utilized, the following represents the basic categories of funding plan goals:

- Baseline Funding- Maintaining a Net Reserve Balance above zero for length of the study.
- Full Funding- Maintaining a Reserve Balance at or near Percent Funded of 100%.
- Statutory Funding- Maintaining a specified Reserve Balance/Percent Funded per statutes.
- Threshold Funding- Establishing and maintaining a set predetermined Reserve Balance or Percent Funded.

### 14. Funding Method (or Funding Plan)

An Association's plan to provide income to the reserve fund to offset expected disbursements from that fund. The following represents two (2) basic methodologies used to fund reserves:

- Cash Flow Method- A method of developing a reserve funding plan where allocations to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.
- Component Method- The component method develops a reservefunding plan where the total contribution is based on the sum of contributions for individual components. The component method is the more conservative (typically higher reserve account balance) of the two funding options and assures that the association will achieve and maintain an ideal level of reserves over time. This method also allows for computations on individual components in the analysis. However, this method has also limitations with respects to variations in actual useful life of components and is much more time intensive to accurately follow this funding strategy.

#### 15. Funding Plan

The combined Funding Method & Funding Goal.

- FY End Balance (same as next FY Start Balance) The balance in reserves at end of applicable fiscal year. See -Calculations Appendix.
- 17. FY Start Balance (same as prior year FY End Balance) The balance in reserves at start of applicable fiscal year.
- 18. Inflation Rate

Expressed as a percentage rate that reflects the increase of this year's costs over the previous year's costs. Also known as a 'cost increase factor'.

### 19. Interest Earned

The annual earning of reserve funds that have been deposited into certificates of deposit (CDs), money market accounts or other investment vehicles. See - Calculations Appendix.

### 20. Interest Rate

The ratio of the gain received from an investment and the investment over a period (usually one year), prior to any federal or state-imposed taxes.

### 21. Interest Rate (net effective)

The ratio of the gain received from an investment and the investment over a period (usually one year), after any federal or state-imposed taxes.

### 22. Levels of Service

Level 1 Reserve Study (Full or Comprehensive)- A Reserve Study in which the following five Reserve Study tasks are performed:

- Component Inventory
- Condition Assessment (based upon on-site visual observations)
- Life and Valuation Estimates
- Fund Status
- Funding Plan

Level 2 Reserve Study (Update, With-Site-Visit/On-Site Review)- A Reserve Study update in which the following five tasks are performed:

- Component Inventory (from prior study)
- Condition Assessment (based upon on-site visual observations)
- Life and Valuation Estimates
- Fund Status
- Funding Plan

\*Note- Updates are reliant on the validity of prior Reserve Studies. Level 3 Reserve Study (Update, No-Site-Visit/Off-Site Review)- A Reserve Study update with no on-site visual observations in which the following three tasks are performed:

- Component Inventory (from prior study)
- Condition Assessment (based upon on-site visual observations)
- Life and Valuation Estimates
- Fund Status
- Funding Plan

\*Note- Updates are reliant on the validity of prior Reserve Studies.

## 23. Percent Funded

A comparison of the Fully Funded Balance (ideal balance) to the Fiscal Year Actual Start Balance expressed as a percentage and used to provide a 'general indication' of reserve strength. See Calculations Appendix.

#### 24. Quantity

The number or amount of a reserve component or subcomponent. 25. Remaining Life (RL)

## The estimated time, in years, that a reserve component

can be expected to continue to serve its intended function.

## 26. Replacement %

A percentage of the total replacement for a reserve component or subcomponent. This parameter is normally 100%.

## 27. Reserve Allocation

The amount to be annually budgeted towards reserves based on a Funding Plan.

### 28. Reserve Component (or subcomponent)

The individual line items in the reserve study, developed or updated in the physical analysis that form the building blocks of the reserve study. They typically are:

- an association responsibility,
- with limited useful life expectancies,
- predictable remaining useful life expectancies,
- above a minimum threshold cost,
- and, as required by statutes.

### 29. Restoration

Defined as to bring back to an unimpaired or improved condition. General types follow:

- Building- In general, funding utilized to defray the cost (in whole or part) of major building components that are not necessarily included as line items and may include termite treatment.
- Irrigation System- In general, funding utilized to defray the cost (in whole or part) of sectional irrigation system areas including modernization to improve water management.
- Landscape- In general, funding utilized to defray the cost (in whole or part) of sectional landscape areas including modernization to improve water conservation & drainage.

### 30. Risk Factor (Percent Funded)

The associated risk of the availability of reserves to fund expenditures by interpreting the Percent Funded parameter as follows:

- 70% and above LOW
- 30% to 70% MODERATE
- 30% and below HIGH

\*High risk is associated with a higher risk for reliance on special assessments, loans and litigation.

## 31. Unit Cost

The current fiscal year's estimated cost to maintain, replace, repair, or restore an individual "unit of measure" of a reserve component or subcomponent to its original functional condition.

## 32. Unit of Measure

A system of units used in measuring a reserve component or subcomponent (i.e. each, lineal feet, square feet, etc.).

## 33. Useful Life (UL)

Total Useful Life or Depreciable Life. The estimated time, in years, that a reserve item can be expected to serve its intended function if properly constructed and maintained in its present application or installation.

## **Disclosures Index**

The below disclosures are in accordance with reserve study standards developed by CAI, APRA and statutory requirements.

1. Items Beyond the Scope of this Report

This reserve study has been conducted to outline a financial plan for the proper and adequate budgeting of the Association component repair and/or replacement. This report should not be utilized for any other purpose and should not be considered or deemed appropriate or reliable for, but not limited to, any of the following:

- Building or land appraisals for any purpose
- State or local zoning ordinance violations
- Building code violations
- Soils conditions, soils contamination or geological stability of site
- Engineering analysis or structural stability of site
- Air quality, asbestos, electromagnetic radiation, formaldehyde, lead, mercury, or radon
- Water quality or other environmental hazards
- Invasions by termites and any or all other destroying organisms or insects
- Damage or destruction due to pests, birds, bats or animals to buildings or site
- Adequacy or efficiency of any system or component on site
- Specifically excluded reserve items
- Septic systems and septic tanks
- Buried or concealed portions of swing pools, pool liners, Jacuzzis/spas or similar items
- Items concealed by signs, carpets or other things
- Missing or omitted information supplied by the Association for the purposes of reserve study preparation
- Hidden improvements such as sewer lines, water lines, or other buried or concealed items

## 2. Qualifications

We are a professional business in the market to prepare Reserve Studies. Our Reserve Analysts' are either designated with or working towards the RS and/or PRA designations which are given by the two leading industry organizations which require peer review, continuing education and provide resources to stay on top of industry trends.

## 3. Invasive Testing

Estimated life expectancies and life cycles are based upon conditions that were readily accessible and visible at the time of the site visit. We did not destroy any landscape work, building walls, or perform any methods of intrusive/invasive testing during the site visit. In these cases, information may have been obtained by contacting the contractor or vendor that has worked on the property. The physical analysis performed during this site visit is not intended to be exhaustive in nature and may include representative sampling.

## 4. Conflicts of Interests

As the preparer of this reserve study; the Reserve Analyst certifies that we do not have any vested interests, financial interests, or other interests that would cause a conflict of interest in the preparation of this reserve study.

5. Representative Sampling

This study and report is based on observations of the visible and apparent conditions of a reasonable representative sampling of the property's elements at the time of inspection. Although due diligence was performed during the inspection phase, we make no representations regarding latent or concealed defects that may exist. The inspection did not constitute any invasive investigations and was not intended to determine whether applicable building components, systems, or equipment are adequate or in compliance with any specific or commonly accepted design requirement, building code, or specification. Such tasks as material testing, engineering analysis, destructive testing, or performance testing of building systems, components, or are they considered by the reserve study industry standard.

## 6. Reliance on Client & Vendor Data Provided

Information provided to the preparer of a reserve study by an official representative of the association regarding financial, historical, physical, quantitative or reserve project issues will be deemed reliable by the preparer. A reserve study will reflect information provided to the preparer of the reserve study. The total of actual or projected reserves required as presented in the reserve study is based upon information provided that was not audited. A reserve study is not intended to be used to perform an audit, an analysis of quality, a forensic study or a background check of historical records. A site visit conducted in conjunction with a reserve study should not be deemed to be a project audit or quality inspection. The results of this study are based on the independent opinion of the preparer and their experience and research during their career in preparing Reserve Studies. In addition, the opinions of experts on certain components have been gathered through research within their industry and with client's actual vendors. There is no implied warrantee or guarantee regarding our life and cost estimates/predictions. There is no implied warrantee or guarantee in any of our work product. Our results and findings will vary from another preparer's results and findings. A Reserve Study is necessarily a work in progress and subsequent Reserve Studies will vary from prior studies.

### 7. Update to Prior Reserve Studies

Level II Studies: Quantities of major components as reported in previous reserve studies are deemed to be accurate and reliable. The reserve study relies upon the validity of previous reserve studies. Level III Studies: In addition to the above we have not visited the property when completing a Level III "No Site Visit" study. Therefore, we have not verified the current condition of the common area components. It is assumed all prior study component information related to quantities, condition assessments, useful life and remaining useful life are accurate.

8. Assumption Regarding Ongoing Maintenance

The projected life expectancy of the major components and the funding needs of the reserves of the association are based upon the association performing appropriate routine and preventative maintenance for each major component. Failure to perform such maintenance can negatively impact the remaining useful life of the major components.

9. Assumptions Regarding Defect in Design or Construction This Reserve Study assumes that all construction assemblies and components identified herein are built properly and are free from defects in materials and/or workmanship. Defects can lead to reduced useful life and premature failure. It was not the intent of this Reserve Study to inspect for or to identify defects. If defects exist, repairs should be made so that the construction components and assemblies at the community reach their full and expected useful lives. We have assumed all components have been properly built and will reach normal, typical life expectancies. In general, a reserve study is not intended to identify or fund for construction defects. We did not and will not look for or identify construction defects during our site visit.

#### 10. Basis of Cost Estimates

Pricing used for the repair or replacement costs indicated in this report are derived from a variety of sources, e.g., recent contractor bids received by subject property HOA or prior clients, construction product vendor catalogs, internet, or national construction cost estimating publishers (RS Means / Marshall & Swift). The material and labor pricing provided are estimates and have been augmented, as necessary, to account for specific site conditions (i.e. material handling, scaffolding, etc.). The total expenses represent a useful guideline whereby reserve funds can be accumulated for future repairs and replacements. The estimated repair and replacement expenses, unless otherwise noted, do not include allowances for architectural, engineering, or permitting fees.

#### 11. Limitations on Report Use

A reserve study is not intended to be used to perform an audit, an analysis of quality, a forensic study or a background check of historical records. A site visit conducted in conjunction with a reserve study should not be deemed to be a project audit or quality inspection. This Reserve Study is provided as an aid for planning purposes and not as an accounting tool. Since it deals with events yet to take place, there is no assurance that the results enumerated within it will, in fact, occur as described. Additionally, other unanticipated expenses may arise that are not included within this reserve study. This reserve study should be reviewed carefully. It may not include all common and limited common element components that will require major maintenance, repair, or replacement in future years, and may not include regular contributions to a reserve account for the cost of such maintenance, repair, or replacement. The failure to include a component in a reserve study, or to provide contributions to a reserve account for a component, may, under some circumstances, require you to pay on demand as a special assessment your share of common expenses for the cost of major maintenance, repair, or replacement of a reserve component.

#### 12. State Specific Disclosures

#### Washington State

RCW 64.34.382 & WA State RCW 64.38.070

This reserve study includes all aspects required per WA State RCW requirements outlined in the Washington Condominium Act and the Homeowners' Association Act.

This reserve study should be reviewed carefully. It may not include all common and limited common element components that will require major maintenance, repair, or replacement in future years, and may not include regular contributions to a reserve account for the cost of such maintenance, repair, or replacement. The failure to include a component in a reserve study, or to provide contributions to a reserve account for a component, may, under some circumstances, require you to pay on demand as a special assessment your share of common expenses for the cost of major maintenance, repair, or replacement of a reserve component.

#### Washington State

Disclosures Required by RCW 64.90.550. This Reserve Study meets all requirements of the Washington Uniform Common Interest Ownership Act.

- This Reserve Study was prepared with the assistance of a reserve study professional and that professional was independent;
- b) This Reserve Study includes all information required by RCW 64.90.550 Reserve Study Contents; and
- This reserve study should be reviewed carefully. It may c) not include all common and limited common element components that will require major maintenance, repair, or replacement in future years, and may not include regular contributions to a reserve account for the cost of such maintenance, repair, or replacement. The failure to include a component in a reserve study, or to provide contributions to a reserve account for a component, may, under some circumstances, require the association to (1) defer major maintenance, repair, or replacement, (2) increase future reserve contributions, (3) borrow funds to pay for major maintenance, repair, or replacement, or (4) impose special assessments for the cost of major maintenance, repair, or replacement.

## **Calculations Index**

### 1. Allocation % =

Reserve Allocation (Component Method) / Total Reserve Allocation (Component Method) x 100

## 2. Current Cost =

Extended Cost (for a component without subcomponents) i. -or-Sum of subcomponent Extended Costs (for a component with subcomponents)

### 3. Extended Cost =

Quantity x Unit Cost x Replacement % x (1+Contingency Rate)

### 4. FY End Balance (same as Next FY Start Balance) =

Initial or current fiscal year-

Current Reserve Balance + Interest Earned + Reserve Allocation to Fund + Special Assessment

to

Fund + Funds Due from Operating - Approved Funds to Disburse - Disbursements

### Subsequent fiscal years-

FY Start Balance + Interest Earned + (Reserve Allocation (from previous year) x (1 + Reserve Allocation Rate) - Disbursements

## 5. Interest Earned=

### Initial fiscal year-

Current Reserve Balance x (Interest Rate

(net effective)/12 x

Number of funding months remaining in current fiscal year)

### Subsequent fiscal years-

FY Start Balance x Interest Rate (net effective) Accumulation Function and Amount Function

### https://www.reservedataanalyst.com/int

## 6. Percent Funded =

(Reserve Account Balance / Fully Funded Balance) x 100

## 7. Reserve Allocation (Component Method) =

Current Cost / Useful Life

### 8. Fully Funded Balance (FFB) =

## **Basic Fully Funded**

Fully Funded = Age/Useful Life \* Cost

Note that "Age" is adjusted for each year of the study (e.g. one year later also equates to an Age which is one year greater). We do not use the age from the first year of the study for future FFB calculations as this would not appropriately address the deterioration of the component over time (i.e. when providing future projections one can make a valid assumption that a component will deteriorate by one year if providing projections for one year later).

Cost (component project cost) is inflated for each year based on an annual inflation rate (compounding) given in this reserve study (e.g. a paint project "cost" may be \$1,000 in Year 1 of the study but will have a "cost" of \$1,030 in Year 2 of the study, and \$1,060.90 in Year 3 of the study, when utilizing an annual 3% inflation rate. Note that we do not use the "cost" (current project cost) from the first year of the study for future year's FFB calculations as this approach does not consider the impact of inflation on the project cost and will usually result in a significantly underfunded reserve account over time. This is also known as the Inflation Adjusted Cost Method

\*\*Unless specifically noted otherwise we have utilized the above FFB formula and methodology in this reserve study.

### Community Association Institute FFB Formula

The Community Association Institute published the below FFB formula to account for inflation and interest earned on deposit ("present value" is based on the current cost only - with no inflation of the project cost) the writers of 'RESERVE FUNDS: How & Why community Associations Invest Assets' published:

 $Basic_FF = (Age/Useful Life) * Present Value$ 

$$\begin{split} CAI\_FF &= Basic\_FF \\ &+ Basic\_FF/(1+interest)^{Remaining\ Life} \\ &- Basic\_FF/(1+inf\ lation)^{Remaining\ Life} \end{split}$$

More mathematical information can be found at the following link: www.reservedataanalyst.com/math

# Villages of Garrison Creek HOA Component Index

Asset ID Description		Replacement	Page
Master			
1001	Benches - Repair/Replacement	2048	61
1002	Bridge Pond - Replace	2026	61
1004	Bridges 1, 2, 3 - Replace	2026	62
1005	Bridges Paint Wood Surfaces	2023	62
1008	Clock Tower Paint / Repair Contingency	2023	63
1083-4	Common Sump Pump Components (765 Heron) - R	2024	79
1013	Creek Pump Creek - Refurbish	2029	64
1012	Creek Pump House Shed Repair Contingency	2023	63
1015	Entry Sign & Monument - Refurbish	2026	64
1102	Fence & Gate (lions park) - Replace	2027	83
1018	Fence (wood) - Paint/Stain	2024	65
1019	Fences Along Lions Park - Replace	2023	65
1103-0	GVW Concrete - Grinding	2023	83
1027-0	GVW Concrete - Replacement	2027	68
1086-0	GVW Tree Care	2023	79
1112b	GVW Tree/Shrub (2027) - Refurbishment	2027	86
1112	GVW Tree/Shrub/Other - Common Area Refurbish	2023	86
1024	Gazebo - Major Renovation	2033	66
1025	Gazebo - Paint	2027	67
1026	Gazebo Roof - Replace	2030	67
1028	Irrigation Controllers 20% Replace	2024	69
1029	Irrrigation Backflow Devices - 11% replace	2023	70
1030	Lights Pole Fixtures Phases I & II - Replace	2041	70
1031	Lights Pole Phases I & II - Replace	2037	71
1033	Mailbox Clusters (10 box) - Replace	2046	71
1033c	Mailbox Clusters (Village 10) - Replace	2035	72
1033e	Mailbox Clusters (Village 8) - Replace	2043	72
1033d	Mailbox Clusters (Village 9) - Replace	2042	72
1040	Mailbox Wooden Structures (10 box) - Replace	2036	73
1040c	Mailbox Wooden Structures (Village 9) - Replace	2023	73
1114	Maintenance & Storage (Trail 1) Shed - Replace	2042	88
1113b	Non GVW Tree/Shrub (2027) - Refurbishment	2027	88
1113	Non GVW Tree/Shrub/Other - Common Area Refur.	2023	87
1027-0.	Non-GVW Concrete (2022) - Replacement	2023	69
1103-01	Non-GVW Concrete - Grinding	2023	84

# Villages of Garrison Creek HOA Component Index

Asset	ID Description	Replacement	Page	
Master Continued				
1027	-01 Non-GVW Concrete - Replacement	2028	68	
1086	-01 Non-GVW Tree Care	2023	80	
1109	Pavement - Crack Sealing & Repair	2023	85	
1041	Pavement Overlay Master	2029	74	
1050	Pavement Seal Coat Master	2029	75	
1062	Pond Large - De-muck & Maintenace	2042	75	
1108	Pond Small - Liner - Replace	2040	85	
1245	Shed - Replace	2063	89	
1065	Slope - Maintenance	2023	76	
1080	Storm Water System Drains & Catch Basins Mainte	2023	76	
1081	Streetside Signs - Replace	2031	77	
1083	-3 Sump Pump 1 HP - (765 Heron) - Replace	2033	78	
1082	-1 Sump Pump 2 HP - High Water / Ground Water	2033	77	
1082	-2 Sump Pump 3/4 HP - Pond Fill - Replace	2033	78	
1084	Sump Pump Backup Generator - Replace	2027	79	
1095	UG Sprinkler Pipe Master Areas 4.8%	2023	81	
1110	VGC Riding Mower - Replace	2029	86	
1096	Walking Paths Bark Dust & Chip Rock Refurbish/Re	2023	82	
1097	Well Clock Tower - Repair Contingency	2027	82	
1099	Well Pump - Replace	2023	83	
Phase	e I			
1035	Mailbox Structures - Ph. I - Replace	2023	90	
1042	Pavement Overlay Phase I	2053	90	
1105	Pavement Replacement Phase I	2023	92	
1051	Pavement Seal Coat Phase I	2029	91	
Phase	e II			
1036	Mailbox Structures - Ph. II - Replace	2023	93	
1043	•	2029	93	
1052	Pavement Seal Coat Phase II	2029	94	
Phase	Phase V			
1037		2045	95	
1045	·	2029	95	

# Villages of Garrison Creek HOA Component Index

Asset ID	Description	Replacement	Page		
Phase V	Phase V Continued				
	L Pavement Overlay Phase V Alley	2053	96		
1111	Pavement Replacement Phase V Alley	2023	98		
1054-0	Pavement Seal Coat Phase V	2029	97		
1054-01	L Pavement Seal Coat Phase V Alley	2029	97		
Phase V	1				
1038	Mailbox Structures - Ph. VI - Replace	2024	99		
1046	Pavement Overlay Phase VI	2029	99		
1055	Pavement Seal Coat Phase VI	2029	100		
Phase V	11				
1039	Mailbox Structures - Ph. VII - Replace	2027	101		
1047	Pavement Overlay Phase VII	2029	101		
1056	Pavement Seal Coat Phase VII	2029	102		
Phase V	111				
1048	Pavement Overlay Phase VIII	2041	103		
1057	Pavement Seal Coat Phase VIII	2029	103		
Phase IX		2025	405		
1009	Concete - Curb Ph. IX - 10% Repair	2035	105		
1044	Pavement Overlay Phase IX	2041	105		
1053	Pavement Seal Coat Phase IX	2029	106		
Phase X					
1010	Concrete Surfaces - Ph. X - 3% Repair	2027	107		
1017	Fence - Metal/Brick - Ph. X - Replace	2037	107		
1020	Gate Entry Access - Ph. X - Replace	2031	108		
1021	Gate Operators - Ph. X - Replace	2032	108		
1022	Gates - Ph. X - Refurbish	2023	109		
1023	Gates - Ph. X - Replace	2031	110		
1049	Pavement Overlay Phase X	2035	110		
1058	Pavement Seal Coat Phase X	2029	111		
1064	Sign - Entry - Ph. X - Replace	2023	112		
	Total Funded Assets	78			
	Total Unfunded Assets	<u>10</u>			
	Total Assets	88			